

ORAU TEAM Dose Reconstruction Project for NIOSH

Page Change

Oak Ridge Associated Universities I Dade Moeller & Associates I MJW Corporation

Page 1 of 152

Document Title:		Document Number:	ORAUT	TKBS-0057
Site Profile for the	West Valley	Revision:	00 PC-1	
Demonstration Pro		Effective Date:	08/17/20	007
		Type of Document	TBD	
		Supersedes:	Revision	00
Subject Expert(s):	Robert E. Burns, Jr.			
Site Expert(s):	N/A			
Approval:	Signature on File	Approva	I Date:	08/14/2007
	Jackson R. Ellis, Document Owner			
Concurrence:	Signature on File	Concurr	ence Date:	08/06/2007
	John M. Byrne, Task 3 Manager			
Concurrence:	Signature on File	Concurr	ence Date:	08/06/2007
	Edward F. Maher, Task 5 Manager			
Concurrence:	Signature on File	Concurr	ence Date:	08/15/2007
	Kate Kimpan, Project Director			
Approval:	Brant A. Ulsh Signature on File for James W. Neton, Associate Director for	or Approva	I Date:	08/17/2007

FOR DOCUMENTS MARKED AS A TOTAL REWRITE, REVISION, OR PAGE CHANGE, REPLACE THE PRIOR REVISION AND DISCARD / DESTROY ALL COPIES OF THE PRIOR REVISION.

Revision

Total Rewrite

New

Document No. ORAUT-TKBS-0057	Revision No. 00 PC-1	Effective Date: 08/17/2007	Page 2 of 152

PUBLICATION RECORD

EFFECTIVE DATE	REVISION NUMBER	DESCRIPTION	
06/22/2007	00	New approved Site Profile for the West Valley Demons Incorporates formal internal and NIOSH review common an increase in assigned dose and a PER is required. required: As determined by the Task Manager. Initiat E. Burns, Jr. Approval:	ents. There is Training
		Signature on File Robert E. Burns, Jr., Document Owner	05/31/2007
		Signature on File John M. Byrne, Task 3 Manager	05/31/2007
		Signature on File Edward F. Maher, Task 5 Manager	06/01/2007
		Signature on File Kate Kimpan, Project Director	05/31/2007
		Brant A. Ulsh Signature on File for James W. Neton, Associate Director for Science	06/22/2007
08/17/2007	00 PC-1	Approved page change revision initiated to assign new owner and to correct PER statement from Rev 00. No required because Task 5 evaluation determined previo cases would not be adversely impacted (no compensa by the Rev 00 issuance of this TBD. No changes were result of formal internal and NIOSH review. Training re determined by the Task Manager. Initiated by Jackson	PER was ously worked bility change) e needed as a equired: As

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 3 of 152
------------------------------	-----------------	----------------------------	---------------

TABLE OF CONTENTS

SECTION

TITLE

PAGE

Acron	yms and	d Abbrevia	ations	13
1.0	Introdu	uction		17
	1.1	Purpose		18
	1.2			
2.0	Sito D	occription		10
2.0	2.1		Ory	
	2.1		ssing Plant Operations Era, 1965 to 1973	
	2.2	2.2.1	0 1 <i>i</i>	
		2.2.1	Plant and Process Description	
			Radiation Protection Program	
		2.2.3	Special Considerations for the Operations Era	
		2.2.4	Chronic Sources of Personnel Exposures	
			2.2.4.1 Plant Ventilation Systems	
			2.2.4.2 Acid Recovery System	
			2.2.4.3 Fuel Receiving and Storage Facility	
		2.2.5	Miscellaneous Sources of Personnel Exposures	25
		2.2.6	Personnel Exposures Associated with Specific Tasks or	
			Duties	
			2.2.6.1 Maintenance Workers	
			2.2.6.2 Operations	
			2.2.6.3 Ventilation System Filter Changeouts	
			2.2.6.4 Overall Workforce	35
	2.3		ssing Plant Residual Radiation Era, 1974 to February 25,	20
	0.4			
	2.4		ssing Plant DOE Era, February 26, 1982, to present	
	2.5		censed (Commercial) Waste Disposal Area, 1963 to 1983	
	2.6		vel Waste Disposal Area, 1966 to present	
	2.7	•	Information for Plant Areas	47
		2.7.1	Operations and Residual Radiation Eras, 1966 to February	4-
		<u> </u>	25, 1982	
		2.7.2	DOE Era, February 26, 1982, to present	49
3.0	Occup	ational M	edical Dose	50
0.0	Occup			
4.0	Occup	ational Er	nvironmental Dose	51
	4.1		n and submersion Dose	
		4.1.1	Stack Releases	52
			4.1.1.1 Particulates	52
			4.1.1.2 Krypton-85	54
			4.1.1.3 lodine-131	
			4.1.1.4 Tritium	
		4.1.2	Ground Level Releases	
	4.2	Ambient	Dose	
	4.3		y of Exposures from Environmental Sources	
5.0	Interna	al Dosimet	try	59

	5.1	Internal Dose Control Program	59
		5.1.1 Operations and Residual Radiation Eras 1966 – February	
		25, 1982	
		5.1.1.1 Nasal Swabs	
		5.1.1.2 Chest Counter	
		5.1.2 DOE Era February 26, 1982 – present	
	5.2	Bioassay program	61
		5.2.1 Operations and Residual Radiation Eras 1966 – February	
		25, 1982	
		5.2.1.1 Bioassay Records	
		5.2.2 DOE Era February 26, 1982 - present	
		5.2.2.1 Routine Bioassay	
		5.2.2.2 Special Bioassay	
		5.2.3 Summary	
	5.3	In Vitro Analyses	65
		5.3.1 Operations and Residual Radiation Eras 1966 – February	05
		25, 1982	65
	- 1	5.3.2 DOE Era February 26, 1982 - present	
	5.4	In Vivo Analyses	
		5.4.1 Operations and Residual Radiation Eras	
		5.4.1.1 Chest Counter	
		5.4.1.2 Commercial Mobile Whole-Body Counting 5.4.1.3 New York University Medical Center Phoswich	
		Counter	70
		5.4.2 U.S. Department of Energy Era	
	5.5	Interpretation of Bioassay Measurements for West Valley Workers	
	5.5		
6.0	Exter	nal Dosimetry	75
	6.1	Basis of Comparison	
	6.2	Site Historical Administrative Practices	75
		6.2.1 Site Access Requirements	75
		6.2.2 Personnel Exposure Control	77
		6.2.3 Evaluation and Recording of Personnel Exposures	78
		6.2.3.1 Dose Recording Practices	78
		6.2.3.2 Nuclear-Chicago Film Badge Exposure Reports	
		6.2.3.3 Landauer Radiation Dosimetry Reports	81
	6.3	Site Dosimetry Technology	
		6.3.1 Whole-Body Monitoring	81
		6.3.2 Extremity Monitoring	
	6.4	Workplace Radiation Fields	
		6.4.1 Beta and Photon	82
		6.4.2 Neutron	82
		6.4.3 Summary	
	6.5	Missed Dose	
	6.6	Uncertainty	
7.0	Attrib	outions and Annotations	84
Kefei	ences.		87

Doc	ument N	o. ORAUT	-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 5 of 152
ATTA	CHMEN				AREAS AND SYSTEMS	
		WI	TH EMPHASI	S ON RADIOLOGIC	AL CONDITIONS	100
A1.0	Acid F	ecoverv	Cell			106
//1.0	A1.1					
		A1.1.1				
A2.0		Recovery	Pump Room.			106
	A2.1					
		A2.1.1 A2.1.2				
		AZ.1.Z	Removable	Contamination Data		107
A3.0	Analyt	ical Aisle	, Laboratories	, and North Operatir	ng Aisle	
	A3.1					
		A3.1.1	•			
		A3.1.2	Removable	Contamination Data		109
A4.0						100
A4.0	A4.1					
	/ (+. 1	A4.1.1				
		A4.1.2				
A5.0						
	A5.1				ne Activity Levels in the Cel	
	A5.2	A5.2.1			xtension	
		A5.2.1 A5.2.2				
		A5.2.3				
		A5.2.4				
	A5.3	Process				
		A5.3.1	External Exp	osure Data		111
		A5.3.2				
		A5.3.3				
	A5.4					
		A5.4.1				
		A5.4.2				
		A5.4.3	Airborne Co	ntamination Data		
A6.0	Chem	ical Opera	ating Aisle an	d Chemical Viewing	Aisle	112
	A6.1	Radiolo	gical Condition	ns		
		A6.1.1				
		A6.1.2				
			0 "			110
A7.0						
	A7.1	Radiolo	gical Condition	ns		
A8.0	Contro	ol Room				
	A8.1					
			•			
			•			

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 6 of 152

A9.0			ontamination Room and Equipment Decontamination Room	
	A9.1		gical Conditions	
		A9.1.1		
		A9.1.2		
		A9.1.3	Airborne Contamination Data	114
A10.0	Extrac	tion and F	Product Purification Cells	114
	A10.1	Radiolog	gical Conditions	115
			External Exposure Data	
			Removable Contamination Data	
		A10.1.3	Airborne Contamination Data	116
A11.0	Extrac	tion Chen	nical Room	116
	A11.1	Radiolog	gical Conditions	116
		A11.1.1	External Exposure Data	116
		A11.1.2	Removable Contamination Data	117
A12.0	Extrac	tion Sam	ble Aisle and Process Sample Cell 2	117
			gical Conditions	
			Removable Contamination Data	
			Airborne Contamination Data	
A13.0	Fuel R	eceivina	and Storage	117
			Radiological Conditions	
			Pool Water Concentration Data	
			External Exposure Data	
			Removable Contamination Data	
			Airborne Contamination Data	
A14.0	Guard	House		
			gical Conditions	
A15.0			ing Aisle	
	A15.1		gical Conditions	
			Exposure Rate Data	
		A15.1.2	Airborne Contamination Data	123
A16.0			e Cell	
	A16.1		gical Conditions	
			External Exposure Data	
		A16.1.2	Removable Contamination Data	124
A17.0	Head E	End Venti	lation Building and Crane Room	124
		Radiolog	gical Conditions	124
		A17.1.1	External Exposure Data	124
		A17.1.2	Removable Contamination Data	124
A18.0	Hot Ac	id Cell		125
			gical Conditions	
			External Exposure Data	

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 7 of 152
			•

	A18.1.2 Removable Survey Data	125
A19.0	Hot Shop	125
	A19.1 Radiological Conditions	
	A19.1.1 External Exposure Data	
	A19.1.2 Removable Contamination Data	
A20.0	Instrument Shop/Old Instrument Shop	126
	A20.1 Radiological Conditions	
	A20.1.1 External Exposure Data	126
	A20.1.2 Removable Contamination Levels	126
A21.0	Interceptor and New Interceptor	126
	A21.1 Radiological Conditions	127
	A21.1.1 External Exposure Data	127
A22.0	Laundry	127
	A22.1 Radiological Conditions	127
	A22.1.1 External Exposure Data	
	A22.1.2 Removable Contamination Data	
	A22.1.3 Airborne Contamination Data	127
A23.0	Load-in Facility	128
A24.0	Low Level Waste Treatment Facility	128
/ 12 110	A24.1 Radiological Conditions	
	A24.1.1 External Exposure Data	
A25.0	Low Level Wastewater Treatment Building	128
	A25.1 Radiological Conditions	
	A25.1.1 External Exposure Data	
	A25.1.2 Removable Contamination Data	129
A26.0	Lower Extraction Aisle	129
	A26.1 Radiological Conditions	129
	A26.1.1 External Exposure Data	129
A27.0	Lower Warm Aisle	129
	A27.1 Radiological Conditions	130
	A27.1.1 External Exposure Data	130
	A27.1.2 Removable Contamination Data	130
	A27.1.3 Airborne Contamination Data	130
A28.0	Main Office Building	131
	A28.1 Radiological Conditions	
	A28.1.1 External Exposure Data	
	A28.1.2 Removable Contamination Data	131
A29.0	Maintenance Shop and Warehouse	131
	A29.1 Radiological Conditions	132

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 8 of 152
			Ŭ

A30.0	Manipulator Repair Room A30.1 Radiological Conditions	
	A30.1.1 External Exposure Data A30.1.2 Removable Contamination Data	132 132
A31.0	Mechanical Operating Aisle (North, East and West)	132
	A31.1 Radiological Conditions	
	A31.1.1 External Exposure Data	
	A31.1.2 Removable Contamination Data A31.1.3 Airborne Contamination Data	
A32 0	MSM Shop/Contact Size Reduction Facility	134
102.0	A32.1 Radiological Conditions	
	A32.1.1 External Exposure Data	
	A32.1.2 Removable Contamination Data	
A33.0	Off Gas Aisle and Process Sample Cell 3	135
	A33.1 Radiological Conditions.	135
	A33.1.1 External Exposure Data	135
	A33.1.2 Removable Contamination Data	135
	A33.1.3 Airborne Contamination Data	136
A34.0	Off Gas Blower Room	
	A34.1 Radiological Conditions	
	A34.1.1 External Exposure Data	
	A34.1.2 Removable Contamination Data	137
A35.0	Off Gas Cell	137
	A35.1 Radiological Conditions	
	A35.1.1 External Exposure Data	137
A36.0	Permanent Ventilation System Building	
	A36.1 Radiological Conditions	
	A36.1.1 External Exposure Data	
	A36.1.2 Removable Contamination Data	138
A37.0	Process Chemical Room	
	A37.1 Radiological Conditions	
	A37.1.1 External Exposure Data	
	A37.1.2 Removable Contamination Data	138
A38.0	Process Mechanical Cell.	
	A38.1 Radiological Conditions	
A39.0	Product Packaging and Shipping, Product Packaging and Handling, Uranium Product Cell, and Uranium Loadout Areas	120
	A39.1 Radiological Conditions	
	A39.1.1 External Exposure Data	
	A39.1.2 Removable Contamination Data	
	A39.1.2 Removable Contamination Data	
		140

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 9 of 152
	•		

A40.0	Pulser Equipment Aisle	
	A40.1 Radiological Conditions A40.1.1 Airborne Contamination Data	
A41.0	Remote Handled Waste Facility	141
A42.0	Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination	
	Aisle	141
A43.0	Scrap Removal Area	
	A43.1 Radiological Conditions	
	A43.1.1 External Exposure Data	
	A43.1.2 Removable Contamination Data	
	A43.1.3 Airborne Contamination Data	142
A44.0	Solvent Storage Terrace	
	A44.1 Radiological Conditions	
	A44.1.1 External Exposure Data	
	A44.1.2 Removable Contamination Data	143
A45.0	Supernatant Treatment System Support Building	
	A45.1 Radiological Conditions	
	A45.1.1 External Exposure Data	
	A45.1.2 Removable Contamination Data	143
A46.0	Upper Extraction Aisle	
	A46.1 Radiological Conditions	
	A46.1.1 External Exposure Data	
	A46.1.2 Removable Contamination Data	144
A47.0	Upper Warm Aisle and Process Sample Cell 1	
	A47.1 Radiological Conditions	
	A47.1.1 External Exposure Data	
	A47.1.2 Removable Contamination Data	
	A47.1.3 Airborne Contamination Levels	146
A48.0	Utility Room and Stairwells	
	A48.1 Radiological Conditions	
	A48.1.1 External Exposure Data	
	A48.1.2 Removable Contamination Data	
	A48.1.3 Airborne Concentration Data	148
A49.0	Ventilation Exhaust Cell	
	A49.1 Radiological Conditions	
	A49.1.1 External Exposure Data	148
A50.0	Ventilation Systems	
	A50.1 Main Ventilation System	148
	A50.2 Head End Ventilation System	150
A51.0	Ventilation Wash Room	150

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 10 of 152
			: «ge : e e: : e=

	A51.1	Radiological Conditions	150
		A51.1.1 External Exposure Data	151
		A51.1.2 Airborne Contamination Data	151
A52.0	Waste	Tank Farm	151
	A52.1	Radiological Conditions	151
		A52.1.1 External Exposure Data	

52
52

LIST OF TABLES

TABLE

<u>TITLE</u>

PAGE

2-1	NFS-defined contamination areas	
2-2	Respiratory protection thresholds	
2-3	Average annual collective dose for maintenance workers for typical tasks, 1970 to 1971	
2-4	Tasks with the highest collective exposures to maintenance workers,	
2 1	1970 to 1971	
2-5	UWA pump changeout data, 1970 and 1971	
2-6	LWA pump changeout data, 1970 and 1971	
2-7	Breakdown of the dose to operations workers for typical tasks and duties	
2-8	Dose rates and occupancy times for operations workers for various areas	
	of the plant, July 1971	33
2-9	Breakdown for analytical workers, July 1971	33
2-10	Personnel exposure associated with main ventilation system filter changes	34
2-11	Collective dose for changeouts of HEV system prefilters	
2-12	Collective dose for changeouts of HEV system roughing filters	
2-13	Collective whole-body, skin, and extremity dose for various work groups,	
~		36
2-14	Collective whole-body, skin, and extremity dose for various work groups, 1968	
2-15	Collective whole-body, skin, and extremity dose for various work groups, 1969	36
2-16	Collective whole-body, skin, and extremity dose for various work groups, 1970	
2-17	Collective whole-body, skin, and extremity dose, various work groups for 1971	
2-18	Typical exposures per person for various job duties, 1970	
2-19	Typical exposures per person for various job duties, 1970	
2-20	Significant radiation sources in the reprocessing plant as of March 15, 1972	
2-21	Exposure rate data for various locations extracted from a health physics	
2-22	Exposure rate data for various locations extracted from a health physics	
	logbook, January to October 1974	
2-23	Exposure rate data for later in the residual radiation era	44
2-24	Estimated quantities of Special Nuclear Material and source material in	
2-25	the SDA through 1975 Estimated radioactivity content in the SDA through 1975	
2-25	Isotopic mix percentages for West Valley plutonium product	
2-20	Radionuclides of concern	
2-27	Dominant radionuclides and conservative estimates of total activity for	
2 20	process building facilities and other site facilities	40
3-1	X-ray exam frequencies for West Valley workers	
4-1	Total particulate releases from West Valley's main stack 1966 through	
	1972	52
4-2	Total ⁸⁵ Kr releases from the West Valley stack 1966 through 1969	
4-3	Monthly ⁸⁵ Kr release data for 1967 and 1971	

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 12 of 152
		•	

4-4 4-5	Airborne releases of ¹³¹ I for July through December 1971	
4-5 4-6	Particulate discharges for 1970 and 1971 External onsite environmental dose for West Valley workers	
4-0 5-1	Summary of <i>in vivo</i> bioassay frequencies for West Valley radiation	
5-1	workers	64
5-2	Summary of routine <i>in vitro</i> bioassay frequencies for West Valley	04
5-2	radiation workers	65
5-3	In vitro analyses and reporting levels for West Valley during the	05
5-5	operations and residual radiation eras	66
5-4	Required detection levels for WVDP <i>in vitro</i> analyses as of September 12,	
J- 4	1990	68
5-5	Required detection levels for priority and routine <i>in vitro</i> samples as of	
00	August 1, 1997	68
5-6	Required detection levels for WVDP <i>in vitro</i> analyses as of March 14,	
00	1998	68
5-7	WVDP decision levels for positive <i>in vitro</i> samples as of November 23,	
01	1998	69
5-8	Sensitivity data for April 1967 in vivo counting	
5-9	Sensitivity data for April 1969 <i>in vivo</i> counts	
5-10	Nuclide mix information for West Valley MFAP source term as of January	
0.0	1, 2000	73
5-11	Nuclide mix information for West Valley uranium source term as of	
• • •	January 1, 2000	
5-12	Nuclide mix information for West Valley plutonium source term as of	
• • -	January 1, 2000	
5-13	Nuclide mix information for freshly separated and aged plutonium at West	
0.0	Valley	
6-1	Nuclear-Chicago film badge type codes	
6-2	Discrepancy codes and explanations	
6-3	Landauer exposure type codes	
6-4	Selection of radiation energies for West Valley facilities	
6-5	Exchange frequencies, MDLs, and maximum annual missed deep dose	
	for personnel dosimeters	83
6-6	Exchange frequencies, MDLs, and maximum annual missed	
	nonpenetrating dose for personnel dosimeters	83
6-7	Uncertainties for positive recorded dose at West Valley	
A-1	Gross beta and gross alpha concentration data for the CUP and SP,	
	December 1965	119
A-2	Radioactivity concentration data for the CUP and SP, January to June	-
-	1966	119
A-3	Gross beta concentration data for the CUP and SP, September 1965 to	
	October 1969	120
A-4	Exposure rates over the top of the FRS pools, November 1965 to May	
	1969	120

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 13 of 152
			. age .e ee=

ACRONYMS AND ABBREVIATIONS

AEC	U.S. Atomic Energy Commission
AMAD	activity median aerodynamic diameter
ARPR	Acid Recovery Pump Room
ASDA	Atomic and Space Development Authority (State of New York)
Bq	becquerel
CAA	Cell Access Aisle
CCR	Chemical Process Cell Crane Room
CEDE	committed effective dose equivalent
CFR	Code of Federal Regulations
Ci	curie
cm	centimeter
COA	Chemical Operating Aisle
CPC	Chemical Process Cell
cpm	counts per minute
CUP	Cask Unloading Pool
CVA	Chemical Viewing Aisle
d	day
D&D	decontamination and decommissioning
DAC	derived air concentration
DOE	U.S. Department of Energy
DOELAP	U.S. Department of Energy Laboratory Accreditation Program
DOG	Dissolver Off Gas
dpm	disintegrations per minute
EDR	Equipment Decontamination Room
EEOICPA	Energy Employees Occupational Illness Compensation Program Act
EMOA	East Mechanical Operating Aisle
EPA	U.S. Environmental Protection Agency
FRS ft	Fuel Receiving and Storage foot
g	gram
gal	gallon
GCR	General Purpose Cell Crane Room
GOA	General Operating Aisle
GPC	General Purpose Cell
HEPA	high-efficiency particulate air
HEV	Head End Ventilation
HLW	high-level radioactive waste
hr	hour
HTO	tritiated water vapor
ICRP in.	International Commission on Radiological Protection inch

IREP	Interactive RadioEpidemiological Program
keV	kiloelectron-volt, 1,000 electron-volts
kg	kilogram
L	liter
LLW	low-level waste
LLWT	Low-Level Waste Treatment (facility)
LLW2	Low-Level Wastewater Treatment Building
LWA	Lower Warm Aisle
LXA	Lower Extraction Aisle
m MDA MDC MDL MeV MFAP MFP mL MOA MPBB MPC MPLB mR mrad mrem MRR MSM MTU MWd	meter minimum detectable activity minimum detectable concentration minimum detectable level megaelectron-volt, 1 million electron-volts mixed fission and activation product mixed fission product milliliter Mechanical Operating Aisle maximum permissible body burden maximum permissible concentration maximum permissible lung burden milliroentgen millirem Manipulator Repair Room Master-Slave Manipulator metric ton of uranium megawatt-day
nCi	nanocurie
NDA	NRC-licensed Disposal Area
NFS	Nuclear Fuel Services
NIOSH	National Institute for Occupational Safety and Health
NOCTS	NIOSH-Office of Compensation Analysis and Support Claims Tracking System
NRC	U.S. Nuclear Regulatory Commission
NYSERDA	New York State Energy Research and Development Authority
NYU	New York University
OGA	Off Gas Aisle
OGBR	Off Gas Blower Room
OGC	Off Gas Cell
ORAU	Oak Ridge Associated Universities
PA	posterior-anterior
PCR	Process Chemical Room
PEA	Pulser Equipment Aisle
PMC	Process Mechanical Cell
PMCR	Process Mechanical Cell Crane Room

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 15 of 152
			U

POC	probability of causation
PPC	Product Purification Cell
PPH	Product Packaging and Handling
PPS	Product Packaging and Shipping
PSC	Process Sample Cell
PSF	Plutonium Storage Facility
PUREX	plutonium-uranium extraction
PVS	Permanent Ventilation System
R	roentgen
RBA	Radiological Buffer Area
RHWF	Remote Handled Waste Facility
s	second
scfm	standard cubic feet per minute
SDA	State-licensed Disposal Area
SP	Storage Pool
SR	Scrap Removal
SRDB Ref ID	Site Research Database Reference Identification (number)
SSC	Sample Storage Cell
SSN	Social Security Number
STS	Supernatant Treatment System
Sv	sievert
SWP	Special Work Permit
TBD	technical basis document
THOREX	thorium extraction
TLD	thermoluminescent dosimeter
TRU	transuranic
U.S.C.	United States Code
ULO	Uranium Loadout Area
UPC	Uranium Product Cell
UWA	Upper Warm Aisle
UXA	Upper Extraction Aisle
VEC	Ventilation Exhaust Cell
VOG	Vessel Off Gas
VWR	Ventilation Wash Room
wk	week
WMOA	West Mechanical Operating Aisle
WTF	Waste Tank Farm
WVDP	West Valley Demonstration Project
WVNSC	West Valley Nuclear Services Company
XC1	Extraction Cell 1
XC2	Extraction Cell 2
XC3	Extraction Cell 3
XCR	Extraction Chemical Room
XSA	Extraction Sample Aisle

Doc	ument No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 16 of 152

- yr year
- microcurie microgram μCi
- μg
- § section or sections

Document No. ORAUT-TKBS-0057 R	Revision No. 00	Effective Date: 06/22/2007	Page 17 of 152
--------------------------------	-----------------	----------------------------	----------------

1.0 INTRODUCTION

Technical basis documents and site profile documents are not official determinations made by the National Institute for Occupational Safety and Health (NIOSH) but are rather general working documents that provide historic background information and guidance to assist in the preparation of dose reconstructions at particular sites or categories of sites. They will be revised in the event additional relevant information is obtained about the affected site(s). These documents may be used to assist NIOSH staff in the completion of the individual work required for each dose reconstruction.

In this document, the word "facility" is used as a general term for an area, building, or group of buildings that served a specific purpose at a site. It does not necessarily connote an "atomic weapons employer facility" or a "Department of Energy [DOE] facility" as defined in the Energy Employees Occupational Illness Compensation Program Act [EEOICPA; 42 U.S.C. § 7384I(5) and (12)]. EEOICPA defines a DOE facility as "any building, structure, or premise, including the grounds upon which such building, structure, or premise is located ... in which operations are, or have been, conducted by, or on behalf of, the Department of Energy (except for buildings, structures, premises, grounds, or operations ... pertaining to the Naval Nuclear Propulsion Program)" [42 U.S.C. § 7384I(12)]. Accordingly, except for the exclusion for the Naval Nuclear Propulsion Program noted above, any facility that performs or performed DOE operations of any nature whatsoever is a DOE facility encompassed by EEOICPA.

For employees of DOE or its contractors with cancer, the DOE facility definition only determines eligibility for a dose reconstruction, which is a prerequisite to a compensation decision (except for members of the Special Exposure Cohort). The compensation decision for cancer claimants is based on a section of the statute entitled "Exposure in the Performance of Duty." That provision [42 U.S.C. § 7384n(b)] says that an individual with cancer "shall be determined to have sustained that cancer in the performance of duty for purposes of the compensation program if, and only if, the cancer ... was at least as likely as not related to employment at the facility [where the employee worked], as determined in accordance with the POC [probability of causation¹] guidelines established under subsection (c) ..." [42 U.S.C. § 7384n(b)]. Neither the statute nor the probability of causation guidelines (nor the dose reconstruction regulation) define "performance of duty" for DOE employees with a covered cancer or restrict the "duty" to nuclear weapons work.

As noted above, the statute includes a definition of a DOE facility that excludes "buildings, structures, premises, grounds, or operations covered by Executive Order No. 12344, dated February 1, 1982 (42 U.S.C. 7158 note), pertaining to the Naval Nuclear Propulsion Program" [42 U.S.C. § 7384I(12)]. While this definition contains an exclusion with respect to the Naval Nuclear Propulsion Program, the section of EEOICPA that deals with the compensation decision for covered employees with cancer [i.e., 42 U.S.C. § 7384n(b), entitled "Exposure in the Performance of Duty"] does not contain such an exclusion. Therefore, the statute requires NIOSH to include all occupationally derived radiation exposures at covered facilities in its dose reconstructions for employees at DOE facilities, including radiation exposures related to the Naval Nuclear Propulsion Program. As a result, all internal and external dosimetry monitoring results are considered valid for use in dose reconstruction. No efforts are made to determine the eligibility of any fraction of total measured exposures to be occupationally derived:

- Radiation from naturally occurring radon present in conventional structures
- Radiation from diagnostic X-rays received in the treatment of work-related injuries

¹ The U.S. Department of Labor is ultimately responsible under the EEOICPA for determining the POC.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 18 of 152
------------------------------	-----------------	----------------------------	----------------

1.1 PURPOSE

This site profile provides information about operations at the West Valley reprocessing plant operated initially by Nuclear Fuel Services (NFS) and subsequently by DOE under the West Valley Demonstration Project. The operations addressed pertain to occupational radiation exposures for monitored or unmonitored workers.

1.2 SCOPE

Section 2.0 provides a description of the site and operations that pertain to possible radiation exposures and discusses radiation source terms. Section 3.0 provides guidance for the determination of occupational medical dose. Section 4.0 provides guidance for the determination of dose to workers outside radiological facilities from external radiation and releases of radioactive materials to the environment. Section 5.0 provides guidance for the determination of intakes of radionuclides inside facilities. Section 6.0 provides guidance for the determination of external doses from measured doses or for periods for which records of measured doses are missing.

2.0 SITE DESCRIPTION

2.1 SITE HISTORY

In 1962, the State of New York's Atomic and Space Development Authority (ASDA) and NFS partnered to build a privately owned nuclear fuel reprocessing plant. Construction of the plant began in June 1963 and took approximately 3 years to complete. The plant was built on 200 acres of land leased from the ASDA by NFS. (The State of New York took title to 3,345 acres of land in 1961 and established the Western New York Nuclear Service Center.)

NFS was granted a license to receive and store fuel on May 27, 1965. The first fuel for reprocessing was received June 3, 1965, and placed in the Storage Pool (SP) on June 5. Approximately 60% of the fuel processed at NFS came from the U.S. Atomic Energy Commission (AEC), as part of its guarantee to supply fuel until an adequate commercial market grew. A majority of this AEC-supplied fuel came from the Hanford N Reactor (DOE 1999).

An operating license was granted to NFS for the reprocessing plant on April 19, 1966, and reprocessing began on April 22. The first three processing campaigns involved fuel from the Hanford N Reactor (Clark 1979).

The West Valley processing plant was designed to be a multipurpose facility with the capability of reprocessing nuclear fuel from a number of different fuel cycles (Bailey 1990). The plant primarily used the plutonium-uranium extraction (PUREX) process; however, one thorium extraction (THOREX) campaign was processed between November 1968 and January 1969.

From 1966 to 1972, the West Valley facility handled and reprocessed a total of 630 tons of fuel from nine different reactors during 28 campaigns. Fuels processed included light-water reactor fuels (from both boiling- and pressurized-water reactors), fuels from AEC-owned reactors (such as the Hanford N Reactor), and a uranium-thorium fuel cycle core from the Indian Point 1 reactor. Plutonium and uranium recovered from irradiated fuels were delivered as nitrates. The recovered uranium was sent to the Fernald (Ohio) Plant, and the plutonium was sent to either Hanford or (later) to the ASDA Plutonium Storage Facility (PSF). In general, AEC plutonium was sent to Hanford, and utility-owned plutonium was retained by the utilities, sold to industry, or sold to NFS for later resale for use in plutonium recycle. NFS and the ASDA entered into a plutonium storage agreement on May 3, 1971,

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 19 of 152
------------------------------	-----------------	----------------------------	----------------

in which ASDA would store plutonium at its PSF. The PSF was approximately 2,200 m eastsoutheast of the NFS plant (ASDA and NFS 1971). Storage of plutonium at the PSF was to be terminated by December 31, 1974 (NFS 1974a, p. 3.2-1).

In March 1972, the reprocessing plant was shut down to complete a series of improvements intended to increase capacity and meet new regulatory requirements. From 1973 to 1975, 756 spent light-water reactor fuel assemblies were shipped to the West Valley facility and placed in the SP in anticipation of resumption of reprocessing operations (from Bailey 1990). However, after a decision by the AEC that a completely new licensing process would be required, and facing more stringent requirements on plant effluents, NFS concluded that reprocessing no longer made economic sense. In 1977 it transferred management of the facility to the New York State Energy Research and Development Authority (NYSERDA).

In 1980, the U.S. Congress passed the West Valley Demonstration Act, which directed DOE to solidify the high-level radioactive waste (HLW) and to decontaminate and decommission the tanks and facilities at the West Valley Demonstration Project (WVDP). DOE assumed operational control of the West Valley site on February 26, 1982, with West Valley Nuclear Services Company (WVNSC) as its contractor (WVNSC 1983).

One of the first major projects under the WVDP was to address the hundreds of unreprocessed spent nuclear fuel assemblies that remained in the SP. During the early 1980s, a campaign was conducted to ship spent fuel assemblies back to their point of origin. When this initial shipping campaign was halted, 125 fuel assemblies still remained in the SP. Work was subsequently performed in the mid-1980s to remove the majority of empty fuel canisters and storage racks in the pool. The SP still contained 149 canisters and 11 rows of storage racks after this work was completed. By the early spring of 2001, all of the remaining 125 spent nuclear fuel assemblies had been transferred into two shipping casks for eventual shipment to the Idaho National Laboratory. By late 2001, the remaining 149 canisters and storage racks had been removed and decontamination of the SP began [excerpted from Jablonski, Al-Daouk, and Moore 2003].

Decontamination of the main reprocessing plant took place in the early 1980s to allow for utilization of the existing facilities for the HLW vitrification project to the extent practicable (Johnson 1991). Decontamination activities took place in a number of former process cells from 1982 through 1987 (Hoffman 1997).

Pretreatment of the HLW began in 1988 to partition the cesium and strontium from the other constituents and thus create two waste streams: one high level and one low level. This partitioning reduced the amount of HLW that required vitrification. This waste pretreatment continued until 1995. The effluent (low-level) liquid from the pretreatment process was sent to the Cement Solidification System to be solidified in cement. This low-level waste (LLW) was packaged in approximately 20,000 steel drums, which are being stored at West Valley pending disposal.

Vitrification of the HLW took place between June 1996 and November 2001. Followed by a program to flush residuals through it, the vitrification facility melter was shut down in September 2002. The HLW solidification campaign involved the vitrification of approximately 24 million Ci of activity into 275 glass logs. Each log contains approximately 2,000 kg of glass. The individual logs are encased in canisters. Individual canisters had a contact dose rate of approximately 2,600 rem/hr in 2003. They are stored in the Chemical Process Cell (CPC) (Petkus et al. 2003).

In 1999 Vitrification Expended Materials Processing was initiated to begin processing unserviceable equipment in the Vitrification Facility. The Remote Handled Waste Facility (RHWF) was subsequently

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 20 of 152
------------------------------	-----------------	----------------------------	----------------

developed to process large-scale, highly contaminated equipment excessed during decontamination and decommissioning (D&D) activities. Groundbreaking for the RHWF took place in 2000, as the WVDP restructured to focus on D&D.

In 2003, projects included removal and treatment of sodium-bearing wastewater from underground storage tanks and decontamination of the process cell used for purification of the plutonium product stream when the reprocessing plant was operating. Debris was removed from the General Purpose Cell (GPC) and Process Mechanical Cell (PMC) and packaged, and the Vitrification Cell Dismantlement Project was initiated.

Shipping LLW off the site was a major activity in 2004, with 104,427 ft³ of waste being shipped for disposal. Footprint reduction began with the removal of 20 office trailers from the site. Decontamination of four of the major process cells continued: the Vitrification Cell, PMC, GPC, and Extraction Cell–2. In November 2004, the Vitrification Melter was removed from the Vitrification Facility, packaged in a specially designed container, and staged on the site for potential offsite disposal. The Vitrification Melter was the last large component removed from the Vitrification Cell. The Vitrification Cell Dismantlement project was completed in mid-2005 (DOE 2006).

LLW shipments for offsite disposal increased significantly in 2005. Site footprint reduction activities escalated, and a number of site employees were moved to an offsite building.

In addition to the reprocessing plant, NFS operated a commercial radioactive waste disposal site at West Valley from 1963 to 1975. Disposal of solid material by land burial began in November 1963. During this time NFS buried waste from commercial generators totaling 2.4 million ft³. These wastes, which came from nuclear power facilities, hospitals, and academic, industrial, and government facilities, and the reprocessing plant itself, were buried in soil trenches. The material ranged in activity from low-specific activity material to containers with exposure rates of 8,000 to 10,000 R/hr (Author unknown ca. 1968, p. 1). This burial site, known as the State-licensed Disposal Area (SDA), encompasses approximately 15 acres. NYSERDA took over maintenance of the SDA in 1983.

NFS also operated a disposal (burial) area for high-level solid wastes generated during fuel reprocessing. These reprocessing wastes, which included fuel cladding, were buried in a 7-acre landfill known as the U.S. Nuclear Regulatory Commission (NRC)-licensed Disposal Area (NDA).

2.2 REPROCESSING PLANT OPERATIONS ERA, 1965 TO 1973

2.2.1 Plant and Process Description

The NFS reprocessing plant was on a 3,345-acre site bounded by a barbed-wire fence and posted as a restricted area. The plant itself and its waste storage operations were performed within a 300-acre security area at about the center of the site. The security area was defined by an 8-ft security fence.

The reprocessing plant consisted of a complex of cells with the various supporting and operating areas grouped around them (Johnson & Higgins 1972, p. 2). The plant was arranged in the shape of a U, with the Fuel Receiving and Storage (FRS) facility on one end and the product removal facilities on the other. The mechanical and chemical processing cells were in the middle (Runion 1970). Most areas of the process building fall into one of three categories: shielded cells, operating aisles, and unshielded rooms (WVDP 2005). The cells consisted of reinforced concrete walls several feet thick. The rest of the plant was of cinderblock construction. Chemical operations were directed from the Control Room, while mechanical operations were directed from operating aisles adjacent to viewing windows in the hot cells (Runion 1970).

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 21 of 152
------------------------------	-----------------	----------------------------	----------------

Fuel reprocessing involved shearing and leaching of fuel elements on the front end, followed by solvent extraction to remove plutonium and uranium. Fuel arrived at the site in shipping casks. The casks were unloaded under water and the fuel was stored in a SP. These operations took place in the FRS facility. Fuel bundles would be inverted and passed through a transfer canal into the PMC. Shearing and sawing equipment removed hardware and segmented the fuel into fixed lengths. The segmented fuel fell through a chute into baskets in the GPC below. The baskets were then passed into the CPC where the segmented fuel was dissolved in acid. This process, known as leaching, dissolved the fuel, leaving behind the cladding and any structural components. This leftover material, referred to as "hulls," was rinsed and disposed of in the NDA as HLW. The plutonium and uranium in the dissolved fuel were separated from the fission products and purified in a series of extraction cells. The purified products were then sent to their owners as nitrate solutions. After May 1971, plutonium solutions were sometimes also sent to the Plutonium Storage Facility, which was owned and operated by the State of New York on the West Valley site. High-level liquid waste generated in the process was stored in underground tanks. Some of the acids used in the process were recycled for reuse.

Thorium-uranium fuel from Indian Point Unit 1 was processed from November 15, 1968, to January 20, 1969 (Birchler 1970). This is referred to as the "Con. Ed." campaign in the vernacular of the day. Following the THOREX processing, the plant was thoroughly flushed to reduce the amount of high-enriched uranium in systems as much as possible. Processing of the thorium fuel required significant changes to the process to account for the high levels of thorium, ²³⁵U, and ²³³U present. The fuel also contained ²³⁹Pu. The high concentrations of fissile species required the use of boron in the dissolving process. A number of systems normally used in processing (e.g., wash systems, silica beds) were not used due to criticality concerns. High ²³⁸Pu activity required resin beds to be regenerated more frequently than usual.

Process Summary:

- Fuel receipt and storage
- Mechanical preparation
- Fuel dissolving
- Solvent extraction
- Plutonium product concentration, storage, and loadout
- Uranium product concentration, storage, and loadout

As of 1970 the plant had processed fuel with burnups as high as 30,000 MWd/MTU (Runion 1970). The last fuel reprocessing campaign at West Valley was completed in November 1971 (Nelson 1973a, p. 1). The last plutonium scrap recovery operation took place in March 1972 (Nelson 1973b, p. 2 of enclosure 2). Afterward, the plant was in a shutdown condition, with operations limited to fuel receipt and storage and decontamination activities. Per the AEC, decontamination activities were significantly curtailed after May 4, 1973 (Nelson 1973b, p. 2 of enclosure 2).

2.2.2 Radiation Protection Program

Given the extreme radiological environment which existed while the plant was in operation, the radiation protection program focused on controlling personnel exposures relative to legal maximums. Exposure control was threshold-oriented, i.e., concerned with not exceeding quarterly exposure limits, allowable breathing zone air concentrations, maximum permissible body burdens (MPBBs), etc. (e.g., see Keely and Wenstrand 1971).

NFS defined contamination areas using a system of four "zones" based upon removable contamination levels (Table 2-1). Zone 1 referred to equipment and areas with no smearable contamination. Zone 2 areas were those where removable contamination levels were such that

special access controls were not deemed necessary. Zone 3 areas were those with contamination requiring special control, and Zone 4 areas required "stringent" control. Entry points into Zone 4 areas had buffer zones classified as Zone 3 areas. Entries into Zone 4 areas were covered under Special Work Permits (SWPs). Radiation Work Permits were used otherwise.

Category	Removable alpha (dpm/100 cm ²)	Removable beta (dpm/100 cm ²)	Posting and barriers
Zone 1	≤10	≤100	"Clean" areas outside the security fence: not posted.
Zone 2	10–50	100–500	"Clean" areas inside the security fence: not posted.
Zone 3	50–500	500–50,000	Posted, rope barrier, step-off pad.
Zone 4	≥500	≥50,000	Posted, rope barrier, step-off pad, entrance was airlock or
			tented.

All repair or maintenance activities in Zone 4 areas or in high radiation areas (exposure rates \geq 100 mR/hr) were performed under SWPs. Standard Operating Procedures addressed contamination control, doffing, etc. Decontamination was performed following maintenance activities to reduce contamination to premaintenance levels. Radioactive wastes generated from maintenance activities were packaged and sent to one of the two burial sites for disposal.

Respiratory protection thresholds were as given in Table 2-2 (NFS 1974b). These values are the maximum allowable concentration for the corresponding respiratory protection equipment.

Radionuclide	No respiratory protection (µCi/cm ³)	Full face canister mask (µCi/cm ³)	Supplied air mask (constant flow) (µCi/cm ³)
Mixed fission products	1E-09	2E-08	1E-06
Pu-239	2E-12	4E-11	2E-09
Uranium	6E-11	1E-09	6E-08

Table 2-2. Respiratory protection thresholds.

It is of note that smoking was allowed in operating areas of the process building such as the Mechanical Operating Aisles (MOAs). A Johnson & Higgins insurance inspection report from 1972 (Nelson 1972) echoes information seen in other documents that smoking in contaminated areas was an issue at West Valley. They recommended more extensive posting and enforcement of "no smoking" requirements in surface contamination areas. As of January 1, 1973, smoking, eating, drinking, or chewing were prohibited in Zone III or Zone IV areas, but smoking was still allowed in designated Zone II areas (NFS 1973a, p. 2).

2.2.3 Special Considerations for the Operations Era

Users of this site profile should bear in mind the West Valley reprocessing plant was an extreme radiological environment throughout the operations era. Fuel segmentation operations resulted in substantial quantities of high specific activity airborne particulate matter, resulting in significant operational difficulties associated with the plant ventilation systems and airflow issues. This, coupled with other unforeseen circumstances involving radioactivity in systems where it was not anticipated, or at unanticipated levels, meant radiological conditions encumbered operation of the facility from the outset. Routine, contact maintenance activities had to be performed in high dose rate environments. Dose rates in normally occupied areas were also high, and radiological contamination was substantial plant-wide from maintenance activities and spills (see Attachment A for details). High backgrounds compromised the effectiveness of contamination control measurements [1].

Document No. ORADI-TRDS-0037 REVISION NO. 00 Ellective Date. 00/22/2007 Fage 23 01 132	Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 23 of 152
--	------------------------------	-----------------	----------------------------	----------------

At its maximum, the plant employed a permanent work force of less than 200 persons during operations. Contract employees had to be brought in once the regular employees reached their quarterly dose limits. There are also reports of using persons "not normally assigned to radiation work" to complete high exposure tasks (Keely 1967a, p. 1). A 1972 insurance survey report remarked, "To facilitate operations and meet AEC established radiation exposure criteria the plant utilizes about 1000 temporary laborers each year. Radiation exposure and contamination hazards are extensive and ever present in this type of operation" (Johnson & Higgins 1972, p. 1).

Users of this site profile should recognize the principal focus of the radiation protection program at West Valley during its operations era was to minimize the number of individuals receiving exposures in excess of legal maximums [2]. This is particularly true for external exposures, which were controlled to a quarterly limit of 3 rem to the whole body. Quarterly skin and extremity limits were also enforced. Thresholds for internal monitoring were also applied, commensurate with the regulatory requirements of that era. Personnel exposures could not be optimized in accordance with normal radiation protection practice given the work environment. Therefore, any assumptions regarding the likelihood of personnel exposures at West Valley during its operations era based on job title or work area should be carefully considered [3]. In particular,

- For the period 1966 through 1973, users should not assume nonradiation workers or individuals whom did not normally work in the process building did not receive appreciable occupational exposures without additional justification.
- Users should be aware that significant contamination or exposure rates (or both) could have been present in areas not normally associated with personnel exposures, such as stairways, lobbies, etc. Significant contamination could result from large spills of process solutions, in which case it would be persistent indefinitely, or from widespread tracking of contamination from maintenance activities, which would not be detected until it reached lower background areas of the building. This consideration applies primarily to the 1966 – 1973 time period.

In addition to the following discussions of personnel exposure mechanisms at West Valley during operations, users are also referred to Attachment A for detail on the radiological environment in the process building and other areas.

2.2.4 Chronic Sources of Personnel Exposures

In a March 1972 letter, the AEC criticized NFS for designing its radiation control program vis-à-vis maximum allowable exposure limits for workers over the course of its operating history rather than making efforts to maintain low levels of exposure, consistent with "universally accepted" radiation protection practice. In response, NFS acknowledged it appeared that the principal cause of these conditions was "performance of plant equipment at less than design expectations" (Miller 1972a, p. 1). The overall largest contributors to the chronically high personnel exposures at West Valley during its operating years are discussed below.

2.2.4.1 Plant Ventilation Systems

The principal personnel exposure mechanism in the processing plant was "finely divided fuel particles" in direct-maintenance work areas adjacent to process cells, in analytical hot cells, in sample enclosures, solution storage areas, filter housings, and ventilation ducts. The particles were released during various head-end process operations, including shearing of fuel rods and transporting these from one process cell to another, dissolving of fuel, and handling the leftover cladding material following dissolving. The particles were a problem for both inhalation exposures and extremity

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 24 of 152
------------------------------	-----------------	----------------------------	----------------

exposures due to their high specific activity and significant beta dose rates (Keely and Wenstrand 1971).

The buildup of this high specific activity particulate matter in ducts and other parts of the ventilation system was a continuing problem. Following treatment in a washer (scrubber), ventilation cell air flowed through a 36-in. duct to filtration equipment at the base of the stack. Buildup of activity in that duct caused significant radiation levels in the Analytical Lab areas, the Lower Extraction Aisle (LXA), and the Control Room. Activity collecting in the washer caused exposure rates of 40 mR/hr in the Analytical Aisle, which was directly above the washer, during processing of high exposure fuels (NFS 1976). Particulate activity in the ventilation system ducting resulted in exposure rates as high as 100 mR/hr in the LXA (below the duct), 10 to 20 mR/hr in the Analytical Laboratories, and 5 to 10 mR/hr in the Control Room (NFS 1976). The plant design was such that periodic filter changes and other maintenance activities on ventilation system components were contact maintenance tasks, i.e., they could not be performed remotely. Personnel involved in these operations encountered considerable exposure rates.

In response to this problem the plant was modified in two ways. First, penetrations were made into the main ventilation system to allow periodic flushing to reduce built up particulate activity. These duct-flushing operations would temporarily reduce the exposure rates in personnel areas, but would also result in high airborne contamination in some areas while flushing was taking place. The second modification was to add an auxiliary ventilation system for the head-end process cells. This Head End Ventilation (HEV) system went into operation in October 1970. Following startup of the HEV system and decontamination of the original ventilation ducts and washer, radiation levels dropped by a factor of 5 to 10 in the Analytical Laboratories and in the Control Room (Miller 1972a, p. 5). However, radiation levels in the 36-in. duct continued to be higher than desired even after the HEV system came on line.

Wenstrand (1972a) states the ventilation duct running between the ventilation washer and the Ventilation Exhaust Cell (VEC) continued to be a primary source of radiation on three levels of the plant. It says the duct and washer were extensively decontaminated following startup of the HEV system to reduce exposure rates in the operating aisles. However, as of March 1972 the radiation levels from the duct had doubled since the decontamination. The report points out the duct contained a number of 90-degree bends that interfered with airflow.

2.2.4.2 Acid Recovery System

Due to startup problems with the waste evaporator systems in 1966, radioactive contamination was spread throughout the acid recovery system. This unanticipated radioactivity in the recovered acid system resulted in significant exposure rates in numerous areas of the processing plant where such elevated levels were not expected.

Carryover of radioactivity from the waste evaporators and buildup of ruthenium on the inner walls of the process chemical feed tanks resulted in exposure rates up to 100 mR/hr in the vicinity of the tanks. Ruthenium buildup also occurred in the recovered acid storage tanks located in the Hot Acid Cell. This cell was constructed of concrete block and did not afford adequate shielding. Exposure rates in the vicinity of the Hot Acid Cell therefore ranged from 100 mR/hr to 1,000 mR/hr. Activity in the recovered acid storage tanks caused exposure rates up to 10 mR/hr in the Control Room and Office areas (NFS 1976). It also caused elevated exposure rates outside the plant, e.g., in front of the office building.

Document No. ORAUT-TKBS-0057 Revision No. 00 Effect	ective Date: 06/22/2007 Page 25 of 152
---	--

2.2.4.3 Fuel Receiving and Storage Facility

The FRS facility was a significant source of personnel exposure for workers in the head end of the plant. The primary source of these exposures (internal and external) was contamination of the pool water from ruptured fuel elements, and failure of the cleanup systems to reduce activity concentrations to desirable levels. A significant decontamination effort was undertaken in the FRS for both the pool water and surrounding floors after the plant shut down in March 1972.

2.2.5 <u>Miscellaneous Sources of Personnel Exposures</u>

This section describes miscellaneous sources resulting in personnel exposures in the reprocessing plant. Attachment A to this document provides detailed information on operating areas and associated radiological conditions.

Buildup of Contamination in Piping

Radioactivity would accumulate in steam lines in the LXA, Upper Extraction Aisle (UXA), and the Chemical Operating Aisle (COA). These steam lines were used to jet process solution. Exposure rates from the lines were 10 to 30 mR/hr and contributed to personnel exposures during sampling and valving operations (NFS 1976).

Duct Flushing Operations

Penetrations were made into the main ventilation system in 1967 to provide for periodic flushing of the ductwork to reduce exposure rates in working areas. These duct-flushing operations would cause elevated airborne radioactivity levels in numerous areas of the plant. In July 1970 the following areas showed concentrations that would have resulted in inhalation exposure in excess of 40 maximum permissible concentration (MPC)-hours (TKW 1970):

- General Operating Aisle (GOA)
- MOA (east and west sides)
- Process Sample Cells (PSCs) 1, 2, and 3
- Extraction Sample Aisle (XSA)
- Pulser Equipment Aisle (PEA)
- South Stairs

Radioactivity in Cooling Water, Steam and Condensate Piping

Radioactivity in cooling water, steam, and condensate piping were a source of elevated exposure rates in the following areas (NFS 1976):

- COA
- LXA
- MOA
- Off Gas Aisle (OGA)
- UXA
- Utility Room
- High Level Waste areas
- Control Room

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 26 of 152

Analytical Activities

Elevated exposure rates existed in the vicinity of sampling stations from activity in sampling bottles and sample lines. Exposure rates were also elevated in the analytical laboratory areas from the handling and assay of samples (NFS 1976).

Extraction Cell Support Equipment

The Lower Warm Aisle (LWA), Upper Warm Aisle (UWA), and the PEA contained pumps, valves, and lines in shielded areas for the transfer of process solution within the process cells. These areas frequently became contaminated from maintenance activities.

2.2.6 Personnel Exposures Associated with Specific Tasks or Duties

This section contains personnel exposure information associated with specific tasks or job duties at the West Valley processing plant in its operations period.

2.2.6.1 Maintenance Workers

Maintenance employees received exposures associated with repair, maintenance, and replacement activities for contaminated plant equipment. These activities often required "personnel exposures higher than those normally received by Operations employees" (NFS 1976).

Analysis of personnel exposure data for maintenance workers for 1970 to 1971 showed the principal sources of exposure for these individuals were the crane rooms and the acid recovery system. Most of the exposure in the crane rooms was associated with decontamination and shielding of the area and equipment before maintenance activities. The total collective dose for prejob decontamination and shielding activities in the three crane rooms was 221 person-rem/yr (NFS 1976).

The maintenance task resulting in the highest personnel exposures was repair or replacement of the crane cable reels. Replacing or untangling of crane or hoist cables was also a significant source of personnel exposure for maintenance workers. Other tasks associated with significant dose to maintenance workers were repair or replacement of crane motors, repair of power manipulators, and retrieval of disabled cranes from the process cells. Collective dose for maintenance workers from decontamination and repair of Master-Slave Manipulators (MSMs) was 10 person-rem/yr. Collective dose for maintenance workers in the Equipment Decontamination Room (EDR) was 22 person-rem/yr (NFS 1976).

Another major source of personnel exposure for maintenance workers was servicing the steam jets used to transfer recovered acid to the acid storage tanks. The jets suffered from high corrosion rates, prompting numerous entries into the Acid Recovery Pump Room (ARPR) to change them. This activity resulted in collective dose of 106 person-rem/yr for maintenance workers. Another significant source of personnel exposure for maintenance workers associated with the acid recovery system was replacement of the heat exchangers in the Acid Recovery Cell. The heat exchangers became contaminated when seals failed, allowing contamination to enter the steam system. Repair and replacement of the heat exchangers resulted in 59 person-rem/yr of collective dose for maintenance workers (NFS 1976).

A cart mounted on a trolley was used for the transfer of samples of process solution between analytical cells. Repair and replacement of this cart following derailment was another source of personnel exposure for maintenance workers associated with the plants analytical areas. Cell entries would be required when the cart would derail, resulting in about 9 person-rem/yr associated with prejob decontamination of the cell and subsequent repair of the cart (NFS 1976).

Maintenance workers experienced high personnel exposures performing blower replacement activities in the Off Gas Blower Room (OGBR) and those associated with the Exhaust Cell Ventilation and HEV systems. These exposures were the result of the equipment being located in areas of elevated exposure rates. The exposure rate in the OGBR ranged from 1,000 mR/hr to 4,000 mR/hr from activity in the acid recovery system and the off gas treatment equipment. The VEC and HEV blowers were located in areas with a typical exposure rate of 100 mR/hr (from the filter banks) (NFS 1976).

Another source of personnel exposure for maintenance workers was repair or replacement of pumps in the UWA and LWA. The pumps were located in shielded locations adjacent to the process cells, and were used to transfer solutions within the cells.

The following is a chronology of radiation exposure conditions and events involving maintenance workers. A number of these involve skin and extremity exposures.

- October 1965: Maintenance was performed on a pump that had been used to empty a fuel cask. The pump read 11 R/hr and the exposure rate to the maintenance workers was a maximum of 1.2 R/hr (Loud 1965a).
- March 1967: "In general, the maintenance work in the Acid Recovery Cell necessitated exposures up to 1,000 mrem to people not normally assigned to radiation work" [emphasis added]. "These exposures began toward the end of March" (Keely 1967a, p. 1).
- December 1967: A maintenance worker received an extremity exposure of 44 rad during work in the GPC Crane Room (GCR) (Wenstrand 1968a).
- December 27, 1967: A maintenance foreman received an indicated 160 rad exposure to his hand as shown by a thermoluminescent dosimeter (TLD) worn as a finger dosimeter. Surveys of the work area concluded the exposure was from hot particles, as the maximum dose rate in the area was found to have been 16 rad/hr. The finger rings of two other individuals (maintenance workers) involved with the task showed 2 rad and 3.8 rad (Lewis 1968).
- June 1968: Installation of a new blower in the OGBR required 26 person-rem of collective dose. The typical working area exposure rate was 1 to 2 R/hr (Keely 1968a).
- August 1968: A maintenance worker received an extremity exposure of 22.5 rem and a skin exposure of 6.28 rem while working in the Recovered Acid Storage Area (Keely 1968b). A different report says his skin exposure was 5.33 rem, the 22.5 rem extremity dose was to the front of his hand, and he received 12.7 rem to the back of his hand. His whole-body exposure was 0.95 rem (Urbon 1968a, p. 2).
- September 1968: A maintenance worker received an extremity exposure of 18.82 rem working in the Chemical Cell Crane Room (Keely 1968c).
- October 1968: Changeout of the Dissolver Off Gas (DOG) blower in the OGBR required the use of 60 people and a collective dose of 48 rem whole body (Keely 1968d).
- December 1968: A maintenance worker exceeded his quarterly extremity exposure limit while working in the GCR. He received a dose of 21.750 rem (Keely 1969a).
- March 1969: A maintenance worker exceeded his quarterly extremity exposure limit when he received an exposure of 13 rem in the GCR (Keely 1969b).

Document No. ORAUT-TRDS-0057 REVISION NO. 00 Effective Date. 06/22/2007 Page 26 01 15	Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 28 of 152
---	------------------------------	-----------------	----------------------------	----------------

- May 1969: A maintenance worker received a skin exposure of 6520 mrem while changing a pump in the hot acid storage area (Keely 1969c, p. 1).
- June 1969: A maintenance worker received an extremity exposure of 11.7 rem during repair work on the GPC crane (Keely 1969d).
- July 1969: Two persons received extremity exposures of 15 rem and 30 rem while working in the GCR (Keely 1969e).
- October 1971: 61 "supplemental workers" received a collective 58 rem of dose changing a pump. NFS staff (operations, maintenance, and health and safety) received an additional 6 rem (Wenstrand 1971a).

NFS performed a review of 1970 and 1971 personnel exposure data for personnel involved in the "major work categories" of operations and maintenance. The average collective dose for operations and maintenance personnel over these 2 years was 985 person-rem and 1,002 person-rem, respectively. They assert incidents were minor contributors to these totals, which implies they were not biased by single events (NFS 1976).

Table 2-3 summarizes average annual collective dose for maintenance workers for typical tasks over the period 1970 to 1971 (NFS 1976). All collective dose data in this site profile reflect external exposure only.

Plant area	Typical work performed	Person- rem/yr
ARPR	Changing recovered acid jets	106
	Misc. maintenance: replacing valves, instrument lines, etc.	4
	Valving	2
	Inspections	1
ARC	Repair or replacement of 7C-3 heat exchanger	14
	Repair or replacement of 7C-5 heat exchanger	45
Analytical cells	Decontamination	5
	Repair, maintenance of transfer cart	4
CCR	Decontamination and shielding	53
	Repair or replacement of crane cable reels	40
_	Repair or replacement of crane motors	27
	Repair PAR	20
	Replace or untangle crane cable	8
	Repair of misc. items	10
	Structural repair of crane	8
	Retrieval of disabled crane	2
EDR	Decontamination and cleanup	7
	Repair of CPC eductors, jumpers, etc.	10
	Repair of CPC PAR	5
GCR	Decontamination and shielding	106
	Repair or replacement of crane cable reels	70
	Repair of cell door hoist	32
	Retrieval of disabled crane	23
	Replace or untangle hoist cables	25
	Repair PAR	19

Table 2-3. Average annual collective dose for maintenance workers for typical tasks, 1970 to 1971.

Plant area	Typical work performed	Person- rem/yr
	Repair or replacement of crane motors	10
	Misc. electrical repairs on crane	12
	Structural repair of crane	3
LWA	Changing pumps or valves	9
	Misc. maintenance	3
	Valving and inspection	1
OGBR	Change blower	6
	Change off gas scrubber pumps	5
	Misc. maintenance: replacing valves, instrument lines, etc.	5
HEV	Replace blowers	3
PMCR	Decontamination and shielding	62
	Repair or replacement of crane cable reels	40
	Replace or untangle hoist cables	31
	Repair or replacement of crane motors	13
	Misc. electrical repairs on crane	12
	PAR repairs	5
	Repair PMC cell equipment	2
	Structural repair of crane	2
UWA	Change pumps	12
	Misc. maintenance	3
VEC	Maintenance and repair of blowers	7
	Misc. maintenance	2
	Decontamination	6
VWR	Install new filters in washer	21
	Replacement and repair of pumps	9
MSM	Repair of manipulators	10
Plant	Misc. maintenance in plant areas (operating aisles)	62
Total		1,002

Table 2-4 ranks the tasks that resulted in the highest exposures (collectively) to maintenance workers in 1970 to 1971 (NFS 1976).

Table 2-4. Tasks with the highest collective exposures to maintenance workers, 1970 to 1971.

Area	Task	Dose
ARPR	Changing recovered acid jets	106
GCR	Decontamination and shielding	106
GCR	Repair or replacement of crane cable reels	70
PMCR	Decontamination and shielding	62
Plant	Misc. maintenance in operating aisles, etc.	62
CCR	Decontamination and shielding	53
ARC	Repair or replacement of 7C-5 heat exchanger	45
CCR	Repair or replacement of crane cable reels	40
PMCR	Repair or replacement of crane cable reels	40
GCR	Repair of cell door hoist	32
PMCR	Replace or untangle hoist cables	31
CCR	Repair or replacement of crane motors	27
GCR	Replace or untangle hoist cables	25
GCR	Retrieval of disabled crane	23
VWR	Install new filters in washer	21

Tables 2-5 and 2-6 show collective dose data for pump changes for the period 1970 through 1971 for the UWA and LWA, respectively.

Table 2-5.	UWA pump changeout data, 1970 and
1971 (Wen	strand 1974, p. 3).

Date	Exposure rate (R/hr)	Collective dose for changeout (person-rem)
1/2/1970	2	0.30
3/26/1970	5	0.47
4/7/1970	10	2.46
5/13/1970	4	1.20
7/6/1970	15	1.44
7/20/1970	4	2.70
2/3/1971	5	2.67
3/31/1971	2	1.46
6/26/1971	7	0.91
7/15/1971	3–5	3.26
10/29/1971	5	5.78

Table 2-6. LWA pump changeout data, 1970 and 1971 (Wenstrand 1974, p. 4).

Date	Exposure rate (R/hr)	Collective dose for changeout (person-rem)
3/23/1970	2	0.70
5/12/1970	3	1.20
5/20/1970	15	0.63
5/26/1970	10	0.88
6/16/1970	2	0.75
6/22/1970	2	0.73
6/30/1970	4	0.38
10/22/1970	7	1.81
11/25/1970	2	0.42
11/30/1970	10	2.85
6/7/1971	5	3.18
7/14/1971	3	1.05
8/3/1971	4	0.72

2.2.6.2 Operations

NFS' review of 1970 and 1971 personnel exposure data found the average collective dose for operations personnel over that period was 985 person-rem (NFS 1976). NFS asserted incidents were minor contributors to the collective dose for operations workers (as well as maintenance workers). Table 2-7 shows the breakdown of collective dose to operations workers for typical tasks and duties (NFS 1976).

Table 2-8 shows dose rates and occupancy times for Operations workers for various areas of the plant for July 1971 (NFS 1976). Table 2-9 shows a breakdown for analytical workers for the same period (NFS 1976).

			1
Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 31 of 152

2.2.6.3 Ventilation System Filter Changeouts

A large contributor to personnel exposures within Operations duties was changeout of ventilation system filters. These included filters associated with the main ventilation system, the HEV system, the DOG system, and the Vessel Off Gas (VOG) system. The average annual collective dose

	Average annual collective dose (person-rem) for operations workers fo					
		General	Ventilation	Acid recovery	Contact	
Plant area	Typical work performed	area	systems	system	maintenance areas	Total
FRS	Fuel receiving, storage, transfer to PMC	250				250
Labs	Sample analysis	50	90		10	150
CR	Process surveillance	5	75			80
GOA	GPC operations	20	60			80
XCR	Mixing chemicals, valving, readings	12	8	60		80
HEV	Filter changes	5	64			69
MOA	PMC operations	20	5		25	50
Sample stations	Taking process samples	20	10	10		40
SR	Decontamination of scrap casks and area	30				30
VEC	Change filters	5	23			28
	Miscellaneous	27				27
OGA	Chemical mixing, valving, readings	5	3	8		16
OGBR	Change filters		15			15
	Waste burial	15				15
	Hull burial	10				10
Offices	Supervision		1	6		7
COA	Valving, readings	4	1			5
PPS/PPH	Product loadout	5				5
Yard	Interceptor, lagoons, etc.	5				5
LLWT	Liquid waste treatment	4				4
LXA	Valving readings	1	3			4
PEA	Readings, valving	2		1		3
WTF	Readings, valving		3			3
CVA	CPC operations	2				2
LWA	Valving	2				2
UXA	Readings, valving	2				2
PCR	Sampling, valving, readings			1		1
UR	Auxiliary services operation	1				1
UWA	Valving	1				1
Totals		503	361	86	35	985

Table 2-7. Breakdown of the dose to operations workers for typical tasks and duties.

Area	Occupancy time (person-hrs./shift)	Dose rate (mR/hr)	Annual collective dose (person-rem)
XCR	6	8	53
Control room	18	1.5	30
UXA	2	1	2
PCR		100	
OGA	0.5	30	16
LXA	0.5	3	2
PPH/PPS	5	1	5
Sampling station	6	4	26
COA	3	1	3
WTF Shelter	0.5	5	3
LLLW	8	0.5	4
Interceptor	5	1	5
FRS	12	15	197
GOA	3	20	66
MOA	18	1.5	30
EDRVA	0.5	0.1	
CVA	8	0.1	1
Office building	7	1	7

Table 2-8. Dose rates and occupancy times for operations workers for various areas of the plant, July 1971.

Table 2-9. Breakdown for analytical workers, July 1971.

Area	Occupancy time (person-hrs./day)	Dose rate (mR/hr)	Annual collective dose (person-rem)
QC lab	12	1	5
Hot lab	36	3	39
Shift office	18	4	26
Hot cells	6	4	9
Supervisor's office	3	5	5
Alpha lab	3	3.5	4
Product lab	15	2	11
Emission lab	6	0.7	2
Mass spec. lab	18	0.7	5
Count lab	9	3	10

associated with changing the filters (roughing and absolute) in the VEC was 23 person-rem for 1970 to 1971 (NFS 1976).

Tables 2-10 through 2-12 below show personnel exposures associated with changeouts of main ventilation and HEV system filters during 1970 and 1971.

The November 1970 exposures are attributed to pre-HEV operation since the activity on the filters accumulated before the system was operating. The HEV system came online in late October 1970.

Additional information pertaining to filter changes follows.

• A memorandum dated December 9, 1966, says the plant ventilation system's roughing filters were changed "contact-wise in a radiation field of 5 to 10 R/hr" (Lewis 1966a).

	Change date	Collective dose (person-rem)
	03/25/1970	4.1
	04/13/1970	1.5
Before HEV operation	09/15/1970	15.8
	11/05/1970	10.1
	11/14/1970	4.1
	03/29/1971	4.5
After HEV operation	07/28/1971	3.2
	11/15/1971	2.2

Table 2-10. Personnel exposure associated with main ventilation system filter changes (NFS 1972a).

Table 2-11. Collective dose for changeouts of HEV system prefilters (NFS 1972a).

North train		South train		
Date	Person-	Date	Person-	
	rem		rem	
10/28/1970	0.2	10/29/1970	0.2	
11/02/1970	0.2	11/02/1970	0.2	
11/25/1970	0.65	11/28/1970	1.98	
12/01/1970	1.23	12/05/1970	1.52	
12/15/1970	4.25	12/23/1970	6.40	
01/02/1970	1.96	01/22/1971	1.01	
02/02/1971	1.40	02/24/1971	1.10	
04/01/1971	4.70	04/15/1971	0.50	
04/30/1971	1.92	05/18/1971	4.02	
06/04/1971	0.75	06/22/1971	0.52	
07/16/1971	4.17	08/04/1971	4.00	
09/17/1971	1.30	09/08/1971	10.00	
11/20/1971	1.37	10/07/1971	2.18	
		12/12/1971	4.58	

Table 2-12. Collective dose for changeouts of HEV system roughing filters (NFS 1972a).

Date	Person-rem
12/04/1970	2.29
12/14/1970	1.73
12/22/1970	2.76
03/01/1971	1.87
03/08/1971	2.15
06/21/1971	1.08
07/15/1971	3.20
10/14/1971	5.26

- The VOG filter read 30 R/hr at 2 ft on November 2, 1967. TLD measurements showed 77 R/hr and 280 rad/hr at 18 in. (Wenstrand 1967a).
- The DOG filter read 200 R/hr at 2 in. and 30 R/hr at 2 ft on November 9, 1967 (Wenstrand 1967a).

- A DOG filter changed on 3/9/1968 read 1000 R/hr at 2 in. and 200 R/hr at 4 ft. The filter was placed in a lead cask that read 10 R/hr to 30 R/hr at 2 in. By March 25, 1968, the new filter read 500 R/hr at 6 in. and 50 R/hr at 4 ft. (Wenstrand 1968b).
- In May 1968 the typical exposure rate in the filter room of the VEC at the start of a filter change was 35 R/hr. Replacement of 30 each roughing and absolute filters required 16 person-rem of whole-body dose (Keely 1968e).
- A DOG filter removed on November 27, 1968, read 1000 R/hr at 3 in. (Keely 1968f).
- Changeout of the main ventilation filters in November 1968 required "a total whole-body exposure of 3 rem" (Keely 1968f).
- In January 1972 HEV prefilters were removed from the south plenum using a new method utilizing the roof of the Filter Change Room. Personnel dose was 1.2 rem to the whole body. The new method is said to virtually eliminate extremity and skin exposure problems (Wenstrand 1972b).

2.2.6.4 Overall Workforce

The <u>average</u> yearly whole-body exposures for process, operations, and service employees working in or frequenting the normal access areas of the processing plant for 1968 through 1971 are as follows.

- 1968 = 2.74 rem/person
- 1969 = 3.81 rem/person
- 1970 = 6.76 rem/person
- 1971 = 7.15 rem/person

These are average whole-body exposures for individual workers. They are not collective dose (Miller 1972a). The increase in 1970 and 1971 over previous years reflects the processing of higher burnup fuels, which resulted in significant increases in personnel exposure throughout the site.

The average weekly whole-body exposure per person for 1967 for various responsibilities was as follows (Wenstrand 1967b):

- Head End Operations = 115 mR/wk
- Chemical Process Operations = 195 mR/wk
- Maintenance = 110 mR/wk
- Health & Safety = 80 mR/wk

Based on these data, NFS made the following projections for annual exposures per person in 1968 under the assumption that the weekly exposure date for 1967 did not change.

- Head End Operations = 5.8 rem/year
- Chemical Process Operations = 9.8 rem/year
- Maintenance = 5.5 rem/year
- Health & Safety = 4.0 rem/year

Table 2-13 through 2-17 below show collective whole-body, skin and extremity dose for various work groups for 1969 through 1971.

Table 2-13. Collective whole-body, skin, and extremity dose for various work groups, 1967 (Wenstrand 1971b, p. 5).

		Collective dose (person-rem)		
Dept.	No. workers	Whole body	Skin	Extremity
Analytical	28	66	175	176
Health & Safety	9	28	68	88
Maintenance	26	77	297	748
Production: Chemical	38	181	324	418
Production: Mechanical	29	77	243	418
Overhead + others	79	121	243	352
Total	209	550	1,350	2,200

Table 2-14. Collective whole-body, skin, and extremity dose for various work groups, 1968 (Wenstrand 1971b, p. 6).

		Collective dose (person-rem)			
Dept.	No. workers	Whole body	Skin	Extremity	
Analytical	34	77	130	331	
Health & Safety	14	62	116	156	
Maintenance	38	135	251	823	
Production	107	368	503	1,268	
Overhead	71	81	110	243	
Total	264	723	1,110	2,821	
Benz + non-NFS	106	127	210	579	

Table 2-15. Collective whole-body, skin, and extremity dose for various work groups, 1969 (Wenstrand 1971b, p. 7).

		Collective dose (person-rem)		
Dept.	No. workers	Whole body	Skin	Extremity
Analytical	29	122	164	763
Health & Safety	16	63	129	182
Maintenance	36	148	320	835
Production	74	404	727	1,649
Overhead	70	122	145	323
Total	225	859	1,485	3,752
Benz + non-NFS	82	109	153	251

Table 2-16. Collective whole-body, skin, and extremity dose for various work groups, 1970 (Wenstrand 1971b, p. 2).

		Collective dose (person-rem)		
Dept.	No. workers	Whole body	Skin	Extremity
Analytical	24	165	173	572
Health & Safety	14	108	230	374
Maintenance	34	204	358	837
Operations	61	532	693	1,459
Overhead	24	46	74	150
Tech. Services	6	43	59	109
Total (NFS)	163	1,098	1,587	3,501
Benz + non-NFS	472	433	1,043	2,630

		Collective dose (person-rem)					
Dept.	No. workers	Whole body	Skin	Extremity			
Analytical	25	146	154	544			
Health & Safety	15	116	236	361			
Maintenance	34	248	517	910			
Operations	66	589	900	1,665			
Overhead	15	41	57	109			
Tech. Services	7	32	47	78			
Total (NFS)	162	1,172	1,911	3,667			
Benz	991	1,194	2,677	4,690			

Table 2-17. Collective whole-body, skin, and extremity dose for various work groups, 1971 (Wenstrand 1972c, p. 2).

Table 2-18 shows typical exposures per person for various job duties for 1970. The data are typical whole-body, skin, and extremity dose per individual. They are not collective dose. The exposure data are for NFS employees. Exposures for contract workers are not included.

Table 2-18. Typical exposures per person for various job duties, 1970 (Wenstrand 1971b, p. 3).

		Typical yearly exposure (rem)			
Jo	b classification	Whole body	Skin	Extremities	
Analytical	Process Control Supervisors	7.3	7.9	26	
	Process Control Analysts	8.6	9.4	40	
	Special Lab Supervisors		6.0	14	
	Special Lab Analysts	6.3	6.4	15	
Health & Safety	Supervisors	8.7	12	23	
	A Technicians	7.9	20	28	
	B, C Technicians	7.2	16	16	
Maintenance	Management	8.9	15	52	
	Supervisors	8.2	15	32	
	Electricians	6.6	13	27	
	Instrument Technicians	7.7	11	16	
	Mechanics	6.9	11	32	
Operations	Management	8.6	10	24	
	Supervisors	10.5	15	32	
	A Operators	8.5	11	21	
	B, C Operators	7.6	10	21	

Table 2-19 shows typical exposures per person for various job duties for 1971. The data are typical whole-body, skin, and extremity dose per individual. They are not collective dose. Exposures for contract workers are not included.

Table 2-20 shows exposure rate data for the processing plant as of March 15, 1972 (after shutdown). From review of the March 1972 report (Wenstrand 1972a) and a follow-up report from July of that year (Wenstrand 1972d), it appears sometimes the exposure rates given are for the source itself, and other times they are general exposure rates in the affected area. Exposure rates that appear to be for a specific source are in **bold** type. These distinctions were drawn by comparing the March 1972 survey report with the follow-up report from July 1972.

Table 2-21 shows exposure rate data for various locations extracted from a health physics logbook for a period between July and December 1973 (NFS 1974c). More detailed information on exposure rates in a given area can be found in Attachment A.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 38 of 152

		Typical yea	Typical yearly exposure (rem)				
Jo	b classification	Whole body	Skin	Extremities			
	Supervisors	9.2	5.6	11.6			
Analytical	Process control	6.8	7.6	31.6			
	Spec. labs	4.4	4.4	13.2			
Health & safety	Supervisors	8.0	18.8	34.8			
	Technicians	7.6	16.0	24.0			
Maintenance	Management	8.4	15.2	20.0			
	Supervisors	7.2	17.2	26.8			
	Electricians	7.2	18.0	27.2			
	Instrument technicians	8.0	11.6	13.6			
	Mechanics	8.0	16.8	34.8			
	Management	6.8	8.8	18.0			
Operations	Supervisors	8.8	16.8	27.2			
Operations	A operators	9.6	13.2	24.8			
	B, C operators	8.8	13.2	26.0			

Table 2-19. Typical exposures per person for various job duties, 1971	Table 2-19.	Typical exposures	per person for various	iob duties. 1971.
---	-------------	-------------------	------------------------	-------------------

٦	Table 2-20.	Signific	cant radiation	sources in	the re	eprocess	ing	plant a	as of Ma	arch 15,	, 1972.
							-				

		Exposure rate	
Plant level	Radiation source	(mR/hr)*	Affected area(s)
Below grade	Contamination around leaking window	20	GOA
Delow grade	HEV Duct	10	GOA
	FRS	10–20	EMOA
	Manipulator Repair Room (MRR)	100	EMOA
100-ft elevation	HEV Room	10	MSM Shop
	Piping in window areas	100	WMOA
	Contamination around shear	2.5	
	Contamination in southwest stairwell	10	Showers and locker room
	Ventilation duct	50	LXA
	Contaminated piping and general	10	COA
114.5-ft elevation	contamination around the C-1 Sampler		
	Contaminated piping in the COA	50	COA
	Ventilation washer	5	LXA
	Ventilation duct	5–10	Laboratory area
131-ft elevation	Ventilation washer	10	Laboratory area
	PMCR Penthouse	5	Laboratory area
	Drain in hot laboratory	10	
	Ventilation duct	2.5	Control Room
144-ft elevation	Hot piping in UXA	20	UXA
144-IL Elevation	Ventilation filter bank	100	UXA
	Hot acid cell	10	Process Chemical Room
	Hot acid tanks, lines, and floor	1,000	XCR
	contamination		
160-ft elevation	Pump pot niche in the PEA	100	XCR
	Ventilation duct	50	XCR
	Hot acid tanks	1,000	XCR
Waste Tank Farm	Ventilation line	500	

2.3 REPROCESSING PLANT RESIDUAL RADIATION ERA, 1974 TO FEBRUARY 25, 1982

This era is characterized by miscellaneous decontamination and plant improvement work. The level of activity was not as great as the period between shutdown in March 1972 and May 1973.

•	data for various locations extracted	Exposure rate	Exposure rate	
Area	Date range	range: low	range: high	Remarks
Analytical aisle	July 9–December 27, 1973	1–4 mR/hr	2–12 mR/hr	
Analytical aisle-north	July 11–December 27, 1973	1–5 mR/hr	1–35 mR/hr	
Counting room	August 3–December 27, 1973	1–2 mR/hr	1–6 mR/hr	
Analytical supervisor's office	July 11–December 27, 1973	2–10 mR/hr	5–40 mR/hr	
Hot lab	July 11–December 27, 1973	1 mR/hr	1–8 mR/hr	
Emission spec. lab	July 11–December 27, 1973	< 1 mR/hr	1 mR/hr	
Mass spec. lab	July 11–December 27, 1973	< 1 mR/hr	1.5 mR/hr	
Product lab	July 11–December 27, 1973	1 mR/hr	1–30 mR/hr	Maximum at hood lip
QC Lab	July 11–December 27, 1973	1 mR/hr	1–13 mR/hr	Maximum at south hood
COA	July 9–December 31, 1973	1–3 mR/hr	1–10 mR/hr	
CVA	July 9–December 31, 1973	1–18 mR/hr	1–50 mR/hr	
Control room	July 9–December 31, 1973	1–3 mR/hr	2–6 mR/hr	
EDR viewing aisle	July 9–December 31, 1973	< 1 mR/hr	< 1 mR/hr	
LXA	July 9–December 31, 1973	1–20 mR/hr	2–35 mR/hr	
FRS	July 15–December 27, 1973	2–10 mR/hr	5–60 mR/hr	
GOA	July 10–December 29, 1973	2–6 mR/hr	2–20 mR/hr	
Instrument shop	July 10–December 26, 1973	1–2 mR/hr	1–2 mR/hr	
Laundry	July 10–December 29, 1973	0.5–1 mR/hr	1–3 mR/hr	
EMOA	July 9–December 27, 1973	1–3 mR/hr	2–10 mR/hr	
WMOA	July 9–December 27, 1973	1–3 mR/hr	1–15 mR/hr	
MSM Shop	July 10–December 29, 1973	1–3 mR/hr	2–20 mR/hr	
Personnel decontamination	July 11–December 27, 1973	< 1 mR/hr	< 1 mR/hr	
room				
Stairs-east	July 10–December 31, 1973	1–2 mR/hr	1–5 mR/hr	
Stairs-north	July 9–December 27, 1973	1–5 mR/hr	3–15 mR/hr	
Ventilation supply room	July 10–December 31, 1973	1–5 mR/hr	1–20 mR/hr	
UXA	July 9–December 31, 1973	1–15 mR/hr	3–30 mR/hr	
LLWT building	July 11–December 12, 1973	1–5 mR/hr	1–18 mR/hr	
WTF shelter	July 12–December 31, 1973	5–225 mR/hr	40–500 mR/hr	
WTF: over tanks	July 12–December 31, 1973	< 1–2 mR/hr	1–3 mR/hr	
XCR	July 18–December 17, 1973	1–10 mR/hr	1–30 mR/hr	
Off gas aisle	September 21–October 30, 1973	10–20 mR/hr	1000 mR/hr	Maximum was at NW corner; says 2–80 mR/hr "@ rope"
Pulser equipment aisle	September 21, 1973	10–300 mR/hr	10–300 mR/hr	Says "west niche" open [only one measurement recorded for 1973]
PCR	July 11–October, 30 1973	1–5 mR/hr	1–10 mR/hr	"Area being cleaned"
PSC-1	July 11, 1973	1–5 mR/hr	1–5 mR/hr	

Table 2-21. Exposure rate data for various locations extracted from a health physics logbook, July to December 1973 (NFS 1974c).
--

		Exposure rate	Exposure rate	
Area	Date range	range: low	range: high	Remarks
PSC-2	July 11–October 30, 1973	2–5 mR/hr	3–5 mR/hr	
PSC-3	July 11–November 3, 1973	5–45 mR/hr	5–50 mR/hr	
PPS	July 18–October 24, 1973	1–4 mR/hr	1–6 mR/hr	
PPH	July 18–October 24, 1973	1–2 mR/hr	1–3 mR/hr	
RER	August 6–October 24, 1973	1–35 mR/hr	1–50 mR/hr	
Rooftops	September 18–December 26, 1973	< 1–100 mR/hr	< 1–500 mR/hr	
South stairs	???–October 28, 1973	1–8 mR/hr	2–15 mR/hr	First entry not dated.
ULO	July 18–October 24, 1973	1 mR/hr	1–2 mR/hr	
Utility room	August 11–October 24, 1973	< 1–2 mR/hr	< 1–2 mR/hr	
NDA	October 24, 1973	0.3–0.5 mR/hr	0.3–0.5 mR/hr	Only one measurement recorded for 1973
XSA	July 11–November 3, 1973	1–6 mR/hr	1–10 mR/hr	

Document No. ORAUT-TKBS-0057 Revision No. 00 Ef	Effective Date: 06/22/2007	Page 41 of 152
---	----------------------------	----------------

Activities at the plant consisted of minor maintenance, decontamination projects, and laboratory analyses, including some for NFS-Erwin (Nelson 1976, p. 6 of inspection report). As of May 1975 they still received three to five fuel shipments per week, usually by truck in NFS shipping casks. Railroad shipments were rarely made by this time. There was approximately 115 tons of fuel in the SP, which was about 45% full (Johnson & Higgins 1975; Nelson 1976, p. 1).

A May 12, 1975, Nuclear Insurance Survey report by Johnson & Higgins states the highest level of personnel exposure at West Valley was around 400 mrem/quarter received by the fuel unloading operators, and that maintenance workers received about 200 mrem/quarter (Johnson & Higgins 1975).

The DOG system went inoperative in November 1975. The VOG system remained in use to ventilate gases from the vessels and tanks in the process building (WVNSC 1994).

Fuel receipts had ceased by 1980, though the plant was still storing spent fuel (Duckworth 1980). The fuel remained in storage until the early 1980s when it was removed by the DOE.

Table 2-22 shows exposure rate data for various locations extracted from a health physics logbook for a period between January and October 1974 (NFS 1974c).

Table 2-23 shows exposure rate data for later in the residual radiation era. The data are cited by Golden, Frank, and Prina (1982).

2.4 REPROCESSING PLANT DOE ERA, FEBRUARY 26, 1982, TO PRESENT

DOE took over operational control of the processing plant site on February 26, 1982 (WVNSC 1983). This included the high-level burial area [4]. Responsibility for the LLW burial area transferred to the State of New York in 1983 (NYSERDA 2004).

Decontamination of the main reprocessing plant took place in the early 1980's to allow for utilization of the existing facilities for the HLW vitrification project to the extent practical. Decontamination and fuel handling activities in the early years of the WVDP resulted in higher personnel doses than experienced later in the project (Hoffman 1997).

As of 1988, the following areas of the main plant remained contaminated and represented sources of potential personnel intakes (Johnson 1991):

- CPC
- PMC
- GPC
- Extraction Cell 1 (XC1)
- Extraction Cell 2 (XC2)
- Hot Acid Cell
- Plutonium Product Handling
- Solvent Storage Terrace

Inspections performed in 1986 found that much equipment in the head end cells (GPC and PMC) had fallen into disrepair. Cranes were not reliable, crane room doors were inoperable, and power manipulators and MSMs were inoperable or inaccessible (Vance 1986). Exposure rate surveys inside the cells found general levels ranged from 40 R/hr to 340 R/hr at a height of 6 ft. Hot spots were

Table 2-22. Exposure rate data for various locations extracted from a health physics logbook, January to October 1974 (NFS 1974c).

	_	Exposure rate	Exposure rate	
Area	Date range	range: low	range: high	Remarks
Analytical aisle	January 4–October 20, 1974	1–7 mR/hr	2–10 mR/hr	
Analytical aisle-north	January 4–October 20, 1974	1 mR/hr	1–15 mR/hr	From 6/2/1974 forward, 20 mR/hr "in paint on PMC door"
Counting room	January 4–October 20, 1974	1 mR/hr	1–4 mR/hr	
Analytical supervisor's office	January 4–October 20, 1974	5–20 mR/hr	5–40 mR/hr	
Hot lab	January 4–October 20, 1974	1 mR/hr	1–4 mR/hr	
Emission spec. Lab	January 4–October 20, 1974	1 mR/hr	1 mR/hr	
Mass spec. Lab	January 4–October 20, 1974	< 1 mR/hr	1 mR/hr	
Product lab	January 4–October 20, 1974	1 mR/hr	1–8 mR/hr	
QC Lab	January 4–October 20, 1974	1 mR/hr	1–2 mR/hr	
COA	January 10–October 18, 1974	1–3 mR/hr	1–5 mR/hr	
CVA	January 10–October 18, 1974	1–15 mR/hr	1–60 mR/hr	October 18, 1974 entry says 1–4 mR/hr, but this is an outlier with respect to the other entries, which are reasonably consistent.
Control room	January 10–October 18, 1974	1–3 mR/hr	1–6 mR/hr	
EDR viewing aisle	January 10–October 18, 1974	< 1 mR/hr	< 1 mR/hr	
LXA	January 10–October 18, 1974	1–35 mR/hr	1–65 mR/hr	
FRS	January 3–October 18, 1974	5–20 mR/hr	5–35 mR/hr	
GOA	January 3–October 18, 1974	2–7 mR/hr	2–20 mR/hr	
Instrument shop	January 17–October 2, 1974	1 mR/hr	1–2 mR/hr	
Laundry	January 2–October 18, 1974	< 1 mR/hr	1 mR/hr	
EMOA	January 3–October 18, 1974	1–4 mR/hr	1–10 mR/hr	
WMOA	January 3–October 18, 1974	1–2 mR/hr	1–5 mR/hr	
MSM shop	January 3–October 18, 1974	2–8 mR/hr	2–11 mR/hr	
Personnel decontamination room	January 2–October 20, 1974	< 1 mR/hr	1 mR/hr	
Stairs-east	January 10–October 18, 1974	< 1–3 mR/hr	1–4 mR/hr	
Stairs-north	January 3–October 18, 1974	1–4 mR/hr	1–8 mR/hr	
Ventilation supply room	January 10–October 18, 1974	1–12 mR/hr	1–20 mR/hr	
UXA	January 10–October 18, 1974	1–20 mR/hr	1–30 mR/hr	
UWA	May 10–October 18, 1974	1–15 mR/hr	1–20 mR/hr	
LLWT building	January 13–October 31, 1974	< 1 mR/hr	< 1–5 mR/hr	
WTF shelter	January 13–October 31, 1974	5–200 mR/hr	30–300 mR/hr	
WTF: over tanks	January 13–October 31, 1974	< 1–3 mR/hr	1–5 mR/hr	
XCR	January 13–October 20, 1974	1–5 mR/hr	1–15 mR/hr	

Area	Date range	Exposure rate range: low	Exposure rate range: high	Remarks
Off Gas aisle	January 15–July 30, 1974	10 mR/hr	1000 mR/hr	Maximum was at NW corner.
Pulser equipment aisle	January 15–October 1, 1974	2–20 mR/hr	2–25 mR/hr	
PCR	January 15–July 30, 1974	1–3 mR/hr	1–5 mR/hr	
PSC-1	January 15–July 30, 1974	1–5 mR/hr	4–8 mR/hr	
PSC-2	January 15–July 30, 1974	3–10 mR/hr	5–15 mR/hr	
PSC-3	January 15–July 30, 1974	1–3 mR/hr	5–20 mR/hr	
PPS	January 11–July 30, 1974	1 mR/hr	1–5 mR/hr	
PPH	January 11–July 30, 1974	< 1 mR/hr	1–2 mR/hr	
RER	January 11–July 30, 1974	10–20 mR/hr	2–60 mR/hr	
Rooftops	May 14–August 21, 1974	< 1–100 mR/hr	< 1–100 mR/hr	
South stairs	May 14–July 30, 1974	1–3 mR/hr	2–5 mR/hr	
ULO	January 11–July 30, 1974	< 1 mR/hr	1 mR/hr	
Utility room	February 12–July 30, 1974	1–2 mR/hr	1–3 mR/hr	
NDA	February 12–September 30, 1974	0.3–0.5 mR/hr	0.5–1.5 mR/hr	
XSA	January 15–July 30, 1974	1–5 mR/hr	1–8 mR/hr	
Old instrument shop	May 20–July 30, 1974	20–75 mR/hr	50–100 mR/hr	
VEC	June 3–July 30, 1974	5–250 mR/hr	5–250 mR/hr	Start date may be June 18.
Southwest stairs	July 30, 1974	2–45 mR/hr		Only one measurement recorded for 1974.

	or later in the residual radiation	
Area	Exposure rate (mR/hr)	Date
Extraction chemical room	5	Ca. 1981
Extraction cell 1	11,300	October 1978
Extraction cell 2	90	April 1978
Extraction cell 3	12	May 1978
Product purification cell	100	Not given
Acid recovery pump room	500 to 1000	March 1976
Liquid waste cell	150 to 1000	March 1976
Chemical process cell	12,000 to 32,000	Ca. 1981
Process mechanical cell	600,000 (maximum)	November 6, 1978
General purpose cell	650,000 (maximum)	November 6, 1978
Miscellaneous areas	2 to 10	May 22, 1980
Acid recovery cell	100 to 150	February 1974
Off gas aisle	1 to 2	September 1980
Upper warm aisle	12 to 90	May 1981
Lower warm aisle	5 to 40	April 16, 1974
Chemical operating aisle	10 to 20; 300 maximum	June 1981
Lower extraction aisle	10	September 18, 1972
Upper extraction aisle	2.5 to 60	May 1981
Mechanical operating aisle	0.1 to 10	May 1981
General purpose cell crane room	50 to 75	March 1978
Pulser equipment aisle	2 to 10	May 22, 1980
Southwest stairway	500 to 1000	Not given
Equipment decontamination room	10 to 100	1977
Scrap removal	1 to 10	1980

Table 2-23. Exposure rate data for later in the residual radiation era	Table 2-23.	a for later in the residual radiation	ו era.
--	-------------	---------------------------------------	--------

found as high as 2,050 R/hr. Solids and liquids (in sump areas) were sampled, showing high levels of ¹³⁷Cs and ⁶⁰Co, plus fissile and transuranic (TRU) species (Vance 1986).

The canisters of vitrified waste are stored in the CPC. An individual canister reads around 2,300 rem/hr at contact (Petkus et al. 2003). The logs of vitrified material read around 5,000 R/hr before being loaded in the canisters. High backgrounds are still a confounding factor with respect to radiation contamination surveys, though not to the extent they were when the plant was operating [5].

2.5 STATE-LICENSED (COMMERCIAL) WASTE DISPOSAL AREA, 1963 TO 1983

The SDA occupies approximately 15 acres of the Western New York Nuclear Service Center immediately adjacent to the 175 acres DOE is using for the WVDP. NFS opened the SDA in 1963 and continued to operate it until 1975, when disposal operations were terminated as a result of problems managing water that infiltrated the disposal trenches. Approximately 2.4 million ft³ of LLW were disposed of in the SDA. This included material such as dry active waste from the NFS reprocessing plant. NYSERDA currently has responsibility for the monitoring and maintenance of the SDA (NYSERDA 2004).

During operations, packaged waste was placed in long trenches excavated in the soil that were then backfilled. Water from rain and snowmelt was able to infiltrate the trenches through cracks and discontinuities in the trench covers and upper levels of the soil. Because of the highly impermeable nature of the soil surrounding the trenches, water accumulated in them and became contaminated from contact with the wastes. In early 1975, this accumulation, coupled with the site operator's (NFS) inability to gain regulatory approval to remove, treat, and discharge the trench water on a controlled basis to an adjacent stream, led to uncontrolled seepage of contaminated water from some of the

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 45 of 152
------------------------------	-----------------	----------------------------	----------------

trenches. Waste burial operations promptly ceased and the SDA has remained shut down ever since (NYSERDA 2004).

Between 1975 and 1981, NFS pumped water out of the trenches several times and treated it before release to the adjacent stream. Redesigning and reworking of the covers reduced, but did not eliminate, water accumulation in the trenches. Water management problems continued to be a concern at the SDA. In 1983, NYSERDA assumed management responsibility for the SDA from NFS (NYSERDA 2004).

In June 1973 the New York State Department of Environmental Conservation published a study of the waste inventory buried in the SDA and the NDA (Kelleher and Michael 1973). It said the greatest volume of waste came from waste disposal firms, most of which was associated with hospital, institutional and industrial activities. The use of the site by nuclear power plants was less than 10% of the total volume, though the authors noted the usage by nuclear power was increasing. ²³⁸Pu was asserted to be the nuclide of greatest concern in terms of its quantity and toxicity. The radionuclide present in the greatest quantity in terms of activity was tritium.

The SDA was closed March 8, 1975, upon discovery of tritium and ⁹⁰Sr in surface waters from leakage from the SDA. Studies of water pumped from the trenches in 1973 showed positive indications of gross beta and gross alpha activity (Duckworth 1976). A February 1974 report on radionuclide analyses on water from SDA trenches showed the following radionuclides: tritium, ⁹⁰Sr, ¹²⁹I, ¹²⁵I, ¹³⁷Cs, ¹³⁴Cs, ¹⁰⁶Ru, ⁵⁴Mn, ⁵⁷Co, ⁶⁰Co, ²²Na, ⁷⁵Se (NFS 1974d).

Tables 2-24 and 2-25 show estimated quantities of radioactive materials buried in the SDA through 1975. The authors did not decay-correct their estimates, which date back to 1963. The data are highly uncertain, as they were based upon assumptions of nuclide mix, waste volume ratios, etc. They are presented to give users an idea of the isotopes present in the SDA trenches more so than quantities or isotopic ratios. It is not clear what is meant by "Misc." or why they lumped together ¹²⁵I with ²²⁶ Ra and ²⁴¹Am (Duckworth 1978a, p. 1).

Table 2-24. Estimated quantities of Special Nuclear Material and source material in the SDA through 1975 (Greco 1978).

	Special nuclear material								Sour	ce material	
Pu-	238	Pu	-239	U-2	35	U-2	33	Th-2	232	U-238 +	Unat
Grams	Ci	Grams	Ci	Grams	Ci	Grams	Ci	lbs	Ci	lbs	Ci
2,136	37,339	2,018	123.906	51,202	0.103	255	2.422	15,393	0.769	1,010,594	151.590

	Eotimatoa	Taaloaotivit	y oontont in		anough fore		n 1070a, p.	<i>L</i>).
			_		I-125, Ra-226			
Tritium	C-14	Co-60	Cs-137	Sr-90	Am-241	Ru-106	Misc.	Pu-238
171,000	1,200	227,000	12,000	29,000	500	3,000	232,000	35,000

A review of solid waste disposal at the West Valley site through 1977 was generated as part of a Safety Analysis Report update in 1978 (Duckworth 1978b, p. 1). It showed a total of 2,349,000 ft³ of waste totaling 710,600 Ci of activity had been buried in the SDA from 1963 through 1975. This included 314,400 ft³ of waste from the reprocessing plant itself. A "special burial" of reactor parts took place at the SDA in 1973, involving an estimated 330,000 Ci of activity.

Radiological Data for the SDA

Three containers of HLW were received in September 1965 having a maximum exposure rate of 45 R/hr. The maximum exposure rate for the waste handlers was 200 mR/hr (Loud 1965b, p. 1).

Document No. ORAUT-TKBS-0057 Revision No. 00 Effective Date: 06/22/2007 Page 46 of 15

Two containers of HLW were received in October 1965 showing a maximum exposure rate of 11 R/hr. The maximum exposure rate to waste handlers was 500 mR/hr. Twelve containers shipped as LLW were received during the month, showing exposure rates from 220 mR/hr to 750 mR/hr (Loud 1965a).

Four shipments of HLW were received in November 1965 with the maximum exposure rate from the containers being 10 R/hr. The maximum personnel exposure rate was 1.5 R/hr to individuals rigging one of the containers (Loud 1965c).

Seven shipments of HLW were received for disposal in December 1965. The highest exposure rate of those containers was 70 R/hr. The maximum personnel exposure rate was 3 R/hr to individuals performing rigging for one of the containers. On December 10, 1965, the working area exposure rate for a crane operator moving HLW from storage into a trench was 25 mR/hr. The exposure rate for workers involved in removing HLW containers from transportation casks on December 31, 1965, was a maximum of 250 mR/hr. The exposure rate from the containers was a maximum of 5 R/hr (Loud 1966a).

High-level waste received for disposal in February 1966 showed exposure rates up to 170 R/hr. Personnel exposure rates for individuals working with these containers were up to 800 mR/hr. The fence around the HLW "compound" had to be relocated due to increasing exposure rates. The exposure rate through the concrete wall around the compound reached 190 mR/hr. The exposure rate at the barbed wire fence was less than 100 mR/hr, and at the chain link (outer fence) it reached 1 mR/hr (Loud 1966b, p. 1).

A container of HLW (received for disposal) in March 1966 read 240 R/hr, which exceeded NFS' license limit of 200 R/hr. They received permission to accept the container from the New York State Department of Labor (Loud 1966c).

2.6 HIGH-LEVEL WASTE DISPOSAL AREA, 1966 TO PRESENT

During the AEC/NRC-licensed era, material was buried at the NDA in holes (shafts) instead of trenches. Holes were dug 3 ft wide by 7 ft long by 50 ft deep. Waste containers were placed in the holes up to 6 to 8 ft below the ground level. They were then backfilled to a thickness of 4 ft above the original grade. Additional cover was added if necessary until a reading made with a GM survey instrument could not be distinguished from background. The holes were placed at least 6 ft apart. Equipment that was too large to fit in a standard-size hole was buried ad hoc. The principal material buried at the NDA was cladding hulls. However, a wide variety of other materials and items were also disposed of in the NDA, including ruptured irradiated fuel assemblies (Kelleher and Michael 1973, p. 8).

The review of solid waste disposal at the West Valley site through 1977 showed a total of 139,500 ft³ of material was buried at the NDA, totaling 551,300 Ci of activity (Duckworth 1978b, p. 1). Of this material, 6,400 ft³ was hulls (pieces of cladding left over after the fuel was leached out), 130,200 ft³ was miscellaneous items such as filters and equipment, and 2,900 ft³ was designated as "Under 200 mR" (Duckworth 1978b, p. 3).

The WVDP built a Liquid Pre-Treatment System on the northeast corner of the NDA. The purpose of the system is to remove organics (solvent) from groundwater around the NDA. As of 2004 the system had never been used (WVDP 2005).

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 47 of 152
------------------------------	-----------------	----------------------------	----------------

Radiological Data for the NDA

As of early 1968 hulls and scrap from the head end cells of the process plant were transferred for burial at least once a week (Runion 1968, p. 8 of Action Plan - Part 2). The burial area routinely exceeded 100 mR/hr in the area occupied by the remote crane operator, who was located in a shielded cubicle 100 ft from the crane. Additional shielding was supposed to have been installed by June 1, 1968, to ensure that the crane operator was not exposed to exposure rates in excess of 300 mR/hr. As of July 24, 1968, a lead glass window had been installed at the NDA to reduce the exposure to the crane operator. The shielding was said to have reduced the exposure rate from the hulls to "about 2 mR/hr," which is said to be indistinguishable from background (Clark 1968a, p. 1).

In July 1969 a dissolver removed from the CPC read 30 R/hr at contact with its shield cask and 50 mR/hr at 50 ft. Fluid leaked from the dissolver while transferring it to the burial area, contaminating the road surface to 50 rad/hr. Cleanup involved scrubbing and removal of some of the surface (Keely 1969e).

In November 1971 a spill contaminated several acres of ground north of the HLW burial area. Levels of 1 mR/hr to 3 mR/hr required extensive cleanup (Wenstrand 1971c, p. 2).

On June 26, 1972, cement blocks were removed from the OGA for burial. They were wrapped in plastic and then brought through the roof of the OGA where they were transferred from the roof to the "Red Stake Truck." The blocks read 5 R/hr (general area), and were described as grossly contaminated by NFS staff, having been used to shield an acid recovery line in the OGA. Contact dose rate measurements showed 15 R/hr, 40 R/hr, and 250 R/hr for whole body, skin of whole body, and extremities, respectively. The self-reading dosimeter of the worker whom unloaded the blocks showed 100 mR for the unloading operation. Afterward, the individual was found to be contaminated, and a nasal swab showed 180 dpm alpha and 170,000 dpm beta. Chemical analysis of the nasal swab showed 19.6 nCi of ¹⁰⁶Ru, 0.24 nCi of ⁹⁰Sr, 0.109 nCi of ²³⁹Pu, and 544 nCi of ⁹⁵Zr/Nb (Nelson 1973a, p. 14 of attachment). Estimates from whole-body counts were an exposure of 71 MPC-hr "of combined concentrations" of ²³⁹Pu, ¹⁰⁶Ru, and ⁹⁵Zr/Nb.

On July 6, 1972, a waste burial worker became contaminated while oiling a lift crane, but the contamination was not detected until the following afternoon. Surveys of his home found contamination on his bedding and jacket. A towel read 25,000 cpm with a GM survey instrument. A nasal swab collected on July 7 showed 5,800 dpm. Two urinalysis samples were collected on July 7 showing 11 dpm/24 hr and 14 dpm/24 hr "of fission products, ^{134,137}Cs." A chest count performed July 10 showed 32 nCi of ¹³⁷Cs.

2.7 ISOTOPIC INFORMATION FOR PLANT AREAS

2.7.1 Operations and Residual Radiation Eras, 1966 to February 25, 1982

Little radionuclide-specific information is available for surface or airborne contamination encountered in the processing plant prior to the characterization activities conducted under the WVDP. When the plant was operating, alpha contamination was assumed to be ²³⁹ Pu and beta was treated as ⁹⁰ Sr for radiation protection purposes (Clark 1968b). In general, contamination within the process building may be characterized as being associated with product streams, feed streams, or waste streams [6].

Available nuclide mix information for product streams show that the plutonium produced at West Valley was in general approximately 75% ²³⁹ Pu by weight (see Table 2-26). In terms of alpha activity, the data show that, in general, the dominant nuclide was ²³⁸Pu (NFS 1969) (HNS 1971). This is consistent with the reactor grade plutonium being separated. An exception is the mix asserted for the

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 48 of 152
------------------------------	-----------------	----------------------------	----------------

plutonium involved in a puncture wound incident in January 1972. This material was predominantly ²³⁹ Pu in terms of both mass and alpha activity (Wenstrand 1972e).

	May 30, 1969		19	71	January 24, 1972 ^a		
laatana	Weight	Alpha activity	Weight	Alpha activity	Weight	Alpha activity	
Isotope	fraction (%)	fraction (%)	fraction (%)	fraction (%)	fraction (%)	fraction (%)	
Pu-238	0.7	59.9	0.6	58.1	0.03	6.0	
Pu-239	76.8	24.1	76.1	24.7	90.7	69.9	
Pu-240	13.7	15.9	14.1	17.1	8.4	24.1	
Pu-241	7.7	0.1	7.9	0.1	0.8	0.02	
Pu-242	1.1	0.02	1.2	0.02	0.1	0.00	

Table 2-26. Isotopic mix data for West Valley plutonium product.

^aFrom a sampling needle responsible for a puncture wound

Plutonium associated with head end operating areas (those upstream of the extraction cells) would likely have been in a metal or oxide form (absorption type S) [7]. Plutonium associated with the process stream, such as would have been encountered in the process, analytical, and product handling areas, would have been in a nitrate form (absorption type M) unless it was known to have been aged contamination [8]. This freshly separated plutonium would have had very little ²⁴¹ Am [9]. If present, ²⁴¹Am should be considered as the same absorption type as the plutonium matrix in which it has ingrown. In other words americium should be treated as absorption type S if it is associated with type S plutonium.

If the chemical form of plutonium is unknown then either type M or S should be selected based on which type maximizes dose to the organ of concern. Bioassay data should be used to determine absorption type in cases where sufficient data exist to establish excretion or retention. Because the plutonium isotopic mixture encountered at West Valley was predominantly ²³⁸Pu on an activity basis, the Super S absorption type should not be applied (ORAUT 2007a). This approach should be applied for West Valley plutonium cases over the entire time period of concern. See also section 5.5.

Alpha contamination from process areas upstream of the extraction cells (in terms of process flow) would have included other alpha species representative of irradiated nuclear fuel. These too would have been in metal or oxide form [10].

As of December 1966 approximately 11,000 kg of commercial reactor fuel had been processed. The first 1,190 kg of uranium produced from this fuel contained 24 ppb plutonium, which exceeded NFS' specification. NFS planned to blend this material with other uranium for which the plutonium content was within specifications to get an acceptable mixture. In addition, all of the plutonium product recovered the week ending December 16, 1966, exceeded specifications for fission product contamination (Lewis 1966b).

From November 15, 1968, through January 20, 1969, the processing plant ran a THOREX fuel cycle to reprocess thorium-uranium fuel from Indian Point Unit 1. Thus, during this time thorium, thorium decay products, and ²³³U would have been encountered in the processing plant in addition to the other nuclides normally encountered. There was also higher than usual amounts of ²³⁵U and ²³⁸Pu present during this campaign (Birchler 1970).

Beta contamination at West Valley would have been a mixture of fission and activation products representative of irradiated nuclear fuel. The nuclides present would have included tritium, ⁵⁸Co, ⁶⁰Co, ⁹⁰Sr/Y, ⁹⁵Zr/Nb, ⁹⁹Tc, ¹⁰⁶Ru/Rh, ¹²⁵Sb, ¹³⁴Cs, ¹³⁷Cs, and ^{141,144}Ce [11]. In 1966, the principal gamma-emitters in the FRS pool water were found to be ⁵⁸Co, ⁶⁰Co, and ¹³⁷Cs (Loud 1966b). In May 1972

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 49 of 152
------------------------------	-----------------	----------------------------	----------------

isotopic measurements of FRS pool water included concentration data for ¹³⁴Cs, ¹³⁷Cs, ¹⁰⁶Ru/Rh, ¹⁴⁴Ce/Pr and ¹²⁵Sb (Jaroszeski 1972). Isotopes of ruthenium, rhodium, zirconium, and niobium were large contributors to the radioactivity in the acid recovery system (NFS 1976). ⁹⁹Tc was prominent in the Uranium Product Cell (UPC) (WVDP 2005).

Keely and Wenstrand (1971) state "entrainment" (resuspension) factors for radioactive particles found in "direct-maintenance" work areas in the plant ranged from 5E-06 m⁻¹ to 1E-03 m⁻¹ depending on work activity and airflow. The work areas they refer to included those adjacent to process cells, in analytical hot cells, in sample enclosures, solution storage areas, filter housings, and ventilation ducts. Resuspension factors were used in conjunction with smear surveys to predict work area air concentrations. Users should assume a particle size of 5 µm activity median aerodynamic diameter throughout the processing plant unless site-specific information is identified.

2.7.2 DOE Era, February 26, 1982, to present

One element of the WVDP was extensive characterization of plant areas and waste products. Characterization of HLW performed in 1986 determined the following radionuclides of concern (Johnson 1991).

Table 2-27. Radiofidelides of concern.				
Radionuclide	Chemical form			
Am-241	All forms			
Co-60	Co(NO ₃) ₂			
Cs-137	All forms			
Pu-238	PuO ₂			
Pu-239/240	PuO ₂			
Sr-90	SrSO ₄			
Th-228	Th(NO ₃) ₄			
Th-232	Th(NO ₃) ₄			
U-234	UO ₂ (OH) ₂			
U-235	UO ₂ (OH) ₂			
U-238	UO ₂ (OH) ₂			

Table 2-27.	Radionuclides of concern	

Strontium titanate was not present in the process building, so absorption type S should not be applied.

Assessments for radiation protection purposes determined that the major beta-gamma nuclides were ⁹⁰Sr/Y, ¹³⁷Cs, ⁹⁹Tc, and tritium. Alpha emitters of concern were isotopes of uranium and plutonium, and other major actinide series elements (²⁴¹Am, ²³²Th, et al.) and their decay products (Hoffman 1997).

Table 2-28 lists dominant radionuclides and conservative estimates of total activity for process building facilities and other site facilities. Some of the activity estimates give two values: one before deactivation and one after. All activity estimates are decay-corrected to September 30, 2004. It is implied the dominant radionuclides are listed in order of decreasing activity, though this is not explicitly stated in the reference (WVDP 2005).

Table 2-28. Dominant radionuclides and conservative estimates of total activity for process building facilities and other site facilities.

		Estimated total activity
Facility or area	Dominant radionuclides	as of 9/30/2004
Acid recovery cell	Pu-241, Am-241, Pu-239, Cs-137, Pu-240	192 Ci before deactivation 66 Ci after deactivation

Facility or area	Dominant radionuclides	Estimated total activity as of 9/30/2004 31 Ci		
ARPR	Pu-241, Pu-238, Am-241, Cs-137, Pu-239			
Analytical decontamination aisle	Cs-137, Sr-90, Pu-241, Am-241, Pu-239	0.1 Ci		
Analytical hot cells	Cs-137, Sr-90, Pu-241, Am-241, Pu-239	39 Ci		
CPC crane room	Sr-90, Cs-137, Pu-241, Am-241, Pu-239	5.5 Ci		
COA	Cs-137, Sr-90, Pu-241, Am-241	Not significant		
CPC	Cs-137, Sr-90, Pu-241, Am-241, Pu-238	116 Ci		
Contact size reduction facility (former MSM repair shop)	Cs-137, Sr-90	Not significant		
Control room	Cs-137, Sr-90	Not significant		
EDR	Sr-90, Cs-137, Pu-241, Am-241, Pu-239	39 Ci		
XC1	Sr-90, Cs-137, Pu-241, Am-241, Pu-239	4,900 Ci before deactivation 71 Ci after deactivation		
XC2	Pu-241, Sr-90, Am-241, Cs-137, Pu-238	2.0 Ci		
XC3	Sr-90, Cs-137, Pu-241, Pu-238, Am-241	1,274 Ci before deactivation 71 Ci after deactivation		
FRS	Cs-137, Sr-90, Pu-241, Am-241, Pu-239	282 Ci before deactivation 192 Ci after deactivation		
GPC	Cs-137, Sr-90, Pu-241, Am-241, Pu-238	6,000 Ci after deactivation		
GCR and crane room extension	Cs-137, Sr-90, Pu-241, Am-241, Pu-239	7.1 Ci		
GOA	Cs-137, Sr-90, Pu-241, Am-241, Pu-239	Not significant		
HEV building and HEV crane room	Sr-90, Cs-137, Pu-241, Am-241, Pu-238	610 Ci (assuming fully-loaded filters)		
Hot acid cell	Pu-241, Am-241, Pu-238, Pu-239, Pu-240	17 Ci (in tanks)		
Liquid waste cell	Sr-90, Pu-241, Cs-137, Am-241, Pu-238	1,014 Ci, mostly in tanks 280 Ci after tanks are removed.		
LWA	Pu-241, Am-241, Pu-238, Pu-239, Pu-240	85 Ci		
MOA	Cs-137, Sr-90, Pu-241, Am-241	Not significant		
Miniature cell	Cs-137, Sr-90, Pu-241, Am-241, Pu-239	8.5 Ci		
OGA	Pu-241, Pu-238, Am-241, Cs-137, Sr-90	40 Ci		
OGBR	Pu-241, Sr-90, Am-241, Cs-137, Pu-239	75 Ci		
Off gas cell (OGC)	Pu-241, Pu-238, Am-241, Cs-137, Sr-90	459 Ci		
PMC	Cs-137, Sr-90, Pu-241, Am-241, Pu-238	2,100 Ci		
PMCR and MRR	Cs-137, Sr-90, Pu-241, Am-241, Pu-238	5.2 Ci		
Product purification cell (PPC)	Pu-241, Am-241, Pu-239, Pu-240, Pu-238	43 Ci		
SR Room	Cs-137, Sr-90, Pu-241, Am-241, Pu-238	0.1 Ci		
Southwest stairs	Pu-241, Pu-238, Am-241, Cs-137, Pu-239	5.2 Ci		
UWA (and pump niches)	Pu-241, Am-241, Pu-238, Sr-90, Pu-239	26 Ci		
Uranium loadout area (ULO)	Sr-90, Cs-137, Pu-241, Am-241, Pu-238	0.1 Ci (in tanks and pumps)		
UPC	Cs-137, Sr-90, Tc-99, Pu-238, Am-241	12 Ci		
VEC	Cs-137, Sr-90, Pt-241, Am-241, Pt-238	66 Ci		
	Cs-137, SI-90, Pu-241, All-241, Pu-238	74 Ci		
Ventilation wash room (VWR Low level waste treatment (LLWT) building	Cs-137, Sr-90, Pu-241, Am-241, Pu-238 Cs-137, Sr-90	None available		
Permanent ventilation system (PVS) building	Cs-137, Sr-90	None available		
Supernatant treatment system (STS) support building	Cs-137, Sr-90, Am-241, Pu-241, Cm-244 (98% of the activity is Cs-137 and Sr-90)	213 Ci (in the valve aisle)		

3.0 OCCUPATIONAL MEDICAL DOSE

Presently, little information has been garnered on medical X-rays required as a condition of employment for West Valley workers. NFS (1976) indicated all radiation workers received preemployment physicals and annual physicals thereafter, with chest X-rays taken every 2 years. Review of claim files in the NIOSH-Office of Compensation Analysis and Support Claims Tracking System (NOCTS) shows workers under DOE received preplacement examinations, which included chest X-rays, and that workers included in respiratory protection programs (e.g., asbestos workers)

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 51 of 152
------------------------------	-----------------	----------------------------	----------------

received routine follow-up exposures. Chest X-rays for West Valley workers have always been performed at an offsite location.

Some of the claim files for West Valley workers make reference to "two view" posterior-anterior (PA) chest X-rays, [e.g., the worker received a "two view chest x-ray (posterior/anterior)]." It is believed the term "two view" reflects a misinterpretation of the stated PA orientation. There is no indication a second view (i.e., a lateral exposure) was ever taken in routine physical examinations.

Based on the above, users should apply the following assumptions when assigning occupational medical dose for West Valley workers. These assumptions should not be applied if specific information for a worker is available.

- For the period 1965 (onset of reprocessing plant operations) through February 1982, assume workers received a single PA chest X-ray at preemployment, every 2 years thereafter, and at termination.
- For March 1982 forward, assume workers received preemployment and termination examinations that included a single PA chest X-ray. If the worker was included in a respiratory protection program, assume he received additional PA chest X-rays every 2 years if under age 45 and annually if 45 or older.

The examination frequencies given for workers in respiratory protection programs are based on practices used at other DOE sites. For example, for 1990 through 2002, asbestos workers at Oak Ridge National Laboratory received chest X-rays every 3 years if they were under age 40, every 2 years if they were between 40 and 49, and annually thereafter. As of 2002, the frequency was changed to annual examinations for asbestos workers 45 and older (ORAUT 2006a). An assumption of an examination every 2 years if under 45 and annually thereafter is therefore believed to be favorable to the claimant.

X-ray examination frequencies are summarized in Table 3-1.

			Examination frequency				
			Additional examinations for workers in respiratory protection programs				
Period	Technique	All workers	Age <45	Age >45			
1965–February 1982	PA chest	Preemployment. Every 2 years. Termination.	None	None			
March 1982–present	PA chest	Preemployment. Termination.	Every 2 years	Annually			

Table 3-1. X-ray examination frequencies for West Valley workers.

Medical X-ray dose should be assigned using the organ dose values given in Table 6-5 of ORAUT-OTIB-0006 (ORAUT 2005a) for the appropriate time period in conjunction with the examination frequencies given in Table 3-1. Information in the claim file would get precedence in cases where examination frequencies could be shown to differ from those assumed in Table 3-1.

4.0 OCCUPATIONAL ENVIRONMENTAL DOSE

This section describes internal and external radiation exposures to workers while outdoors on the West Valley reprocessing plant or WVDP site. "Site" in this context means within the security fence. It does not refer to the Western New York Nuclear Service Center property within which the plant site

Document No. ORAUT-TKBS-0057 Revision	n No. 00 Effective Date: 06/22/	2007 Page 52 of 152
---------------------------------------	---------------------------------	---------------------

is located. NFS considered the boundary of the state property its site boundary during operations, not the area defined by its security fence [12].

4.1 INHALATION AND SUBMERSION DOSE

Airborne releases of radioactive material at West Valley were discharged to the atmosphere from the plant's 200-ft main stack and a number of ground-level release points associated with specific facilities or operations.

4.1.1 <u>Stack Releases</u>

The following discussion focuses on airborne emissions from the West Valley stack during operations. Stack releases after the plant ceased operating were much smaller in magnitude. The airborne effluents during operations are assessed using maximizing assumptions of 2,600 hr/yr of occupancy, a breathing rate of 1.5 m^3 /hr, and a particle size of 1 µm activity median aerodynamic diameter (AMAD). The latter leads to maximized organ dose for the nuclides considered. These maximizing assumptions would not normally be used in a site profile. In most cases a best estimate approach would be provided utilizing 2,000 hr/yr of occupancy and a particle size of 5 µm AMAD. A maximizing approach is used here to emphasize the magnitude of West Valley's airborne effluents vis-à-vis dose to personnel who spent time outdoors while onsite.

NFS' technical specification limits for airborne effluents were as follows (Runion 1970, Table 1):

- A continuous release limit of 0.1 µCi/s for particulates (alpha plus beta)
- A daily release limit of 12,600 Ci/d for ⁸⁵Kr
- An annual release limit for ¹³¹I of 3.3 Ci

The daily limit for ⁸⁵Kr reflects the batchwise nature of the fuel dissolving process.

NFS performed both continuous monitoring and sampling of its stack effluent. Monitoring data were usually provided in monthly plant status reports. Results were typically reported as a fraction (percentage) of the applicable technical specification limit. Occasionally, total activity would be included in monthly effluent statements, but in general, total activity was only reported on an annual basis.

Particulate releases reported prior to March 1969 represent 1 day of decay for short-lived activity. Beginning in March 1969, particulate samples were decayed for 3 days prior to counting (Keely 1969b).

4.1.1.1 Particulates

Table 4-1 shows total particulate releases (alpha plus beta) from the main stack for 1966 through 1972. Fuel dissolving was carried out between 1966 and 1971. The processing plant shut down in 1972 after completion of plutonium recovery operations.

West Valley's main stack 1966 through 1972.			
Year	Total particulates released (Ci)		
1966	0.15		
1967	0.45		
1968	1.14		

Table 4-1. Total particulate releases from West Valley's main stack 1966 through 1972

1969	0.12
1970	0.19
1971	0.01
1972	0.15

Table 4-1 shows 1968 was the maximum year for particulate releases from the West Valley processing plant, despite higher burnup fuels being processed in later years. The relatively large particulate release of 1.14 Ci for 1968 was the result of numerous filter failures (see North and Clark 1968 and NFS 1968).

NFS reported total beta and alpha particulate releases of 1.86E-1 Ci and 1.16E-3 Ci, respectively, for 1970 (Miller 1972b). These values give a beta-to-alpha ratio of 160. For 1971, NFS reported total beta and alpha particulate releases of 1.39E-2 Ci and 1.92E-4 Ci, respectively (Miller 1972b). These values give a ratio of 72. NFS (1976) states the ratio of 72 for 1971 was "also typical of other years."

Applying the beta-to-alpha ratio of 72 to the particulate release for 1968 gives 1.12 Ci beta and 1.56E-2 Ci alpha. These were the maximum particulate releases from the West Valley stack over its history. In terms of annualized release rate, the values are 3.55E-8 Ci/s beta and 4.95E-10 Ci/s alpha.

A calculation of site boundary alpha and beta particulate concentrations performed ca. 1974 (Author unknown ca. 1974) states the minimum dispersion (i.e., maximum concentration) is given by a dispersion coefficient of 2.5E-7 s/m³. This is a larger value than seen in more recent, albeit more formal, references. For example, the 1985 environmental monitoring report for the WVDP reports a maximum dispersion coefficient of 1.4E-7 s/m³ (WVNSC 1986, Table 4-1).

Since the annual average breathing zone concentration on the site property will be significantly less than that where the maximum dispersion coefficient occurs, using the maximum coefficient to estimate onsite concentration is favorable to the claimant. In this case, the maximum dispersion coefficient is $2.5E-7 \text{ s/m}^3$.

Calculation of maximized annual intake from the particulate releases for 1968 is shown below. The occupancy of 2,600 hr/yr reflects 50 hr/wk for 52 wk/yr.

Туре	Total release (Ci)	Annual release rate (Ci/s)	Dispersion coefficient (s/m³)	Concentration (Ci/m ³)	Concentration (Bq/m ³)	Breathing rate (m³/hr)	Occupancy (hr/yr)	Annual intake (Bq)
Beta	1.12	3.55E-08	2.5E-07	8.9E-15	3.3E-04	1.5	2,600	1.3E+00
Alpha	1.56E-02	4.95E-10	2.5E-07	1.2E-16	4.6E-06	1.5	2,600	1.8E-02

The magnitude of the maximum particulate intakes from stack emissions are such that selection of isotopic mix is largely immaterial. If one assumes Type M ²³⁹Pu for 100% of the alpha intake, the resulting effective dose is 8.5E-2 mrem for a particle size of 1 µm AMAD. The maximum organ dose is 2.7 mrem to the bone surface. Likewise, if one assumes Type S ¹⁰⁶Ru for 100% of the beta intake, the resulting effective dose is 7.4E-3 mrem and the maximum organ dose is 3.4E-2 mrem to the lung. These calculations reflect effective and organ dose coefficients from International Commission on Radiological Protection (ICRP) Publication 68 (ICRP 1995) and ICRP Publication 72 (ICRP 1996), respectively.

The calculations above show the magnitude of the particulate releases from the main stack, and associated personnel dose were of minimal consequence even under unrealistic, maximizing assumptions.

4.1.1.2 Krypton-85

Reports of the total activity of ⁸⁵K released for a given year have only been identified for 1966 through 1969. These are given in Table 4-2. The largest release for these years was 328,000 Ci in 1967.

Table 4-3 shows ⁸⁵Kr release data for 1967 and 1971 in terms of fraction of the daily release limit for each month. These are the only data available for 1971. No data have been found for 1970, but the 1971 releases should be comparable. There is little correlation between particulate and noble gas emissions, so particulate data are not a reliable means for estimating ⁸⁵Kr releases.

Table 4-2.	Total ⁸⁵ Kr releases from the
West Valle	y stack 1966 through 1969.

Year	Total Kr-85 released (Ci)
1966	77,000
1967	328,000
1968	193,000
1969	300,000

Table 4-3. Monthly ⁸⁵Kr release data for 1967 and 1971.

	Kr-85 releases	s (% of daily limit)	Kr-85 release	es (Ci/month)
Month	1967	1971	1967	1971
January	7.7%	50.0%	30,076	195,300
February	6.0%	52.0%	21,168	183,456
March	0.0%	10.3%	0	40,232
April	5.3%	22.0%	20,034	83,160
May	7.4%	No fuel dissolved	28,904	0
June	7.2%	30.0%	27,216	113,400
July	16.4%	40.0%	64,058	156,240
August	17.9%	42.0%	69,917	164,052
September	0.0%	7.3%	0	27,594
October	4.9%	41.0%	19,139	160,146
November	5.0%	27.0%	18,900	102,060
December	7.2%	N/A	28,123	0
Totals			327,537	1,225,640

The curies per month data given in Table 4-3 were computed by multiplying the reported fraction by 12,600 Ci (the daily release limit) and then by the number of days in the respective month. The Ci/month values for 1967 sum to 327,537 Ci, matching the reported value of 328,000 Ci in Table 4-2.

The total ⁸⁵Kr released in 1971 corresponds to an annualized release rate of 0.04 Ci/s. Applying the maximum dispersion coefficient of 2.5E-7 s/m³ (see Section 4.1.1.1) gives a maximum concentration on the site property of 1.0E-8 Ci/m³, or 370 Bq/m³.

The ICRP Publication 68 effective dose rate factor for ⁸⁵Kr is 2.2E-11 Sv/d per Bq/m³ (ICRP 1995). Applying this to the maximum ⁸⁵Kr concentration gives an effective dose rate of 8.14E-9 Sv/d, or 8.14E-4 mrem/d. Applying a maximizing assumption for occupancy of 2,600 hr/yr gives an effective dose of 0.09 mrem.

4.1.1.3 Iodine-131

The fuel processed at West Valley had decayed for a minimum of 12 months prior to dissolving. Longer cooling times were typical, particularly for fuel with high burnup (i.e., that from commercial

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 55 of 152
------------------------------	-----------------	----------------------------	----------------

power reactors). Currently, the data identified for airborne releases of radioiodines from West Valley during operations are incomplete. Data are available for 1966 through 1969 and for part of 1971 (July through December). The partial data for 1971 are shown in Table 4-4.

The data in Table 4-4 suggest the ¹³¹I released from the West Valley stack was a small fraction of the technical specification limit of 3.3 Ci/yr. Further, the iodine releases data given in monthly summary reports for 1966 through 1969 are never more than a small fraction of the technical specification limit. These values are reported as "less than" some fraction of the limit, though the fractions vary from month to month. The largest value observed was less than 7% of the limit reported for August and

for July through December 1971.					
Month	Curies discharged				
July	1.66E-04				
August	5.62E-04				
September	7.80E-05				
October	1.54E-04				
November	2.37E-04				
December	7.80E-05				

Table 4-4. Airborne releases of ¹³¹I for July through December 1971.

September 1968. However, 7% of 3.3 Ci is significantly larger than the releases given in Table 4-4 for 1971.

Given the variable and incomplete nature of the reported airborne iodine releases from West Valley, a maximizing evaluation was performed using the technical specification limit of 3.3 Ci/yr. In terms of release rate, 3.3 Ci/yr equates to 1.0E-7 Ci/s. Calculation of the associated maximized annual intake is shown below.

		Annual	Dispersion					
	Total	release rate	coefficient	Concentration	Concentration	Breathing	Occupancy	Annual intake
Туре	release (Ci)	(Ci/s)	(s/m³)	(Ci/m ³)	(Bq/m ³)	rate (m ³ /hr)	(hr/yr)	(Bq)
I-131	3.3	1.05E-07	2.5E-07	2.6E-14	9.7E-04	1.5	2,600	3.8E+00

The ICRP Publication 68 effective dose coefficient for ¹³¹I in vapor form is 2.0E-8 Sv/Bq (ICRP 1995). Using this value, an intake of 3.8 Bq gives an effective dose of 7.6E-8 Sv, or 7.6E-3 mrem. The Publication 68 organ dose coefficient for the thyroid for ¹³¹I in vapor form is 3.9E-7 Sv/Bq. This yields a maximum organ dose of 1.5E-1 mrem to the thyroid.

4.1.1.4 Tritium

NFS did not include tritium in its stack monitoring data during the operations era. Tritium was released from fuel assemblies during segmentation operations in the head end process cells. The U.S. Environmental Protection Agency (EPA) Office of Radiation Programs took measurements of tritium releases from West Valley over four processing campaigns from June through November 1971 (EPA 1972). They correlated their tritium release data to fuel burnup and then used NFS' processing records to estimate tritium releases over the past 6 years. They estimated a total of 2,800 Ci had been released, for an average of 460 Ci/yr. They determined the speciation was 76% tritiated water vapor (HTO) and 24% gaseous.

For a maximizing assessment, it is assumed the entire 2,800 Ci of tritium is released in a single year and that it is 100% HTO. Calculation of the associated maximized intake is shown below.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 56 of 152

		Annual	Dispersion					
	Total	release rate	coefficient	Concentration	Concentration	Breathing	Occupancy	Annual intake
Туре	release (Ci)	(Ci/s)	(s/m³)	(Ci/m ³)	(Bq/m ³)	rate (m ³ /hr)	(hr/yr)	(Bq)
Tritium	2,800	8.88E-05	2.5E-07	2.2E-11	8.2E-01	1.5	2,600	3.2E+03

Applying the ICRP Publication 68 effective dose coefficient for HTO (1.8E-11 Sv/Bq; ICRP 1995) gives an effective dose of 5.8E-8 Sv, or 5.8E-3 mrem. Multiplying by 1.5 to account for skin absorption gives 8.7E-3 mrem.

4.1.2 Ground Level Releases

There were several sources of airborne effluents at or near ground level at West Valley over its history. These included:

- Discharges from laundry facilities
- The FRS vent
- The Extraction Chemical Room (XCR) vent
- The XCR tank vent
- The Process Chemical Room (PCR) tank vent
- The Low Level Waste Treatment (LLWT) Facility

The above were sources of ground level airborne effluents while the plant was in operation. There were other sources of ground level releases during the WVDP, but these releases were much smaller in magnitude than those during operations. The following discussion focuses on the operations era.

Table 4-5 summarizes particulate discharges from the stack and ground level release points at West Valley in 1970 and 1971 (Miller 1972b).

	Total dischar	ges for 1970	Total discharges for 1971		
Source	Gross alpha (Ci)	Gross beta (Ci)	Gross alpha (Ci)	Gross beta (Ci)	
Stack	11.6E-4	18.6E-2	1.92E-4	1.39E-2	
Laundry	6.1E-6	2.4E-5	9E-7	8.9E-5	
LLWT			1E-7	1.7E-5	
FRS vent	2.5E-6	1.7E-4	9.2E-6	2.5E-4	
XCR vent	6.7E-6	1.7E-4	6.9E-5	6.6E-4	
PCR tank vent	5E-8	3E-6	5E-8	3E-6	
XCR tank vent	2.8E-6	8.5E-2	2.8E-6	8.5E-2	
Totals	1.178E-3	2.714E-1	2.74E-4	9.99E-2	

Table 4-5. Particulate discharges for 1970 and 1971.

Table 4-5 shows the largest source of beta particulate emission other than the stack was the XCR tank vent, which released 8.5E-2 Ci of activity for both 1970 and 1971. The XCR vent was the largest source of alpha particulate, with 6.9E-5 Ci being released in 1971. In terms of annualized release rate, these values are 2.7E-9 Ci/s and 2.2E-12 Ci/s for beta and alpha, respectively.

The 1985 environmental monitoring report for the WVDP reports a maximum dispersion coefficient for a ground level release of 6.44E-6 s/m³. This value corresponds to a receptor azimuth of 337.5° at a distance of 805 m (WVNSC 1986, Table 4-2). Use of this value with the above release rates to calculate intake is shown below.

Туре	Total release (Ci)	Annual release rate (Ci/s)	Dispersion coefficient (s/m ³)	Concentration (Ci/m ³)	Concentration (Bq/m ³)	Breathing rate (m ³ /hr)	Occupancy (hr/yr)	Annual intake (Bq)
Beta	8.5E-02	2.70E-09	6.44E-06	1.7E-14	6.4E-04	1.5	2,600	2.5E+00
Alpha	6.9E-05	2.19E-12	6.44E-06	1.4E-17	5.2E-07	1.5	2,600	2.0E-03

Treating the beta intake as 100% Type S 106 Ru of 1 µm AMAD particle size gives an effective dose of 1.6E-7 Sv, or 1.6E-2 mrem. Treating the alpha as Type M 239 Pu with a particle size of 1 µm AMAD gives an effective dose of 9.4E-8 Sv, or 9.4E-3 mrem.

4.2 AMBIENT DOSE

Nuclear-Chicago's "Explanation of Exposure Report Data" on the reverse of its exposure reports states ordinarily they considered any exposure on a control badge to be from a source other than that which caused exposure to a monitored individual. Control readings were therefore subtracted from readings of personnel badges (Author unknown ca. 1967). Likewise, the "Explanations and Remarks" on the reverse of Landauer's exposure reports says control readings were normally subtracted from personnel badge readings. However, it adds personnel badge readings may be normalized to Landauer's own control films (only) if it appeared the controls which accompanied the personnel badges had been "exposed differently than the personnel packet" (See Item 6 of Attachment B).

Exposure rates outside the process building during the operations era were significant with respect to exposure to control dosimeters stored in the Guard House. The exposure rate at the Guard House during operations was nominally 2 mR/hr from radioactivity in the plant's acid recovery system.

Heacker (1972) discusses the problem of dose accumulating on the control badges stored in the Guard House. He says the control badge for the week of December 20 to 26, 1971, showed 60 mrem because there was a drum reading 30 R/hr on a truck parked overnight at the cooling tower. The control badge reading for the following week was 20 mrem (Heacker 1972).

Per Heacker (1972), it is estimated control badges received a dose of 20 mrem/wk from elevated background during operations. Prorating this for 50 hours/wk of occupancy yields 6 mrem/wk which needs to be added to dosimeter and missed dose for monitored workers at West Valley over the period 1966 through 1973.

It is assumed the exposure rate at the storage location for the control badges was reduced following initial cleanup activities completed in 1973. An estimate of the dose rate to control badges in the Guard House for the period 1974 until 1982 can be made from later area monitoring data.

After DOE took over site operations in February 1982, dosimetry was only issued to persons whom entered radiologically controlled areas. An area monitoring program served to monitor exposures in uncontrolled areas to demonstrate compliance with applicable limits. The program used TLDs stationed in numerous (indoor) locations about the plant site. Reported results were net values above background stated in terms of mrem/500 hr of occupancy. Control TLDs were stored in a shielded location (e.g., see WVNSC 1999).

The earliest period for which area monitoring data are available for the Guard House is 1983 to 1985. The annual doses measured for that location were 14 mrem, 11 mrem, and 14 mrem for 1983 to 1985, respectively (Roberts 1986). These values are based on 2,000 hours of occupancy. Adjusting for 2,600 hours of occupancy, the maximum annual value of 14 mrem becomes 18 mrem. This dose

should be added to dosimeter and missed dose for monitored West Valley workers for the period 1974 to 1981.

Personnel dosimetry was required for entry into the plant security area during the operations and residual radiation eras. Users should not need to assign external dose for an unmonitored worker during this time. For the DOE era, monitoring data representative of what an unmonitored worker would have received from ambient exposure while outdoors on the West Valley site have not been identified. To be favorable to the claimant, it is assumed an unmonitored worker was exposed to an annual dose equal to the applicable administrative limit for the period in question. For 1982 through 1993 the administrative limit for annual dose to an unmonitored individual is assumed to have been 170 mrem (see Roberts 1986). For 1994 forward the annual limit was 100 mrem per 10 CFR Part 835.

4.3 SUMMARY OF EXPOSURES FROM ENVIRONMENTAL SOURCES

The maximizing calculations described in Section 4.1 show intakes associated with airborne effluents at West Valley were negligible.

Monitored workers should be assigned an additional 312 mrem/year to dosimeter or missed dose for the period April 1966 through 1973. For 1974 to 1981, 18 mrem/year should be added. The added dose should reflect the monitoring period, i.e., 6 mrem/week or 26 mrem/month for April 1966 through 1973, and 0.35 mrem/week or 1.5 mrem/month for 1974 through 1981. The dose should be prorated as appropriate for partial years of employment. The additional dose should be treated as photons in the 30- to 250-keV energy group (ORAUT 2006b).

Personnel dosimetry was required for entry into the plant security area between 1966 and February 1982, when DOE took over site operations [13]. Users should not need to assign external dose for an unmonitored worker during this time. For 1982 to 1993 170 mrem/yr should be assumed for unmonitored workers [14]. For 1994 forward, 100 mrem/yr should be assumed [14]. This dose should be treated as photons in the 30- to 250-keV energy group (ORAUT 2006b).

Table 4-6 summarizes external dose to be assigned to monitored and unmonitored workers at West Valley to account for excess background subtraction and onsite ambient exposures. All external dose assigned from Table 4-6 should be photons in the 30- to 250-keV energy group (ORAUT 2006b).

Table 4-0. External onsite environmental dose for west valley workers.				
	Monitored workers		Unmonitored	workers
	Additional dose		Ambient dose	
Year	(mrem/yr)	Uncertainty	(mrem/yr)	Uncertainty
1965	312	Normal, ±30%	N/A	N/A
1966	312	Normal, ±30%	N/A	N/A
1967	312	Normal, ±30%	N/A	N/A
1968	312	Normal, ±30%	N/A	N/A
1969	312	Normal, ±30%	N/A	N/A
1970	312	Normal, ±30%	N/A	N/A
1971	312	Normal, ±30%	N/A	N/A
1972	312	Normal, ±30%	N/A	N/A
1973	312	Normal, ±30%	N/A	N/A
1974	18	Constant	N/A	N/A
1975	18	Constant	N/A	N/A
1976	18	Constant	N/A	N/A
1977	18	Constant	N/A	N/A

Table 4-6.	External	onsite e	environmental	dose for	West	Valley	/ workers ^a .
------------	----------	----------	---------------	----------	------	--------	--------------------------

. 00 Effective Date: 06/22/2007 Page 59 of 152

	Monitored workers		Unmonitored	d workers
	Additional dose		Ambient dose	
Year	(mrem/yr)	Uncertainty	(mrem/yr)	Uncertainty
1978	18	Constant	N/A	N/A
1979	18	Constant	N/A	N/A
1980	18	Constant	N/A	N/A
1981	18	Constant	N/A	N/A
1982	0	N/A	170	Constant
1983	0	N/A	170	Constant
1984	0	N/A	170	Constant
1985	0	N/A	170	Constant
1986	0	N/A	170	Constant
1987	0	N/A	170	Constant
1988	0	N/A	170	Constant
1989	0	N/A	170	Constant
1990	0	N/A	170	Constant
1991	0	N/A	170	Constant
1992	0	N/A	170	Constant
1993	0	N/A	170	Constant
1994	0	N/A	100	Constant
1995	0	N/A	100	Constant
1996	0	N/A	100	Constant
1997	0	N/A	100	Constant
1998	0	N/A	100	Constant
1999	0	N/A	100	Constant
2000	0	N/A	100	Constant
2001	0	N/A	100	Constant
2002	0	N/A	100	Constant
2003	0	N/A	100	Constant
2004	0	N/A	100	Constant
2005	0	N/A	100	Constant
2006	0	N/A	100	Constant
2007	0	N/A	100	Constant

^a Additional dose should be prorated as appropriate for partial years of employment.

5.0 INTERNAL DOSIMETRY

5.1 INTERNAL DOSE CONTROL PROGRAM

5.1.1 Operations and Residual Radiation Eras 1966 – February 25, 1982

The internal dose control program at West Valley during operations consisted of screening methods such as air samples and nasal swabs as a method to estimate internal exposures. Bioassay was viewed as an evaluation aid in determining historical levels of exposure, and not as a means for exposure control (O'Reilly 1975). The screening tools were based on the legal thresholds for mandatory personnel monitoring, i.e., 25% of the applicable AEC or NRC limits (O'Reilly 1975). NFS was under regulation and oversight from the AEC over the entire operations era. Regulatory authority transitioned to the NRC in 1974. Radiation protection standards for the site were therefore prescribed by 10 CFR Part 20 throughout the operations and residual radiation eras, until operational authority was transferred to DOE on February 26, 1982.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 60 of 152
------------------------------	-----------------	----------------------------	----------------

5.1.1.1 Nasal Swabs

As of 1968, and through at least 1974, NFS' action limits for nasal swabs were 50 dpm alpha and 5000 dpm beta (O'Reilly 1975). NFS stated nasal swab results were "used as a screening technique to determine when further evaluation is required. If the nasal swabs indicate the alpha activity is less than 50 dpm, the exposure is considered by NFS to be far enough below the limits specified in 10 CFR 20.103 that further evaluation is not required." They asserted their 50 dpm alpha criterion corresponded to "about 25%" of the Part 20 limit, and point out that personnel monitoring was not required until 25% of the limit was likely to be exceeded. "This specific procedure has been in effect at NFS since 1968" (O'Reilly 1975).

As of 1972, nasal swabs were taken after "each zone entry" and counted for alpha and beta. If activity was detected, urinalysis and a whole-body count were performed. If alpha activity above 3 dpm/d was detected in the urinalysis, then fecal sampling was performed (Nelson 1973a, p. 5 of attachment).

NFS' 1973 Safety Analysis Report says nasal swabs were obtained upon exiting from Zone 4 areas to screen for inhalations (NFS 1976).

1974: Nasal swabs were taken when "potential for inhalation of radioactive materials has increased." "Based on the activity found on nasal swabs, additional internal monitoring such as bioassay sampling or whole-body counting may be required" (NFS 1974b).

5.1.1.2 Chest Counter

The chest counter was a 3- by 3-in. Nal detector formerly used as a thyroid monitor. Per Keely and Wenstrand (1971), the detector was collimated and used at a distance of 10 cm from the chest. (The detector was at 10 cm when the collimator was in contact with the subject being counted.) The chest counter was used at West Valley as a screening tool. Initially comparisons were made between the gross count rate from an individual suspected of an intake and that from a control subject. Later the procedure evolved to use a phantom as a control and a conversion factor for computing a measure of intake. The chest counter was in use at least as early as November 1966 (Helgeson 1966), and was used routinely back to at least 1967 (Miller 1972a).

As of 1971, the NFS procedure for use of the chest counter was to align the system using ¹³⁷Cs, count a phantom, then count the individual of interest. The counts were performed with the collimator in contact with the subject. The gross count rates for a region of interest 15 channels (8 below and 7 above) about the ¹³⁷Cs peak were determined for the phantom and the individual. The net count rate was computed and multiplied by a conversion factor to get "relative lung burden" (HNS 1971).

As of September 1972 the chest counter had been replaced by an on-site whole-body counter (Miller 1972a).

5.1.2 DOE Era February 26, 1982 – present

Presently, the WVDP uses a combination of bioassay and air sampling data for internal dose assessment. Air sampling data are used in cases where bioassay methods lack requisite sensitivity, e.g., for the alpha constituents of the mixed fission and activation product source term. In these cases, the detection limits associated with bioassay methods are such that the corresponding dose could exceed the site investigation level if it is assumed the date of intake was 12 months earlier. Derived air concentration (DAC)-hour calculations are therefore used to assess exposures to airborne

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 61 of 152
------------------------------	-----------------	----------------------------	----------------

alpha activity. Workers for whom decision levels are established via alpha air monitoring must also participate in the alpha *in vitro* bioassay program (Kubiak 1998 p. 14).

The WVDP investigation level for internal dose assessment is 100 mrem committed effective dose equivalent (CEDE). If a DAC-hour calculation gives a CEDE of 10 mrem or less, no additional action is taken. However, all data and calculations are placed in the worker's dosimetry file. If the calculated CEDE exceeds 10 mrem, then additional sampling is required (Kubiak 1998 p. 40).

5.2 BIOASSAY PROGRAM

5.2.1 Operations and Residual Radiation Eras 1966 – February 25, 1982

In vitro bioassay at West Valley during its operations era was a combination of routine and for cause analyses. Records show that ad hoc urine and fecal analyses were performed at least as early as September 1967. A routine urinalysis program was in place since at least 1968. It appears a routine fecal analysis program started sometime between 1968 and 1970 (Wenstrand 1968c) [15].

In vivo bioassay at West Valley during its operations era was performed using the chest counter (described above), a commercial mobile whole-body counting service, and a phoswich counter operated by the New York University (NYU) Medical Center in Rochester, New York. The latter was used for follow-up *in vivo* counts for TRU elements following significant intakes. An onsite *in vivo* counter was installed at West Valley sometime in 1972 (Miller 1972a).

As of 1967, the NFS bioassay program for plutonium depended upon the location in the plant where an intake may have occurred. If a suspected intake occurred in a mechanical processing area, it was assumed the intake would have been accompanied by fission products. Therefore, for these areas, the internal dose control program consisted of a combination of nasal swabs to look for gross beta activity and *in vivo* counting using the NFS chest counter. Follow-up bioassay (fecal sampling or *in vivo* counting) would be ordered based on the results of the nasal swab and chest count. Plutonium in the mechanical processing (head end) areas would most likely have been in an insoluble form (metal or oxide) (Runion 1967a, p. 3).

If a possible plutonium intake occurred in a chemical processing area, the plutonium would have been in nitrate (soluble) form. Urinalysis was therefore used for these individuals (Runion 1967a).

In April 1968 Clark (1968b) asserted NFS' procedures required urine samples if:

- There was a positive nasal swab
- Work was performed in an area with alpha contamination greater than 500,000 dpm/100 cm²
- There was a loss of air supply in an area with smearable alpha contamination greater than 500 dpm/100 cm² or smearable beta contamination greater than 50,000 dpm/100 cm²
- Facial contamination was detected above 50 cpm alpha or 100 cpm beta (per probe area)

It is assumed that a "positive" nasal swab referred to a result in excess of the action limits given in Section 5.1.1.1.

As of 1968 fecal sampling was not part of the NFS bioassay program except for on an ad hoc basis when deemed necessary by their Health and Safety Department (Clark 1968b). However, a February

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 62 of 152
------------------------------	-----------------	----------------------------	----------------

29, 1968, memorandum discusses start-up of a fecal monitoring program for workers whom routinely entered alpha-contaminated areas (Wenstrand 1968c). By 1970 this routine fecal sampling was an element of their program. A summary report from the bioassay technician for 1970 says 200 fecal samples were shipped out that year (Kester 1971).

As of 1972, "All permanent employees exposed to radiation receive an annual physical from the plant's physician" which included blood counts and "checks for internal alpha (plutonium) exposure" (Johnson & Higgins 1972]. NFS (1976) says a baseline radiation history was established for each radiation worker, which included a physical, blood counts, and urinalysis records. Blood counts and urinalysis were repeated semi-annually. It is not known how far back this practice dated.

As of September 1972 NFS had replaced the chest counter with a "shielded whole-body counter", and stated that "all plant personnel are now routinely counted by the whole-body counter once yearly and at any other time there is reason to believe an uptake has occurred" (Nelson 1973a, p. 5 of attachment). The annual whole-body counts replaced urinalyses for mixed fission products under an assumption that intakes of ⁹⁰Sr or ¹⁴⁷Pm would be accompanied by other, gamma-emitting isotopes (Nelson 1973b, p. 8 of enclosure).

NFS (1976) states urine samples were collected semi-annually on all radiation workers "to evaluate the potential long-term buildup of plutonium in the body." It appears this practice was in place at least back to 1969 (e.g., see Keely and Wenstrand 1971). Fecal samples were also collected from radiation workers on an annual basis and analyzed for plutonium. It appears this practice began sometime between 1968 and 1969 (see Clark 1968b and Keely and Wenstrand 1971).

As of October 1973 the frequency for plutonium urinalysis had been decreased to annually for radiation workers (Nelson 1973b, p. 8 of enclosure). NFS' calculations showed the program would detect a single intake of soluble plutonium of 20% of a MPBB 12 months post-intake. "Uranium exposures are evaluated by using plutonium as a tracer." "Commercial waste burial contractor employees" received annual whole-body counts and annual urinalyses for mixed fission products and tritium (Nelson 1973b, p. 9 of enclosure). Tritium had accumulated in water in burial trenches up to $0.1 \,\mu\text{Ci/cm}^3$. In an inspection report the AEC remarked on the fact annual urinalysis for tritium would represent a high limit of detection. Other contractor employees received bioassay evaluations if "nasal smears are positive and exceed specified limits" (Nelson 1973b, p. 9 of enclosure).

As of 1974 the internal monitoring program for radiation workers in the process building remained as it was in about October 1973. Annual urine samples were collected and analyzed for plutonium and all radiation workers were whole-body counted annually for fission products (NFS 1974b).

A May 18, 1977, memorandum says NFS' procedures had been modified to implement entrance and termination whole-body counts. This was apparently not being done before this time (Oldham 1977).

NFS sometimes experienced delays in processing bioassay samples. A December 28, 1967, letter from the AEC stated, "The bioassay program needs modification and improvements. Specifically the procedure for issuance, follow-up and retrieval of filled urinalysis sample bottles from employees as well as records thereof have not been effective in some instances ... A better effort is necessary in obtaining more timely samples following evidence of possible internal depositions." Earlier that year (September), 38 bioassay samples were lost due to an error by the parcel delivery service used (Clark 1968b). In 1974 a worker involved with possible inhalation exposure submitted urine samples on February 23 and 24 which were not sent to the vendor for analysis until May 16, 1974 (O'Reilly 1975). It is not known how NFS stored its samples or if preservatives were added.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 63 of 152
------------------------------	-----------------	----------------------------	----------------

5.2.1.1 Bioassay Records

As of April 1968 a "Bioassay Log" was kept documenting the names of employees involved in the bioassay program and dates their samples were issued and shipped (Clark 1968b).

As of April 1972 exposure to airborne radioactive material was recorded on a "Lapse of Radiation Control" form. "Bioassay results and whole body counts are recorded on appropriate forms in the individual personnel folders and are available for examination by the employee" (Miller 1972a). A September 7, 1972, memorandum confirms this practice (Duckworth 1972).

In its 1973 Safety Analysis Report, NFS said dosimetry records were maintained by the Health and Safety Department for each employee or worker (NFS 1976). These records included previous radiation exposure, current radiation exposure, urinalysis results, fecal analysis results, whole-body counting data, and "special reports," such as exposure estimates for lost or damaged film badges. These reports were submitted to the individuals and to the AEC as required.

5.2.2 DOE Era February 26, 1982 - present

Bioassay at the WVDP comes under six categories (Kubiak 1997):

- Baseline upon initial employment
- Re-entry, upon resumption of bioassay for an employee previously monitored
- Periodic routine bioassay
- Termination bioassay upon termination of employment or radiation worker status
- Discontinue bioassay upon transfer from monthly to quarterly external monitoring or removal from the respiratory protection program (*in vitro* only)
- Special bioassay

5.2.2.1 Routine Bioassay

The routine bioassay program at the WVDP includes both in vivo and in vitro monitoring.

All radiation workers are included in the *in vivo* bioassay program. In addition, any female whom declares a pregnancy receives both *in vivo* and *in vitro* bioassay at the time of declaration and when the pregnancy is declared ended (Kubiak 1998, p. 35).

All dosimetry qualified personnel monitored on a monthly basis or individuals with respiratory protection qualifications for work in radiological areas are included in the WVDP *in vitro* bioassay program. The *in vitro* program required baseline, annual, and termination sampling (Kubiak 1998, p. 31).

As of July 31, 1990, routine *in vitro* analyses for the WVDP were to include (WVNSC 1990a):

- Plutonium isotopic
- Total uranium
- ²⁴¹Am

• ⁹⁰Sr

As of December 7, 1990, routine in vitro analyses for the WVDP were to include (WVNSC 1990b):

- Plutonium isotopic
- Total uranium
- ⁹⁰Sr

5.2.2.2 Special Bioassay

Special bioassay is required if action levels established for workplace surface and airborne contamination levels and personnel contamination are reached or exceeded, or if otherwise requested by the RP Department management or technical staff. Special bioassay can be *in vivo* and/or *in vitro*. The action levels for special bioassay are (Kubiak 1998, p. 33):

- A routine bioassay measurement is determined to be positive for radioactive content.
- Facial contamination or detectable radioactivity on nasal or mouth swabs indicates a potential for intake.
- A respiratory protection factor for a respirator is exceeded and exposes the worker to airborne concentrations exceeding the DAC.
- Airborne monitoring indicates the potential for internal dose in excess of 100 mrem CEDE.
- Wound contamination (in or around a skin break), which is:
 - Greater than 100 dpm/100 cm² alpha
 - Greater than 10,000 dpm/100 cm² beta/gamma
 - Extensive personnel decontamination is required

5.2.3 Summary

Table 5-1 gives a summary of ad hoc and routine *in vivo* monitoring carried out at West Valley from 1966 to the present.

Period	Ad hoc	Routine
1966–September, 1972	 Chest counter used for onsite screening Ad hoc counts for TRU using the phoswich counter at NYU-Rochester (post-incident follow-ups) 	 Commercial, mobile whole body counter for annual counts of selected workers Routine counts using the chest counter (frequency unclear)
September, 1972–1977	Onsite whole body counter used for screening of suspected intakes involving MFP	 Radiation workers were counted annually for MFP using onsite whole body counter
1977–present ^a	 Onsite whole body counter used for screening of suspected intakes involving MFP 	 Radiation workers were given baseline, annual, and termination counts for MFP using onsite whole body counter

Table 5-1. Summary of *in vivo* bioassay frequencies for West Valley radiation workers.

a. In 1993 the system changed from a Nal detector and a bed geometry to an intrinsic germanium detector in a stand-up geometry.

Table 5-2 gives a summary of routine *in vitro* monitoring carried out at West Valley from 1966 to the present. *In vitro* bioassay was also performed ad hoc based on nasal smears or other indicators of

possible intake. The type of bioassay (urinalysis or fecal analysis) was selected based on the chemical form (soluble or insoluble) of suspected material.

Table 5-2. Summary of routine in vitro bioassay frequencies for West Valley radiation workers.

Period	Routine urinalysis	Routine fecal analysis
1966–1972	 Semiannual for all radiation workers for plutonium ≥ Annual for selected workers for MFP (may have been more frequent than annually) 	Annual for all radiation workers beginning ca. 1968.
1973–February, 1982	 Annual for all radiation workers for plutonium Annual for MFP and tritium for SDA workers (through 1975)^{a, b} 	None known
March, 1982–late 1990	• Baseline, annual, and termination for workers with monthly TLD exchange or with respiratory protection qualifications. Analytes were plutonium isotopic, total uranium, Am-241 and Sr-90.	None known
Late 1990-present	• Baseline, annual, and termination for workers with monthly TLD exchange or with respiratory protection qualifications. Analytes were plutonium isotopic, total uranium, and Sr-90.	None known

a. Annual whole body counts replaced routine urinalysis for mixed fission products (MFPs) for workers in the process building.
b. The SDA was closed in May 1975.

5.3 IN VITRO ANALYSES

5.3.1 Operations and Residual Radiation Eras 1966 – February 25, 1982

In vitro bioassay at West Valley during its operating era was generally performed by commercial vendors. However, it appears nuclide-specific urinalyses (i.e., those not analyzed for mixed fission products) were performed in house in 1970 (Kester 1971). It is not known when this practice actually began or how long it continued.

As of June 1967 the minimum detectable "concentration" [sic] for the plutonium urinalysis vendor was 0.45 dpm/d (Clark 1968c).

A letter dated March 19, 1968, states the minimum detectable excretion <u>rate</u> for the bioassay laboratory performing their urinalyses for plutonium was "0.3 dpm/<u>L</u>" [sic] (Monroe 1968). Keely and Wenstrand (1971) show a value of 0.3 dpm/<u>d</u> for plutonium nitrate in urine.

NFS did not normalize its urinalysis results to a reference excretion rate of 1.4 L/d. Activity per 24 hours was computed by taking the product of the analysis result in activity per unit volume and the total volume collected and dividing the resulting activity by the sampling interval (e.g., see Author unknown 1974). So for example if 0.85 L was collected over a period of 12 hours and showed 0.12 dpm/L, the result would be recorded as

$$\frac{0.12 \text{ dpm/L} \times 0.85 \text{ L}}{0.5 \text{ d}} = 0.20 \text{ dpm/d}$$

The same result collected over 24 hours would have been reported as 0.10 dpm/d.

In general 24-hour urine samples collected at West Valley during the operations and residual radiation periods had an excretion volume of less than 1 L. Some instances were noted of greater than 1 L collections for periods greater than 24 hours in the NOCTS files, but these were uncommon. Users should therefore multiply urinallysis results reported in terms of activity excreted per liter by 1.4 to correct them to a reference excretion rate of 1.4 L/d.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 66 of 152
------------------------------	-----------------	----------------------------	----------------

The "Yearly Report from Bioassay Technician" for 1970 implies urinalyses for other than mixed fission products were performed onsite, and that counts were often lost "due to electrical storms." His numbers show approximately 10% of the counts were lost. The onsite counting in 1970 included samples collected in 1969 since they lost three months of counting due to a strike. Counting began in April 1970. For the year they counted 393 urine samples in house, shipped out approximately 150 samples for urinalysis for mixed fission products, and shipped out approximately 200 fecal samples (Kester 1971).

Sometimes a batch of urine samples from an individual would be submitted to the analysis lab with instructions to analyze the most recent sample first. The remaining samples were only to be analyzed if the initial analysis showed an activity concentration in excess of some threshold. Otherwise the lab was instructed to discard the remaining samples.

As of 1973 plutonium urinalysis was performed by a commercial vendor via plutonium separation and alpha spectroscopy. It was not performed onsite. The detection limit was 0.2 dpm/L (Nelson 1973b, p. 9 of enclosure). NFS' calculations showed the program would detect a single intake of soluble plutonium of 20% of a MPBB 12 months post-intake. "Uranium exposures are evaluated by using plutonium as a tracer."

In its report summarizing an inspection performed in October 1973 the AEC assumed a detection limit for tritium urinalysis of 0.02 μ Ci/L. It is not explicitly clear this was a representative MDC (Nelson 1973b, p. 9 of enclosure).

Table 5-3 summarizes analytes, vendors, and observed reporting levels for *in vitro* analyses at West Valley during the operations and residual radiation eras. The reporting levels represent "less than" values given in analysis reports, e.g., "< 0.3 dpm/L." In many cases reporting levels may be inferred from the analysis reports from the various vendors. Some reporting levels are *a priori* values, others are *a posteriori*. Reporting levels are not apparent in analysis reports for samples associated with incidents or which otherwise showed positive activity for all samples.

The information in Table 5-3 comes from NOCTS and other records. The analyses listed should not be interpreted as complete or inclusive. Analytes in addition to those in the table are likely.

Year	Analyte	Vendor	Observed reporting levels
	MFP in urine	Controls for Radiation, Inc.	10 to 50 dpm/L
	Gross beta in urine ^a	Teledyne	7770 dpm/L ^b
1967	Total U in urine	Controls for Radiation, Inc.	0.1 µg U/L
1907		Teledyne	0.1 μg U/L
	Total Pu in urine	Controls for Radiation, Inc.	0.2 to 0.4 dpm/L
		Teledyne	0.3 dpm/L
	MFP in urine	Teledyne	30 dpm/L
	Total U in urine	Teledyne	0.1 μg U/L
1968	Total Pu in urine	Teledyne	0.3 dpm/L
1900	Pu-239 in feces	Eberline	0.9 dpm/sample ^c
	Total Pu in feces	Teledyne	0.3 dpm/g
		Eberline	0.3 dpm/g ^d
	MFP in urine	unknown	50 dpm/L ^e
1969	Gross beta in urine	Eberline	7770 dpm/L ^b
1303	Sr-90 in urine	Eberline	444 dpm/L ^b
	U-232 in urine	unknown	0.22 dpm/L ^t

Table 5-3. *In vitro* analyses and reporting levels for West Valley during the operations and residual radiation eras.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 67 of 152
------------------------------	-----------------	----------------------------	----------------

Year	Analyte	Vendor	Observed reporting levels
	U-235 in urine	Eberline	0.22 dpm/L ^t
	Total Pu in urine	unknown	0.3 dpm/L ^g
	MFP in feces	unknown	22 dpm/sample ^h
	Pu-239 in feces	Eberline	0.9 dpm/sample ^c
	Total Pu in feces	Eberline	0.3 dpm/g ^d
	MFP in urine	unknown	50 dpm/L ^e
1970	Pu-239 in feces	Eberline	0.9 dpm/sample ^c
	Total Pu in feces	Eberline	0.3 dpm/g ^d
1971	MFP in urine	unknown	50 dpm/L ^e
1971	Total Pu in feces	unknown	0.3 dpm/g ^d
	MFP in urine	unknown	50 dpm/L ^e
4070	Pu-239/240 in urine	Ledoux & Company	0.09 to 0.20 dpm/L
1972	Total Pu in urine	Ledoux & Company	0.20 to 0.40 dpm/L
	Total Pu in feces	unknown	0.3 dpm/g ^d
1070	Pu-239/240 in urine	unknown	0.3 dpm/L ^{g, i}
1973	Total Pu in urine	unknown	0.3 dpm/L ^{g, i}
	MFP in urine	Ledoux & Company	50 dpm/L ^e
	Tritium in urine	Ledoux & Company	4E-3 µCi/L
1974	Pu-238 in urine	Ledoux & Company	0.07 to 0.58 dpm/L
	Pu-239/240 in urine	Ledoux & Company	0.03 to 0.43 dpm/L
	Total Pu in urine	Ledoux & Company	0.07 to 0.72 dpm/L
	Tritium in urine	Ledoux & Company	4E-3 µCi/L ¹
1975	Pu-238 in urine	Ledoux & Company	0.05 to 0.10 dpm/L
1975	Pu-239/240 in urine	Ledoux & Company	0.04 to 0.07 dpm/L
	Total Pu in urine	Ledoux & Company	0.09 to 0.16 dpm/L
	MFP in urine	Eberline	50 dpm/L ^e
	Tritium in urine	Ledoux & Company	2E-3 µCi/L
	Pu-238 in urine	Ledoux & Company	0.06 to 0.10 dpm/L
1976	Pu-239/240 in urine	Ledoux & Company	0.05 to 0.08 dpm/L
	Total Pu in urine	Ledoux & Company	0.07 to 0.14 dpm/L
	Pu-238 in urine	Eberline	0.04 to 0.10 dpm/sample
	Pu-239 in urine	Eberline	0.05 to 0.07 dpm/sample
	Pu-238 in urine	Ledoux & Company	0.07 to 0.58 dpm/L ^k
1977	Pu-239/240 in urine	Ledoux & Company	0.03 to 0.43 dpm/L ^k
1377	Total Pu in urine	Ledoux & Company	0.07 to 0.72 dpm/L ^k

a. Result includes a value of 2 to 3 dpm/L for average ⁴⁰K excretion for an unexposed individual. This implies ⁴⁰K was not separated prior to counting for gross beta.

- b. Selected from ORAUT-TKBS-0026-5 Rev. 0 (technical basis document (TBD) for occupational internal dose for Argonne National Laboratory West) after a review of TBDs showed it to be the highest value for the time period of interest. This is a minimum detectable concentration (MDC) rather than a reporting level.
- c. Selected from ORAUT-TKBS-0007-5 Rev. 1 PC-1 (TBD for occupational internal dose for Idaho National Engineering Laboratory) after a review of TBDs showed it to be the highest value for the time period of interest. This is an MDA rather than a reporting level.
- d. Assumed same as reported by Teledyne.
- e. Assumed high end of range reported by Controls for Radiation, Inc. in 1967. This bounds the 30 dpm/L value reported by Teledyne in 1968.
- f. Reflects the MDCs given in ORAUT-TKBS-0026-5 Rev. 0 (TBD for occupational internal dose for Argonne National Laboratory – West) and ORAUT-TKBS-0007-5 Rev. 1 PC-1 (TBD for occupational internal dose for Idaho National Engineering Laboratory) for uranium isotopic analyses.
- g. Assumed the value given by Teledyne in 1968, which should be bounding for later analyses.
- Reflects the MDA given in ORAUT-TKBS-0007-5 Rev. 1 PC-1 (TBD for occupational internal dose for Idaho National Engineering Laboratory) for ⁶⁰Co, ⁹⁰Sr and ¹³⁴Cs.

- i. (Nelson 1973b, p. 9 of enclosure) reports a minimum detectable level of 0.2 dpm/L for plutonium in urine in 1973.
- j. Assumed value reported for 1974.
- k. Assumed range reported for 1974.

5.3.2 DOE Era February 26, 1982 - present

The WVDP continues to use vendors for analysis of *in vitro* bioassay samples. Required detection levels are specified by the WVDP for different analytes based on the requested turnaround time.

Table 5-4 shows the WVDP required detection levels for *in vitro* analyses as of September 12, 1990, for different turnaround times. "Priority 1 Processing" means immediate turnaround, Priority 2 was approximately 30 days, and routine processing was approximately 3 months (WVNSC 1990c).

Table 5-5 shows the WVDP required detection levels for priority and routine *in vitro* samples that were to be implemented "on or about" August 1, 1997 (Kubiak 1997, pp. 42–43).

		Priority 1 processing		Priority 2 processing		Routine processing
Analytical method	Analytes	Urine (dpm/sample)	Fecal (dpm/sample)	Urine (dpm/sample)	Fecal (dpm/sample)	Urine (dpm/sample)
Pu isotopic	Pu-238/239/240	8.0E-02	6.0E+01	2.0E-02	6.0E+01	2.0E-02
Am-241	Am-241	8.0E-02	3.3E+01	2.0E-02	3.3E+01	2.0E-02
Cm isotopic	Cm-243/244/245	1.2E+00	3.4E+01	2.0E-02	3.4E+01	2.0E-02
Th isotopic	Th-228/230/232	1.0E-01	3.0E+00	1.0E-01	3.0E+00	NA
Sr-90	Sr-90	3.4E+01	2.2E+04	3.4E+01	2.5E+04	3.4E+01
Sm-151	Sm-151	1.2E+02	3.1E+05	1.2E+02	3.1E+05	NA
Eu isotopic	Eu-154/155	8.0E+00	2.2E+04	8.0E+00	2.2E+04	NA
Total uranium	Total U	1.0 µg/sample	240 µg/sample	1.0 µg/sample	240 µg/sample	1.0 µg/sample
U isotopic	U-233/234/235/238	1.0E-01	3.0E+01	9.0E-02	3.0E+01	NA

Table 5-4. Required detection levels for WVDP in vitro analyses as of September 12, 1990.

Table 5-5. Required detection levels for priority and routine *in vitro* samples as of August 1, 1997.

Analytical	Urinalysis		Fecal analysis	
method	Priority	Routine	Priority	Routine
Pu isotopic	2.0E-01 dpm/L	2.0E-02 dpm/L	6.0E+01 dpm/sample	N/A
Am-241	2.0E-01 dpm/L	2.0E-02 dpm/L	3.3E+01 dpm/sample	N/A
Th isotopic	1.0E-0 dpm/L	N/A	3.1E+00 dpm/sample	N/A
Sr-90	8.9E+00 dpm/L	1.1E+00 dpm/L	3.1E+00 dpm/sample	N/A
Total U	2.0E-04 µg	2.0E-04 µg	5.3E+08 dpm/sample	N/A
U isotopic	1.0E-01 dpm/L	N/A	3.1E+01 dpm/sample	N/A

Table 5-6 shows the WVDP required detection levels for *in vitro* analyses as of March 14, 1998, for different turnaround times (WVNSC 1997).

Table 5-6. Required detection levels for WVDP in vitro analyses as of March 14, 1998.

Analytical		Urinalysis (dpm/L)			Fecal analysis (dpm/g)	
method	Analytes	Priority	Routine	Follow-up	Priority	Routine
Pu isotopic	Pu-238	2.2E-02	2.2E-02	2.1E-02	2.2E-03	N/A
	Pu-239/240					
Sr-90	Sr-90	8.9E+00	1.1E+00	9.1E-01	2.2E-02	N/A
KPA ^a	Total uranium	4.4E+05	4.4E+05	4.4E+05	N/A	N/A

Am-241	Am-241	2.2E-02	2.2E-02	2.1E-02	2.2E-03	N/A
Th isotopic	Th-228	2.2E-02	2.2E-02	2.1E-02	3.8E-03	N/A
	Th-230					
	Th-232					
U isotopic	U-233/234	2.2E+01	3.3E-02	3.3E-02	4.4E-03	N/A
	U-235					
	U-238					
Gamma spec	Cs-137	3.8E+01	3.8E+01	N/A	N/A	N/A

a. KPA = kinetic phosphorescence analysis.

As of September 12, 1990, if WVDP received an *in vitro* result showing a concentration greater than the required detection level, an evaluation was performed to determine if the result should be considered positive. A result greater than three times the 1-sigma error was considered positive and a confirmatory sample was collected. If the confirmatory sample also showed positive activity, then a dose assessment was performed. Results less than three times the 1-sigma error were considered nondetections (WVNSC 1990c). This practice continued until July 1997.

In July 1997 WVDP revised its decision criterion for positive *in vitro* results to one based on the standard deviation observed for a series of blank samples. An *in vitro* result greater than two times the standard deviation for the representative blank was considered positive (Kubiak 1997). This was subsequently revised further to assert decision levels as a fraction of minimum detectable activity (MDA). The WVDP decision levels as a fraction of MDA are given in Table 5-7. These values are as of November 23, 1998 (Kubiak 1998).

Table 5-7.	WVDP decision levels for positive in vitro samples as of
November	23, 1998.

Analysis	Urine detection limit	Fecal detection limit
Sr-90	\geq 0.93 MDA and \geq 4.9E-10 $\mu Ci/mL$	Not performed
Total uranium	≥ 3.8E-05 µg/mL	Not performed
Pu isotopic	Pu-238 ≥ 0.77 MDA	Pu-238 ≥ 0.71 MDA
Am-241	≥ 0.71 MDA	Not performed
Th isotopic	Any Th result \geq 0.71 MDA	Not performed
U isotopic	U-234 and U-238 ≥ 0.71 MDA	Not performed
	U-234/U-238 > 3 or	
	U-234 ≥ 0.71 MDA	
	U-238 < 0.71 MDA	

5.4 IN VIVO ANALYSES

5.4.1 Operations and Residual Radiation Eras

5.4.1.1 Chest Counter

In a December 1966 letter Helgeson states he felt that the NFS chest counter would see levels "much less" than 1 μ Ci for typical fission and activation products, and most likely levels "less than a few tens of nanocuries" (Helgeson 1966).

Results from the NFS chest counter are sometimes reported in nanocuries of ¹³⁷Cs and fraction of maximum permissible lung burden (MPLB). Other reports of chest counter data show total counts, a background count, the net count rate, and "relative lung burden" computed from the net count rate. Example values of relative lung burden are 20.17 and 13.17. Relative lung burden may be the same as percent MPLB, but this has not been verified.

5.4.1.2 Commercial Mobile Whole-Body Counting

December 1, 1966

Two West Valley workers were counted on December 1, 1966. Positive activity was reported for ⁴⁰K, ⁶⁰Co, ⁹⁵Zr/Nb, and ¹³⁷Cs for both individuals. Positive ¹⁰⁶Ru/Rh was reported for one of them. No ¹³¹I was observed in either individual (Helgeson 1966).

April 17 to 20, 1967

Helgeson Nuclear Services performed whole-body counts on 160 radiation workers at West Valley April 17 to 20, 1967 (Wenstrand 1967c). "Trace quantities of gamma emitting nuclides other than potassium-40 and cesium-137 were detected in 22% of the individuals counted. The maximum deposition was from Zr/Nb-95." Nuclides identified were ⁶⁰Co, ⁶⁵Zn, ⁵⁸Co (¹³⁴Cs), ⁹⁵Zr/Nb, ¹³⁷Cs, and ^{103/106}Ru. It was stated "All Co-58 results may be interpreted as Cs-134" (HNS 1967). Approximately one-third of Production, Maintenance, and Health and Safety personnel showed detectable internal deposition of radionuclides (Keely 1967b).

The mobile whole-body counter used was a scanning bed counter in a 24-ft van with an 8- by 4-in. Nal detector. Individuals were counted for approximately 8 minutes (HNS 1967).

Table 5-8 shows sensitivity data for the April 1967 whole-body counting for "typical" background at 2.326 sigma (99% confidence) (HNS 1967).

counting.		
Isotope	Background (cpm)	MDA
K-40	72.4	8.8 g
Co-60	38.7	0.81 nCi
Zn-65	57.8	2.73 nCi
Co-58	73.9	1.70 nCi
Zr/Nb-95	93.1	1.28 nCi
Cs-137	129.8	1.89 nCi
Ru-103/106	333.6	2.22 nCi

Table 5-8. Sensitivity data for April 1967 *in vivo* counting.

The format of the reports for the April 1967 in vivo counting is as follows.

Last name, First name + Middle initial, Social Security Number (SSN) Weight in pounds followed by seven values of net count rate (cpm) for ⁴⁰K, ⁶⁰Co, ⁶⁵Zn, ⁵⁸Co, ⁹⁵Zr/Nb, ¹³⁷Cs, and ^{103/106}Ru, respectively. ⁴⁰K result in grams of potassium ⁶⁰Co result in nanocuries ⁶⁵Zn result in nanocuries ⁵⁸Co result in nanocuries ⁵⁸Co result in nanocuries ¹³⁷Cs result in nanocuries ¹³⁷Cs result in nanocuries

Note that reported results may be negative.

April 15 to 17, 1968

128 people were counted by the mobile whole-body counting vendor from April 15 to 17, 1968. "The very high background encountered caused severe disturbances in the low energy end of the spectrum, below approximately 0.4 MeV." This affected the sensitivity for nuclides with primary

	Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 71 of 152
--	------------------------------	-----------------	----------------------------	----------------

gamma lines below this energy, such as ¹³¹I, ⁵¹Cr, and ^{141/144}Ce. The vendor estimated, based on visual inspection of the spectra, that none of those isotopes was present at a level greater than or equal to 10% of the MPBB. "The background at the whole-body counter was the highest in our experience." This was said to render their simultaneous equations for evaluating results "useless" (HNS 1968).

The format for 1968 in vivo counting reports is as follows (HNS 1968).

Name and SSN

Results: nuclide, units; result; two sigma confidence level; percent of MPBB or lung burden if determined to be insoluble. For potassium, the last value is the ratio of the grams of potassium to the individual's body weight in kilograms.

April 17 to 18, 1969

The commercial provider was on site for mobile whole-body counting from April 17 to 18, 1969. Only 29 people were counted. "Low levels of typical mixed fission and corrosion products were seen in a number of people" (HNS 1969a). "Eight people were measured for americium-241 and small photopeaks were visualized in the graphs in each of the eight. In every case, however, the level of activity was below what we define as our minimum sensitivity of 0.5 nanocurie." One individual was also counted for ²³⁵U. The ²⁴¹Am and ²³⁵U counts were performed using a 0.5- by 8-in. Nal detector. These were lung counts as opposed to whole-body counts (HNS 1969a). The sensitivity for ²³⁵U was asserted to be 50 µg (HNS 1969a). The ⁵⁰-µg sensitivity for ²³⁵U was asserted to be at a confidence level of "about 80%" (HNS 1969b). The ²⁴¹Am sensitivity is said to be 0.5 nCi ±0.5 nCi at 2 sigma.

The *in vivo* counts (whole body and lung) for April 1969 were performed at the "schoolhouse," which afforded a lower background than that experienced in previous years (HNS 1969a).

The results reports for 1969 should be self-explanatory. Table 5-9 shows sensitivity data for an 8-minute count using a background measured April 17, 1969, and assuming 140 g of potassium plus 10 nCi of ¹³⁷Cs in an individual. Sensitivity was defined as three times standard deviation of background divided by the calibration factor (HNS 1969a).

Isotope	Background (cpm)	Sensitivity (nCi)*
Potassium	90.81	22.5 g
Sb-124	41.93	2.3
Sb-125	224.88	7.4
Ba/La-140	56.71	2.0
Ce-144	497.99	27.3
Cs-134	153.32	2.3
Cs-137	186.77	2.6
Cr-51	351.97	29.0
Co-58	147.61	2.3
Co-60	82.12	1.7
Au-198	335.80	3.0
I-131	282.42	2.4
Ir-192	253.41	2.1
Mn-54	150.29	2.1
Hg-203	547.64	5.1
Ru-106	299.41	12.7
Se-75	247.67	5.2

Table 5-9. Sensitivity data for April 1969 in vivo counts.

Ag-110m	126.29	2.2
Sr-85	299.41	2.9
Ta-182	118.08	2.4
Tc-99m	473.99	1.9
Sn-113	185.98	3.0
Zn-65	103.94	4.5
Zr/Nb-95	167.63	2.7

May 10 to 11, 1971

The commercial provider was on site for mobile whole-body counting from May 10 to 11, 1971. Only 11 people were counted (HNS 1971). It appears they were all counted mixed fission and activation products (MFAPs), ²⁴¹Am, and ²³⁹Pu. Two of the 11 persons showed positive lung burdens of ²³⁹Pu/²⁴¹Am. The counts for MFAPs were still performed using the scanning bed counter. The ²³⁹Pu/²⁴¹Am counts were lung counts performed using a pair of 5-in.-diameter dual-scintillator (phoswich) detectors.

The "sensitivities" reported for mixed fission and activation products for the May 1971 *in vivo* counting were essentially the same values as from 1969 (HNS 1971). Sensitivities for plutonium counts were asserted for each individual based on estimates of chest wall thickness.

July 17 to 18, 1972

The commercial provider was on site for mobile whole-body counting July 17 to 18, 1972. Eleven individuals were lung counted for ²³⁹Pu and ²⁴¹Am, and four were counted for MFAPs (whole body). Due to a miscommunication, the persons counted for TRU elements were not counted for MFAPs, though they were supposed to have been. The lung counts for TRU elements were performed using the same phoswich detectors used in 1971. A 0.5- by 8-in. Nal was also used "for some studies in the lower energy regions" (HNS 1972). The initial results indicated one positive ²⁴¹Am count and two possible plutonium depositions (Wenstrand 1971d).

The sensitivity values for the July 1972 counts do not differ significantly from those given above for the 1969 counting.

5.4.1.3 New York University Medical Center Phoswich Counter

West Valley sometimes sent individuals involved in significant plutonium intakes for follow-up in vivo counting using the phoswich system operated by the NYU Medical Center in Rochester, New York. The Medical Center had two counters: a 8- by 4-in. Nal and a CsI-Nal phoswich detector. Individuals were counted for plutonium only unless sufficient time had elapsed since intake for ingrowth of ²⁴¹Am. Counts were performed of the head, chest, or liver.

In November 1967 the minimum sensitivity of the NYU plutonium counter is said to be an equivalent of 8 nCi of plutonium in the whole body based on a skull count (Lewis 1967a). As of July 1968 NYU stated the detection limit of their counter for plutonium was 1.0 nCi in the skull, corresponding to approximately 10 nCi in the whole body, and 2.0 nCi in the chest or liver (Laurer 1968).

5.4.2 U.S. Department of Energy Era

When DOE took over responsibility for operations at West Valley in February 1982, a bed-type lung counter was in use for *in vivo* monitoring. The counter used a single 4- by 4-in. Nal detector and a 256-channel MCA. The reported MDAs were 35 nCi for ¹³⁷Cs and 25 nCi for ⁶⁰Co. The 4-by-4 detector was used through at least February 1987. Later versions of *in vivo* monitoring procedures describe the lung counter as a 5- by 3-in. Nal detector surrounded by a 1-in. lead shield. This

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 73 of 152
------------------------------	-----------------	----------------------------	----------------

detector was in use by November 1988 (WVNSC 1988). Johnson (1991) reports MDAs for this system (for lung counts at contact) of 190 Bq (5.1 nCi) for ¹³⁷Cs and 55 Bq (1.5 nCi) for ⁶⁰Co. The lung counting system was only calibrated for ¹³⁷Cs and ⁶⁰Co.

As of May 12, 1993, the *in vivo* monitoring program had transitioned to a high resolution, stand-up scanning whole-body counter utilizing hyper-pure germanium detectors (WVNSC 1993). The MDA for this system is 7 nCi of ¹³⁷Cs, which is used as the tracer analyte in the WVDP *in vivo* monitoring program (Kubiak 1997, p. 20). Currently count-specific MDAs are reported for the nuclides in the counting library used (e.g., mixed fission and activation products). Hoffman (1997) states the *in vivo* counter can detect internal deposition of gamma-emitting nuclides "at a level much less than 10 nanocuries" and less than 1% ALI. At the time the *in vivo* laboratory participated in intercomparison studies.

5.5 INTERPRETATION OF BIOASSAY MEASUREMENTS FOR WEST VALLEY WORKERS

Tables 5-10, 5-11, and 5-12 show nuclide mix information for the MFAP, uranium, and plutonium source terms at West Valley as of January 1, 2000. These data were derived from (WVNSC 1997) by converting CEDE fractions to activity fractions. The alpha activity fractions for the plutonium mixture given in Table 5-12 were approximated by removing the ²⁴¹Pu activity and renormalizing the remaining constituents.

January 1, 2000.	
Nuclide	Activity fraction
Sr-90	46.73%
Cs-137	51.87%
Pu-238	0.05%
Pu-239	0.01%
Pu-240	0.03%
Pu-241	0.42%
Am-241	0.74%
Am-243	0.02%
Cm-244	0.12%

West Valley MFAP source term as of January 1, 2000.

Table 5-10. Nuclide mix information for

Table 5-11. Nuclide mix information for West Valley uranium source term as of January 1, 2000.

Nuclide	Activity fraction
Ra-226	0.00%
Th-228	0.97%
Th-229	0.02%
Th-230	0.02%
U-232	0.93%
U-233	5.63%
U-234	61.87%
U-235	2.44%
U-236	8.88%
U-238	19.24%

2000.		
Nuclide	Activity fraction	α activity fraction
Pu-238	10.55%	44.65%
Pu-239	2.86%	12.10%
Pu-240	2.18%	9.23%
Pu-241	76.36%	
Am-241	8.04%	34.02%

Table 5-12. Nuclide mix information for West Valley plutonium source term as of January 1, 2000.

The plutonium mixture in Table 5-12 is representative of aged material. Freshly separated plutonium during the operations era would not show appreciable ²⁴¹Am content and would be best represented by the activity fractions given in Table 2-26. Table 5-13 summarizes the alpha activity fractions to use for fresh and aged plutonium mixtures at West Valley. The mixture for the fresh material is the 1971 data from Table 2-26. Absorption type (M or S) should be selected based on what is known about the material involved in an intake. If the chemical form is unknown, then both type M and S should be used to see which results in the largest organ dose. The absorption type indicated by bioassay measurements should be used in cases where there are a sufficient number of measurements to make a determination. The absorption type S.

	α activity fraction for plutonium mixtures		
Nuclide	Freshly separated material	Aged material	
Pu-238	58.1%	44.65%	
Pu-239	24.7%	12.10%	
Pu-240	17.1%	9.23%	
Pu-241	0.1%		
Pu-242	0.02%	Not reported	
Am-241		34.02%	

Table 5-13. Nuclide mix for freshly separated and aged plutonium at West Valley

The same approach described above for selection of absorption type for plutonium should be applied for uranium and thorium. Absorption type should be selected based on which one yields the higher dose to the organ of interest unless there is sufficient bioassay data with which to make a determination. For uranium, users should select between absorption types F, M or S. For thorium users should select between absorption types M or S.

The nuclide mix information for MFAP given in Table 5-10 is representative of aged material. Fresh material would show additional, shorter-lived nuclides. These are discussed in Section 2.7.1. Specific nuclide mix information that would aid in the evaluation of *in vitro* analysis results for gross beta or MFP is not available. Keely and Wenstrand (1971) describe an incident involving inhalation of MFAP by two workers. *In vivo* counting performed three days post-intake showed the activity to be predominantly ⁹⁵Zr/Nb. The next largest contributor was ¹³⁷Cs, followed by ¹⁰⁶Ru/Rh and ⁶⁰Co. However, these *in vivo* results do not represent the activity mix of the inhaled material or consider other contributors such as isotopes of strontium, yttrium, cerium, and promethium.

The internal monitoring program at West Valley during operations was designed to detect chronic levels of intake corresponding to a threshold of 25% of applicable legal (10 C.F.R. pt. 20) limits. Radiation workers were included in routine *in vitro* and *in vivo* analysis programs, but the frequency and sensitivity of this monitoring was established relative to the 25% threshold for mandatory personnel monitoring. The routine *in vivo* monitoring program made use of the chest counter until

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 75 of 152
------------------------------	-----------------	----------------------------	----------------

mid-1972. The counter was aligned to count ¹³⁷Cs activity, which is cleared rapidly from the body following intake. The *in vitro* monitoring program for MFP would also have had limited sensitivity for non-chronic exposures.

Users may employ ORAUT-OTIB-0002 (ORAUT 2007b) or ORAUT-OTIB-0018 (ORAUT 2005b) as appropriate for assigning internal dose for unmonitored workers or those for whom monitoring data are missing or incomplete. These documents should be used in accordance with their stated applicability and limitations.

6.0 EXTERNAL DOSIMETRY

6.1 BASIS OF COMPARISON

From review of the available reference material, it appears external whole-body dose data for persons monitored at West Valley have always been reported in rem or fractions thereof. This includes dose to the skin of the whole body. However, the calibration methods used by the commercial dosimetry vendors or by the WVDP prior to becoming accredited under the DOE Laboratory Accreditation Program (DOELAP) are currently unknown. The WVDP external dosimetry program first became DOELAP accredited for whole body dose in January 1990 [16]. Users should therefore compute organ dose using conversion factors from exposure through 1989. From 1990 forward organ dose conversion factors from deep dose equivalent should be used. Skin dose measurements, if needed, should be used as reported.

6.2 SITE HISTORICAL ADMINISTRATIVE PRACTICES

NFS used vendors to process its whole-body personnel monitors from the onset of monitoring throughout its tenure at the site. No definite date has been established for when personnel monitoring began. The transition of responsibility for the site from NFS to DOE under the West Valley Demonstration Act also saw a transition to on-site processing of personnel whole-body dosimetry. This practice continues to the present. A vendor is used for extremity monitoring.

6.2.1 <u>Site Access Requirements</u>

NFS Radiation Work Permits prescribe the following personnel dosimetry requirements (NFS 1973a, p. 2):

- For plant entry: film badge
- For entry into Radiation Areas: film badge, dosimeters and current dose rate survey.
- For entry into High Radiation Areas: film badge, dosimeters and current dose rate survey.

NFS (1976) states all "employees and workers" entering radiation areas were required to wear film badges in addition to the indirect reading dosimeters. NFS (1974b, p. 4.0) states, "Each permanent employee is issued a film badge and dosimeter ... at the Guard House as he enters [the] exclusion area and he is to wear it all times in the plant areas." This is echoed in (Nelson 1973b, p. 7 of enclosure 2), which says, "First line control over the issuance of personnel monitoring devices is exercised at the Security Area Guard House." Dosimeters and badges worn by people "normally assigned to radiation work" were to be returned to the badge racks after each shift (NFS 1974b, p. 4.0). Temporary badges were supposed to be assigned if a worker lost his badge (Runion 1967, p. 2).

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 76 of 152
------------------------------	-----------------	----------------------------	----------------

It appears the same dosimetry requirements applied to workers in the waste disposal areas. Workers in the area now known as the SDA wore "radiation badges and gamma dosimeters" (i.e., film badges and pocket meters, respectively) (Author unknown ca. 1968).

NFS (1976) states neutron exposures were encountered in the FRS and the plutonium loadout area. "Neutron film badges" were therefore used in those areas. NFS (1974b, p. 4.0) states, "Special film badges sensitive to neutrons will be worn by personnel working in plutonium loadout and shipping areas when directed to do so. A satisfactory alternate procedure will be to place neutron films in typical locations and calculate exposures" using occupancy times. "On lower burnup fuels, Health and Safety will waive these requirements."

NFS' practice was to assign extremity dosimeters (TLDs) when extremity dose rates were expected to exceed those for the skin of the whole body (Duckworth 1973).

A memorandum titled "Personnel Accountability and Dosimetry" (Heacker 1972) discusses concerns about personnel accountability at West Valley during an accident scenario vis-à-vis their film badges. It states they could not be certain an individual had on the right badge or if they had a badge at all, and that the sign-in procedure was not rigorously followed. It mentions a "brown and white nuisance badge," but says not all employees wore them. It also says badges were checked for contamination each shift at the guardhouse, but they could still have undetected contamination inside them. The impetus for these statements was to emphasize the need, in Heacker's view, for photo badges such as those used at AEC sites. He used the photo badge in use at the time at Oak Ridge National Laboratory as an example. NFS' records show isolated cases of personnel picking up the wrong dosimeter at the storage rack on their way in to the plant, but it does not appear this was a common occurrence or that it happened at a disproportionate frequency relative to other facilities where a similar number of people were badged. Once recognized, cases where individuals wore the wrong dosimeter were addressed by sending the badges for processing and assigning new badges to the affected individuals. After processing, the reported dose was assigned to the appropriate individual. Dose could also be assigned through the use of survey data or pocket chamber readings. Concurrence was sought from the affected individuals when such dose estimations were made.

Under the current program, dosimetry is issued to radiation workers as follows, as "determined by the employee's potential exposure" (Hoffman 1997):

- Radiation Worker I, quarterly exchange
- Radiation Worker II, quarterly exchange
- Radiation Worker I, monthly exchange
- Radiation Worker II, monthly exchange

Dosimetry is only issued to workers who meet the following criteria:

- Have completed a baseline whole-body count or bioassay (or both)
- Are included on the periodic whole-body count or bioassay roster (or both)
- Have completed radiation worker training
- Have completed General Employee Training
- Have no radiological restrictions
- Have their radiation dose history on file or on request by the Radiation Protection department

Workers who are badged monthly are also issued direct-reading dosimeters, which along with the TLDs, are worn continuously by workers in Radiation Control Areas. In some cases, electronic dosimeters are used in addition to the TLDs and direct-reading dosimeters (Hoffman 1997). These

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 77 of 152
------------------------------	-----------------	----------------------------	----------------

are used to supplement external dose information obtained from TLDs, and do not serve as a primary dosimeter.

Visitor badges are issued to those having a "valid need" to enter areas requiring dosimetry.

Supplemental dosimetry, if used, is placed at the location of the highest anticipated dose rate to monitor localized exposures (to extremities, for instance).

During construction of the RHWF, all construction workers were trained as Radiation Workers and were issued a TLD while they were in the RHWF Radiological Buffer Area (RBA). Individuals who were expected to spend less than 80 hr/quarter in the RBA were classified as visitors and were not Radiation Worker trained or issued dosimetry. Some means of tracking the total time spent in the RHWF RBA was supposed to be in place and if a visitor reached the 80-hour limit, they could be subject to Radiation Worker training and issued dosimetry (Crotzer 2000, p. 2).

6.2.2 <u>Personnel Exposure Control</u>

Personnel exposures at West Valley during plant operation were controlled relative to the legal maximums for <u>quarterly</u> exposure at that time:

- 3 rem to the whole body (or 5 rem/yr for "younger employees" (see Keely 1968a)
- 7.5 rem to the skin of the whole body
- 18.75 rem to the extremities

Personnel exposures were such that NFS had to utilize a substantial number of contract employees each quarter once the regular employees reached their limits. NFS used upwards of 1,000 contract employees per year, relative to a permanent staff of under 200. Controlling exposures to lower limits would have required substantial increases in personnel (e.g., see Wenstrand 1971e).

In response to a number of extremity overexposures, NFS revised its SWPs in the third quarter of 1967 to include limits for skin and extremity exposures (Lewis 1967b). Their Health and Safety Manual had been amended to include daily limits for skin and extremity exposure in April of that year (Keely 1967b). The individuals receiving extremity overexposures were maintenance or mechanical operators performing decontamination and maintenance on mechanical processing equipment such as manipulators. Lead gloves therefore procured for such tasks. Keely and Wenstrand (1971) says 20,000-V lineman's gloves were also used, though he does not indicate when this practice began. He also says if the gloves were too cumbersome to wear, workers changed their cotton gloves "every few minutes" to reduce the build up of contamination.

The individuals affected by the 1967 extremity overexposures were "removed from work which could give any further significant extremity dosage," so it does not appear that they were removed from radiation work altogether (Lewis 1967b).

In a February 24, 1971, letter to its headquarters, NFS points out the majority of over-exposures at West Valley over its operating history were from chronic exposure and not acute events. In September 1969 they made efforts to reduce the rate of accumulated dose, but over-exposures still occurred. The practice was modified in the first quarter of 1970 by putting workers on dose rate restrictions once they exceeded 80% of their quarterly limit (Duckworth 1971). Thus, individuals were placed on dose rate restriction when they reached 2,400 mrem whole body, 6,000 mrem skin, or 16,000 mrem extremity dose in an effort to "help control chronic over-exposures" (Wenstrand 1970). Exposure control practices were changed again in the second quarter of 1970 to where workers were

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 78 of 152
------------------------------	-----------------	----------------------------	----------------

placed on daily dose restrictions once they exceeded 80% of their limit and total radiation work restriction when they reached 90% (Duckworth 1971).

As of May 1971, NFS controlled dose to contract employees to the following quarterly limits (Metzler 1971):

- 2 rem to the whole body
- 4 rem to the skin of the whole body
- 13 rem to the extremities

NFS began a practice of summing and recording dose results from pocket chambers and extremity TLDs for contract employees for comparison with these limits. The impetus was frequent occurrences of these individuals being called in for work whom were already on dose restrictions (Metzler 1971).

NFS points out the lag time between collection and processing of film badges contributed to personnel exposure problems. They began sending their film badges to the processor by Special Delivery, which reduced the lag time to about 2 weeks (Duckworth 1971). In 1970, NFS was encouraged by its insurance carrier to find ways to reduce the delay time for the processing of film badges and to consider doing its own processing. Accumulated dose (for the purpose of determining individuals to place on work restriction) was based on film badge data when available and "dosimeter" (i.e., pocket chamber) data if not (Keely 1970a). A May 1972 insurance inspection report (Johnson & Higgins 1972, p. 16) also mentions the long delay times for processing personnel dosimetry, saying the turnaround is "about three weeks from mailing to receipt of results." This is said to be a decrease from what delays used to be (Johnson & Higgins 1972, p. 16).

6.2.3 Evaluation and Recording of Personnel Exposures

6.2.3.1 Dose Recording Practices

NFS determined skin and whole-body dose from film badges, and extremity dose from TLD finger dosimeters (NFS 1974b, p. 2.3). The film badge was the dosimeter of record. If the film had "an obviously incorrect exposure," supplementary data, such as dosimeter readings and surveys were used to determine the exposure (NFS 1974b, p. 4.0).

Per NFS, "All persons entering radiation areas or restricted areas identified in 10 CFR 20.202 are required to wear two indirect reading dosimeters with a range of 200 mR." These dosimeters were read at the end of each shift and the reading recorded. These readings were totaled each week and transferred to the individual's exposure card. The exposure card contained all of the information required on an AEC Form 5 (NFS 1976). Self-reading dosimeter results were supposed to have been recorded on the SWP if they exceeded 100 mR. A weekly dosimeter log was also kept (O'Reilly 1975, p. 4 of inspection report). The indirect reading dosimeter totals provided a temporary value for whole-body exposure until film badge results were received (NFS 1976).

Extremity TLDs were issued to those receiving exposures where skin dose was anticipated to exceed the whole-body dose. The extremity TLDs issued were to be returned to the Hot Lobby for processing upon completion of the work. Depending on what time work was completed, sometimes the TLDs were not read until the following morning (Duckworth 1973, p. 1).

For dose to the skin of the whole body, the TLD results were used as a temporary measure until the film badge readings came back. For dose to the extremities, the TLD reading was the dose of record (NFS 1976). At one point NFS added a TLD disk to the film badge that could be read locally in an

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 79 of 152
------------------------------	-----------------	----------------------------	----------------

effort to predict the film badge reading. They say the TLD disk and the film badge generally agreed to within 30%.

Whole-body exposure data was received from the film badge supplier and recorded on individual's exposure card. Exposure data from pencil dosimeter and TLD readouts was also compiled daily and recorded on an individual's card. Lifetime totals were summarized quarterly (Duckworth 1972).

Keely (1970b) suggests there were discrepancies between the "dosimeters" (pocket meters) and the film badges. "Overexposures" indicated by the pocket meters were not treated as true dose until the film badge result was available.

Review of "Finger Dosimeter Records" forms from April 1972 showed entries under "Name" also included an indication of whether the dose was "skin" or "ext" (i.e., extremity) (NFS 1972b).

The NFS records include several requests from the site asking the dosimetry vendors to change personnel dose results based on "dosimeter" (pocket chamber) readings (for examples, see Keely 1968g,h). Both ask for personnel monitoring results to be changed based on "dosimeter" readings. The latter asks that a reported dose of 2,290 mR be changed to 165 mR. It is not known if the dosimetry vendors actually made these changes, and if so, where they would appear.

The requests from NFS for changes to film badge readings did not specify what prompted them. None of the requests seen had the corresponding dosimetry reports attached. An April 4, 1967, letter from Runion to the AEC says most rejections of film badges are due to overheating, accidental exposure to light, water damage, uneven exposure, or exposure through the back of the badge. It states if a badge is rejected for any reason, the person's pocket dosimeter readings are summed and added to his previous film badge dose (Runion 1967b, p. 2).

NFS made distinctions between NFS employees and non-NFS (e.g., Benz Construction workers) in its radiation exposure summaries. In the 1970 to 1971 era, Benz workers outnumbered NFS employees by approximately 5:1. NFS often gave detailed breakdowns of radiation exposure associated with specific job functions or tasks, but only for NFS employees. Data for Benz workers was all lumped together. They also appear to have distinguished between contract employees who worked at the reprocessing plant and those whom worked at the SDA (Nelson 1973b, p. 8 of enclosure). This reference states, "Contractor employee exposures are monitored by H&S [health and safety] by daily review of their dosimeter records."

Much of the external dose information in the NOCTS claim files for individuals whom worked at West Valley under NFS consists of a single sentence asserting total whole body, skin, and extremity dose for their period of employment. No individual monitoring data are provided. Dose reconstructors will therefore need to fractionate the reported total dose over the employment period a number of different ways so that latency is accounted for in the POC calculation in a manner most favorable to the claimant. This can be done, for example, by loading the reported total dose over the first few years of employment, the last few years, and evenly over the employment period and taking the result that yields the largest POC. However, in doing so the dose assigned for any individual year should not exceed the corresponding legal maximum. Annual legal maximums for the operations era are as follows (e.g., see Wenstrand 1971b).

- 12 rem whole body
- 30 rem skin
- 75 rem extremity

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 80 of 152
------------------------------	-----------------	----------------------------	----------------

6.2.3.2 Nuclear-Chicago Film Badge Exposure Reports

Nuclear-Chicago reported the "current reading" for an individual under either the heading "X-G-N" or "BETA," with X-G-N referring to X-ray, gamma and neutron. X-ray plus gamma results and neutron results (if any) were reported separately under the "X-G-N" column, with the X-ray plus gamma result listed above the neutron value. Results in this column were in rem, with a vertical dashed line representing the decimal point. So for example, an entry of "123" to the right of the dashed line would be read as 123 mrem. In contrast, beta dose was reported to the nearest 10 mrem, so only two digits appeared to the right to the right of the vertical "decimal point" line. Hence, an entry of "25" to the right of the line would be read as 250 mrem.

Nuclear-Chicago used an 8000 series number to identify neutron films under the "Film Number" column. Later Nuclear-Chicago exposure reports gave X-ray plus gamma and neutron results in separate columns.

Later Nuclear-Chicago exposure reports indicated a badge type in the second column. These were as shown in Table 6-1.

Type code	Туре
1	X-ray, beta, gamma clip-on
2	X-ray, beta, gamma wrist
3	X-ray, beta, gamma ring
5	Extended range X-ray, beta, gamma
14	X-ray, beta, gamma, and neutron clip-on
24	X-ray, beta, gamma, and neutron wrist

Table 6-1.	Nuclear-Chicago	film badge	type codes.

Frequency codes identified the exchange frequency. It appears a code of "1" indicated a monthly exchange and "5" indicated quarterly.

On the older Nuclear-Chicago reports, values in columns labeled "H" indicated the total number of readings used to arrive at a given total. So for example, the value should be "3" at the end of a

calendar quarter for a monthly subscriber. The "H" column only accommodated a single character, so the letters O, A, B, and C were used for 10, 11, 12, and 13, respectively.

Entries in Column "D" indicated cases where badges could not be read at all or evaluated accurately. The codes shown in Table 6-2 were used.

Discrepancy codes used in Column "D"	
of Nuclear-Chicago Exposure Reports	Explanation
1	The film was not returned within 90 days. Evaluation was not
	possible due to aging of the sensitive film.
2	Film was apparently exposed to light. No reading was possible.
3	The film was blacked out, indicating either exposure to light or
	chemical fumes, or an exposure in excess of 600 R.
4	The film was soaked in water, over-heated, or otherwise
	mishandled in such a way that reading was not possible.
5	The film was exposed unevenly or partially obliterated, meaning
	the reading will reflect less information than usual, with a
	corresponding loss of accuracy.

Table 6-2. Discrepancy codes and explanations.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 81 of 152
------------------------------	-----------------	----------------------------	----------------

Discrepancy codes used in Column "D" of Nuclear-Chicago Exposure Reports	Explanation
6	Exposure occurred through the back of the badge, meaning a loss of accuracy due to self-shielding.

Later Nuclear-Chicago reports include a column for skin dose. This was the sum of the X-ray plus gamma dose and any beta dose.

6.2.3.3 Landauer Radiation Dosimetry Reports

The personnel exposure data in the Landauer reports are largely self-explanatory. Their reporting levels (ca. 1971) were 10 mrem for X-or gamma rays, 40 mrem for hard beta, 20 mrem for fast neutron, and 10 mrem for thermal neutron. Column 5 indicated the dosimeter type and Column 6 the exposure type.

The dosimeter type codes typically seen for West Valley workers are "J" and "N," corresponding to "Regular beta-gamma body film badge" and "Fast neutron-only body film badge." See Attachment B for other dosimeter type codes that may be encountered. Table 6-3 lists the exposure type codes.

Table 0-3. Lanuauer exposure type code		
Code	Exposure type	
1	Total body	
2	Skin dose	
3	Right finger	
4	Left finger	
5	Right wrist	
6	Left wrist	
7	Other extremity	
8	Other total body	

Table 6-3.	Landauer	exposure	type codes.

Codes listed in column 4 for discrepancies or other notes are too numerous to include here. See Attachment B.

6.3 SITE DOSIMETRY TECHNOLOGY

6.3.1 Whole-Body Monitoring

Whole-body monitoring was performed using film badges from the onset of personnel monitoring through August 1982. At least two film badge vendors were used: Nuclear-Chicago and Landauer. In October 1970 NFS discontinued film badge service with Nuclear-Chicago and ordered film badges from Eberline Instrument Corporation for a comparison evaluation with the Landauer badges (Keely 1970c). However, it is not known if another vendor was actually used.

The changeover from film badges to a Harshaw TLD system began in August 1982 (Daugherty 1986, p. 3). The Harshaw TLD system was replaced in September 1986 with a Panasonic TLD system, which is still in use. The external dosimetry program is presently accredited by the DOE Laboratory Accreditation Program (Hoffman 1997).

6.3.2 **Extremity Monitoring**

NFS used TLD chips for extremity monitoring, which were read on site. These "finger dosimeters" went into service in March 1967 "on personnel exposed to high extremity dose rates" (Keely 1967a, p.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 82 of 152
------------------------------	-----------------	----------------------------	----------------

1). A 1968 memorandum describes using TLD disks in black pouches attached with adhesive tape for extremity monitoring. It states they were good for single use in high exposure rate areas, but did not work well for continuous wearing by analytical laboratory workers (Keely 1968i). Wenstrand (1968d) says they are "using LiF TLD disks to monitor extremity exposure to laboratory analysts. The analyst is assigned two dosimeters and tapes at the beginning of each shift week and wears the dosimeters during the entire week. During the week, the analyst must change tapes on the dosimeters several times as the adhesive wears off." NFS is requesting a "plastic ring dosimeter holder" to replace the "tapes."

A statistical evaluation was made of the extremity exposure of 76 work teams in the MSM Repair Shop during the fourth quarter of 1971. The 76 pairs of extremity dosimeters showed an average difference of 88% with a maximum of 275%. The minimum detectable dose for the extremity TLD was said to be 10 mrem (Duckworth 1973, p. 3).

6.4 WORKPLACE RADIATION FIELDS

6.4.1 Beta and Photon

The West Valley reprocessing plant used the same solvent extraction process (PUREX) used at AEC plutonium production facilities, notably, the Hanford site. The workplace photon energy spectra, therefore, would likewise have been dominated by high-energy photons from mixed fission and activation products, with a low-energy component representing down-scatter. This is shown in the photon energy distribution information provided in the Hanford site profile for the separation plants. The photon energy selections established for the separations plants are 75% >250 keV and 25% 30 to 250 keV (ORAUT 2006c). The same selections should be used for photon exposures in the reprocessing plant at West Valley. Likewise, beta (electron) exposures should be treated as 100% > 15 keV. These selections should be applied for all facilities and areas over the entire time period of concern (1965 – present).

Workers in the waste burial areas received exposures from handling and emplacement of waste containers and items. These included waste materials and items from commercial entities (in the case of the SDA) and HLW from the reprocessing plant. LLW from the reprocessing plant were also disposed of at the SDA. Users should assume the energy groups for photons and electrons as given above for the processing plant [17].

6.4.2 <u>Neutron</u>

Neutrons could have been encountered in the FRS (cask handling operations), the Product Packaging and Handling (PPH), and the Product Packaging and Shipping (PPS) areas from spontaneous fission sources and (α , n) reactions. Given a lack of information on workplace neuron spectra at West Valley, users should assume 100% of any neutron dose was from the 0.1 to 2.0 MeV energy group [18].

Any positive neutron dose reported for West Valley workers based on personnel dosimetry or survey data should be doubled to reflect ICRP Publication 60 radiation weighting factors (ICRP 1991). This would apply to any missed neutron dose assigned as well.

6.4.3 <u>Summary</u>

Table 6-4 summarizes the Interactive RadioEpidemiological Program (IREP) energy group selections that should be made for West Valley cases.

Area	Radiation type	Energy selection	Fraction
All areas	Photon	30–250 keV	25%
		>250 keV	75%
All areas	Electron	>15 keV	100%
FRS, PPH, PPS	Neutron	0.1–2.0 MeV	100%

Table 6-4. S	Selection of radiation energies for	West Valley facilities.
--------------	-------------------------------------	-------------------------

6.5 MISSED DOSE

Exchange frequencies, minimum detectable levels (MDLs) and maximum annual missed dose are given in the tables below for the personnel dosimetry badges used at West Valley. Table 6-5 provides data for deep dose. Table 6-6 is for nonpenetrating radiation. The MDLs for deep and nonpenetrating dose for the commercial film badge reflect the guidance provided in (ORAUT 2006d) and (ORAUT 2005c), respectively. The MDLs for the Harshaw and Panasonic TLDs are given in DOE-era dosimetry reports in NOCTS claim files.

An asserted MDL for the commercial film badges used at West Valley has not been identified. Landauer's reporting limit for its film badge was 40 mrem for hard beta.

NFS asserted the MDL for its extremity TLD chips was 10 mrem. It is assumed this value is for penetrating radiation. Slawson (1999) reports the MDL for the Landauer Type U extremity dosimeter ranges from 5.1 to 5.9 mrem and averages 5.5 mrem. Claim files in NOCTS give a MDL for the

Table 6-5.	Exchange frequencies,	MDLs,	and maximum	annual	missed of	deep dose	for personnel
dosimeters	6.						

		MDL	Exchange	Maximum annual
Period	Dosimeter	(rem)	frequency	missed dose (rem)
Until 1982	Commercial film badge	0.040	Weekly (n = 52)	1.040
			Monthly $(n = 12)$	0.240
1982–August 1986	Harshaw TLD	0.015	Monthly $(n = 12)$	0.090
			Quarterly $(n = 4)$	0.030
September 1986–present	Panasonic TLD	0.010	Monthly $(n = 12)$	0.060
			Quarterly $(n = 4)$	0.020

Table 6-6. Exchange frequencies, MDLs, and maximum annual missed nonpenetrating dose for personnel dosimeters.

		MDL	Exchange	Maximum annual
Period	Dosimeter	(rem)	frequency	missed dose (rem)
Until August 1982	Commercial film badge	0.050	Weekly $(n = 52)$	1.300
			Monthly $(n = 12)$	0.300
August 1982–August 1986	Harshaw TLD	0.030	Monthly $(n = 12)$	0.180
			Quarterly $(n = 4)$	0.060
September 1986–present	Panasonic TLD	0.030	Monthly $(n = 12)$	0.180
			Quarterly $(n = 4)$	0.060

Landauer Type U finger ring of 30 mrem/exchange. It is assumed the difference reflects that between penetrating and nonpenetrating radiation. The extremity dosimeters were used on an ad hoc basis, so no annual missed dose can be asserted.

Practices for assigning personnel neutron dosimetry at West Valley during operations have not been identified. If necessary, users should assume a neutron MDL of 80 mrem, consistent with that asserted for neutron film dosimeters in previous site profiles (e.g., Hanford). Any neutron missed

dose assigned using this MDL should be doubled to account for ICRP Publication 60 radiation weighting factors (ICRP 1991).

6.6 UNCERTAINTY

Film badges normally over-respond in the workplace except for where plutonium or americium are the primary contributors to external dose (ORAUT 2006d). Dose contributions from low-energy photons are not believed to ever have been prevalent at West Valley given the predominance of photon exposures from the ventilation and acid recovery systems. Use of recorded film badge dose for photon exposure is therefore believed to be favorable to the claimant.

Specific information pertaining to the uncertainty associated with recorded personnel dose at West Valley has not been identified. Uncertainties to assign for positive recorded dose are given in Table 6-7. These have been reproduced from information provided in the external dosimetry technical basis documents for the Y-12 and X-10 sites. Additional discussion of the uncertainties in film badge data may be found in (Morgan 1961).

Table 0-7. Officertainties for positive recorded dose at west valley.				
Dosimeter	Period of use	Photon	Beta	Neutron
Commercial film badge	1965–1982	±30%	±30%	±50%
Commercial TLD	1982-present	±15%	±15%	±15%

Table 6-7. Uncertainties for positive recorded dose at West Valley.

7.0 ATTRIBUTIONS AND ANNOTATIONS

Where appropriate in the preceding text, bracketed callouts have been inserted to indicate information, conclusions, and recommendations to assist in the process of worker dose reconstruction. These callouts are listed in this section with information that identifies the source and justification for each item. Conventional references are provided in the next section that link data, quotations, and other information to documents available for review on the Oak Ridge Associated Universities (ORAU) Team servers.

This site profile was authored by Robert E. Burns, Jr., Certified Health Physicist (CHP). Many of the following attributions, therefore, represent conclusions and impressions drawn from detailed review of records from when the West Valley site was operating.

[1] Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.

Elevated exposure rates existed throughout the process building and exterior to it during the operations era. Review of operating records showed numerous instances of removable contamination being spread throughout multiple areas of the process building. Contamination incidents sometimes would not be recognized until it reached radiological buffer areas at personnel ingress/egress points.

[2] Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.

This is apparent through review of plant records and AEC inspection reports. The AEC often remarked about the radiation protection program being implemented vis-a-vis legal maximums.

- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 Elevated exposure rates from acid recovery system components and contamination from major spills affected all areas of the plant. Plant records indicate persons not normally involved in radiation work were sometimes brought in to support tasks in the process building when personnel exposure limits became a constraint. Table 2-7 shows acid recovery supervisors collectively averaged 6 person-rem/yr. between 1970 and 1971. The work area for these individuals was "offices."
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The NDA is within the DOE fence line, and the WVDP built a Liquid Pre-Treatment System on the northeast corner of the NDA ca. 2004. The purpose of the system was to remove organics (solvent) from groundwater around the NDA.
- [5] Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The information on the contact dose rate from the unshielded glass logs and the impact of elevated exposure rates on release surveys is from discussions the author had with site radiation protection manager during a site visit in June 2006.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 These three streams represent the three principal processes when the plant was operating: mechanical and chemical preparation of the fuel, separation of the uranium and plutonium products, and handling of the associated chemical wastes.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The fuels processed at West Valley consisted of both metal and oxide forms.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The plutonium product from the PUREX process is in an aqueous nitrate form. Plutonium contamination will undergo oxidation as it ages, reducing its solubility.
- [9] Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The PUREX process separates the americium present in the feed stream from the plutonium product stream. ²⁴¹Am slowly grows back in over time from decay of ²⁴¹Pu.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The fuels processed at West Valley consisted of both metal and oxide forms.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The nuclides listed represent those observed in *in vivo* counting data for operations era workers.

- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 This is apparent from review of NFS documents discussing atmospheric releases and correspondence between NFS and the AEC.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 No references have been identified suggesting NFS ever changed its site access requirements for personnel monitoring for external exposure.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 170 mrem/yr was the administrative limit for annual dose to unmonitored workers as of 1986 (Roberts 1986). To be favorable to the claimant, it is being assumed unmonitored individuals

(Roberts 1986). To be favorable to the claimant, it is being assumed unmonitored individuals received an annual dose equal to this limit for the period 1982 – 1993. Likewise, for 1994 forward an annual dose equal to the 100 mrem/yr limit of 10 CFR 835 is being assumed.

- [15] Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 (Wenstrand 1968c) is a letter from NFS to Eberline requesting information on their ability to support a fecal monitoring program. Plant records show a routine fecal analysis program was in place as of 1970.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 Communication between Bob Burns and Paul Szalinski, CHP, Integrated Environmental Management, on March 15, 2007.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 The photon energy spectra at the waste burial sites are not expected to differ from those in the processing plant in a way that would not be favorable to the claimant.
- Burns, Jr. Robert E., CHP. Shonka Research Associates. Senior Health Physicist. March 2007.
 This neutron energy group is representative of fission neutron spectra and is also most favorable to the claimant.

REFERENCES

ASDA (New York State Atomic and Space Development Authority) and NFS (Nuclear Fuel Services), 1971, Plutonium Storage Agreement between New York State Atomic and Space Development Authority and Nuclear Fuel Services, May 3. [SRDB Ref ID: 28316, p. 205]

Author unknown, ca. 1967, "Explanation of Exposure Report Data." [SRDB Ref ID: 24431, p. 222]

Author unknown, ca. 1968, "Facilities Description." [SRDB Ref ID: 29117, p. 237]

- Author unknown, 1968, "Radiation-Contamination Status Report, May 1968," memorandum to R. B. Keely, West Valley, New York, June 3. [SRDB Ref ID: 24422, p. 178]
- Author unknown, 1969, "Head End Vent., P.S.A.R., Third revision pre. Subm.," January 15. [SRDB Ref ID: 29127]
- Author unknown, 1974, results of radiation counts. [SRDB Ref ID: 24404, p. 1780]
- Author unknown, ca. 1974, "Site Boundary Concentrations of α and β Releases from FRP Stack Annual β Sector Width Averaged."
- Bailey, W. J., 1990, West Valley Facility Spent Fuel Handling, Storage, and Shipping Experience, Pacific Northwest National Laboratory, Richland, Washington, November. [SRDB Ref ID: 30229]
- Birchler, J. E., 1970, "Plant Cleanout Between Processing of a Thorium Fuel and a Low Enriched Uranium Fuel," NFS-PS-138, memorandum to J. R. Clark, West Valley, New York, December 16. [SRDB Ref ID: 26331, p. 33]
- Clark, J. R., 1968a, "USAEC Compliance Inspection," memorandum to Dr. E. D. North, Nuclear Fuel Services, July 24. [SRDB Ref ID: 28343, p. 281]
- Clark, J. R., 1968b, "Compliance with AEC Letter of December 28, 1968," memorandum to Dr. E. D. North, Nuclear Fuel Services, April 8. [SRDB Ref ID: 24455, p. 87]
- Clark, J. R., 1968c, untitled memorandum to E. D. North, January 26.
- Clark, J. R., 1968d, "Compliance Status," memorandum to Dr. E. D. North, Nuclear Fuel Services, May 21. [SRDB Ref ID: 28343, p. 317]
- Clark, J. R., 1968e, "Criteria for Removal of Dog Filters," memorandum to Distribution, April 8. [SRDB Ref ID: 28343, p. 328]
- Clark, J. R., 1979, untitled memorandum to C. B. Woodhall, November 5.
- Crotzer, M. E., 2000, "Thermoluminescent Dosimeter (TLD) Badge Requirements During Remote Handled Waste Facility Construction," memorandum to D. K. Pletz, IO:00:0036, West Valley Nuclear Services Company, West Valley, New York, July 6. [SRDB Ref ID: 25642]
- Daugherty, H. F., 1986, "Handling and Disposition of Radioactively Contaminated Soil," memorandum to J. L. Knabenschuh, FA:86:0097, West Valley, New York, August 28. [SRDB Ref ID: 25992]

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 88 of 152

- DOE (U.S. Department of Energy), 1999, Plutonium and Uranium Recovery from Spent Fuel Reprocessing by Nuclear Fuel Services at West Valley, New York from 1966 to 1972, Revised, Office of Defense Programs, Washington, D.C., November. [SRDB Ref ID: 6251, p. 25]
- DOE (U.S. Department of Energy), 2006, Ohio Field Office Web site.
- Duckworth, J. P., 1970, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, West Valley, New York, April 28. [SRDB Ref ID: 24455, p. 126]
- Duckworth, J. P., 1971, "Radiation Exposure at West Valley Plant," memorandum to E. R. Oppel, West Valley, New York, February 24. [SRDB Ref ID: 24437, p. 1377]
- Duckworth, J. P., 1972, "Proposed 20.408 Compliance Procedure," memorandum to E. J. Heerwagen, Nuclear Fuel Services, Rockville, Maryland, September 7. [SRDB Ref ID: 24437, p. 1550]
- Duckworth, J. P., 1973, untitled letter to J. P. O'Reilly (Directorate of Regulatory Operations, Region 1, U.S. Atomic Energy Commission), Nuclear Fuel Services, West Valley, New York, January 10. [SRDB Ref ID: 24455, p. 307]
- Duckworth, J. P., 1976, "Pumpout Data of Waste Burial Trenches," memorandum to W. A. Oldham, October 20. [SRDB Ref ID: 28330, p. 114]
- Duckworth, J. P., 1978a, "Estimate Input Curie Content in the Commercial Burial Area," 9-78-060, memorandum to Distribution, West Valley, New York, June 19. [SRDB Ref ID: 28330, p. 69]
- Duckworth, J. P., 1978b, "NFS Waste Burial History," 9-78-029, memorandum to W. A. Oldham, West Valley, New York, March 27. [SRDB Ref ID: 28330, p. 71]
- Duckworth, J. P., 1980, untitled (letter report to Director, Office of Nuclear Material Safety and Safeguards), 9-80-20, Nuclear Fuel Services, West Valley, New York, April 28. [SRDB Ref ID: 26312, p. 609]
- EPA (Environmental Protection Agency), 1972, *The Observation of Airborne Tritium as a Source and Environmental Waste Discharge from a Nuclear Fuel Reprocessing Plant*, Office of Radiation Programs, Winchester, MA, May.
- G. [author's initial], 1974, "FRS Air Samples week ending 5/15/74." [SRDB Ref ID: 24404, p. 1765]
- Golden, M. P., D. E., Frank, and E. R. Prina, 1982, "NFS, WVNY, Summary of Decontamination Information," memorandum to W. R. Jacoby, Westinghouse, January 14. [SRDB Ref ID: 25980] Section 2.4
- Greco, S. R., 1978, "Special Nuclear and Source Material in Commercial Burial Trenches," 9-78-061, memorandum to J. P. Duckworth, West Valley, New York, June 20. [SRDB Ref ID: 28330, p. 67]
- Heacker, H. V., 1971, "PPC Air Circulation and Filtration," memorandum to C. Alday, West Valley, New York, November 11. [SRDB Ref ID: 24437, p. 1108]

- Heacker, H. V., 1972, "Personnel Accountability and Dosimetry," memorandum to B. E. Knight, West Valley, New York, January 21. [SRDB Ref ID: 24404, p. 26]
- Helgeson, G. L., 1966, untitled letter to R. B. Keely (Nuclear Fuel Services), Helgeson Nuclear Services, Pleasanton, California, December 8. [SRDB Ref ID 24404, p. 1880]
- HNS (Helgeson Nuclear Services), 1967, *Report of Whole Body Counting for Nuclear Fuel Services, Inc.*, Pleasanton, California, April 27. [SRDB Ref ID 24404, p. 1840]
- HNS (Helgeson Nuclear Services), 1968, *Report of Whole Body Counting for Nuclear Fuel Services, Inc.*, Pleasanton, California, May 3. [SRDB Ref ID 24404, p. 1930]
- HNS (Helgeson Nuclear Services), 1969a, *Report of In Vivo Counting for Nuclear Fuel Services, Inc.*, Pleasanton, California, June 6. [SRDB Ref ID 24404, p. 2020]
- HNS (Helgeson Nuclear Services), 1969b, "Announcement of New Services," press release, Pleasanton, California, January 1. [SRDB Ref ID 24404, p. 2049]
- HNS (Helgeson Nuclear Services), 1971, *Report of In Vivo Counting for Nuclear Fuel Services, Inc.*, Pleasanton, California, September 16. [SRDB Ref ID 24404, p. 2020]
- HNS (Helgeson Nuclear Services), 1972, Report of In Vivo Counting for Nuclear Fuel Services, Inc., Pleasanton, California, October. [SRDB Ref ID 24404, p. 2136]
- Hoffman, R. L., 1997, Radiation Safety at the West Valley Demonstration Project, DOE/NE/44139-75, West Valley Nuclear Services Company, West Valley, New York, May 6. [SRDB Ref ID: 30272]
- ICRP (International Commission on Radiological Protection), 1991, 1990 Recommendations of the International Commission on Radiological Protection, Publication 60, Pergamon Press, Oxford, England.
- ICRP (International Commission on Radiological Protection), 1995, *Dose Coefficients for Intakes of Radionuclides by Workers*, Publication 68, Pergamon Press, Oxford, England.
- ICRP (International Commission on Radiological Protection), 1996, *Age-Dependent Doses to the Members of the Public from Intake of Radionuclides*, Publication 72, Pergamon Press, Oxford, England.
- Jablonski, J. F., A. Al-Daouk, and H. Moore, 2003, "Progress on Fuel Receiving and Storage Decontamination Work at the West Valley Demonstration Project," *Waste Management 2003 Symposium, February 23-27, 2003, Tucson, AZ.* [SRDB Ref ID: 30291]

Jaeger, P., ca. 1969, untitled memorandum to R. B. K. [initials]. [SRDB Ref ID: 24404, p. 1744]

- Jaroszeski, R. A., 1972, "Identification of Fission Products in FRS Pool Water," memorandum to J. M. Jump, NFS-AL-143, Nuclear Fuel Services, West Valley, New York, May 11. [SRDB Ref ID: 24437, p. 2021]
- Johnson & Higgins, 1972, Nuclear Loss Control Evaluation, Nuclear Fuel Services, Inc., Fuel Reprocessing Plant, West Valley, New York. [SRDB Ref ID: 24404, p. 1307]

- Johnson & Higgins, 1975, Nuclear Insurance Survey, Nuclear Fuel Services, Inc., Fuel Reprocessing Plant, West Valley, New York. [SRDB Ref ID: 24404, p. 1294]
- Johnson, P., 1991, Development Of Derived Investigation Levels For Use In Internal Dosimetry At The West Valley Demonstration Project, University of Pittsburgh, Pittsburgh, Pennsylvania. [SRDB Ref ID: 30275]
- Keely, R. B., 1966, "Radiation-Contamination Status Report, September 1966," memorandum to W. H. Lewis, West Valley, New York, October 12. [SRDB Ref ID: 24419, p. 169]
- Keely, R. B., 1967a, "Radiation-Contamination Status Report, March 1967," memorandum to R. Wischow, West Valley, New York, April 7. [SRDB Ref ID: 24419, p. 124]
- Keely, R. B., 1967b, "Radiation-Contamination Status Report, April 1967," memorandum to R. P. Wischow, West Valley, New York, May 3. [SRDB Ref ID: 24419, p. 108]
- Keely, R. B., 1967c, "Radiation-Contamination Status Report, February 1967," memorandum to W. H. Lewis, West Valley, New York, April 7. [SRDB Ref ID: 24419, p. 134]
- Keely, R. B., 1967d, "Radiation-Contamination Status Report, January 1967," memorandum to W. H. Lewis, West Valley, New York, February 6. [SRDB Ref ID: 24419, p. 142]
- Keely, R. B., 1967e, "Radiation-Contamination Status Report, December 1966," memorandum to W. H. Lewis, West Valley, New York, January 6. [SRDB Ref ID: 24419, p. 151]
- Keely, R. B., 1967f, "Radiation-Contamination Status Report, June 1967," memorandum to R. P. Wischow, West Valley, New York, July 6. [SRDB Ref ID: 24419, p. 80]
- Keely, R. B., 1968a, "Radiation-Contamination Status Report, June 1968," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, July 1. [SRDB Ref ID: 24422, p. 169]
- Keely, R. B., 1968b, "Radiation-Contamination Status Report, August 1968," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, September 2. [SRDB Ref ID: 24422, p. 166]
- Keely, R. B., 1968c, "Radiation-Contamination Status Report, September 1968," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, October 1. [SRDB Ref ID: 24422, p. 165]
- Keely, R. B., 1968d, "Radiation-Contamination Status Report, October 1968," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, November 5. [SRDB Ref ID: 24422, p. 164]
- Keely, R. B., 1968e, "Radiation-Contamination Status Report, May 1968," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, June 3. [SRDB Ref ID: 24422, p. 171]
- Keely, R. B., 1968f, "Radiation-Contamination Status Report, November 1968," memorandum to W.
 G. Urbon, Nuclear Fuel Services, West Valley, New York, December 5. [SRDB Ref ID: 24422, p. 163]

- Keely, R. B., 1968g, untitled letter to Mrs. Wilson (R. S. Landauer Jr. & Company), Nuclear Fuel Services, West Valley, New York, August 27. [SRDB Ref ID: 24431, p. 77]
- Keely, R. B., 1968h, untitled letter to Mrs. McDonald (R. S. Landauer Jr. & Company), Nuclear Fuel Services, West Valley, New York, June 26. [SRDB Ref ID: 24431, p. 116]
- Keely, R. B., 1968i, untitled letter to Nuclear Service Laboratories, Nuclear Fuel Services, West Valley, New York, October 8. [SRDB Ref ID: 24431, p. 41]
- Keely, R. B., 1968j, "Health and Safety Department Report for April 1968," memorandum to W. G. Urbon, West Valley, New York, May 1. [SRDB Ref ID: 24422, p. 173]
- Keely, R. B., 1968k, "Radiation Contamination Status Report, July 1968," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, August 2. [SRDB Ref ID: 24422, p. 167]
- Keely, R. B., 1969a, "Radiation Contamination Status Report, December 1968," memorandum to W.
 G. Urbon, Nuclear Fuel Services, West Valley, New York, January 2. [SRDB Ref ID: 24422, p. 162]
- Keely, R. B., 1969b, "Radiation Contamination Status Report, March 1969," memorandum to W. H. Lewis, Nuclear Fuel Services, West Valley, New York, April 2. [SRDB Ref ID: 24422, p. 151]
- Keely, R. B., 1969c, "Radiation Contamination Status Report, May 1969," memorandum to J. P. Duckworth, Nuclear Fuel Services, West Valley, New York, June 3. [SRDB Ref ID: 24422, p. 146]
- Keely, R. B., 1969d, "Radiation Contamination Status Report, June 1969," memorandum to J. P. Duckworth, West Valley, New York, July 7. [SRDB Ref ID: 24422, p. 143]
- Keely, R. B., 1969e, "Radiation-Contamination Status Report, July 1969," memorandum to J. P. Duckworth, West Valley, New York, August 5. [SRDB Ref ID: 24422, p. 140]
- Keely, R. B., 1969f, "Radiation Contamination Status Report, February 1969," memorandum to W.
 G. Urbon, Nuclear Fuel Services, West Valley, New York, February 28. [SRDB Ref ID: 24422, p. 155]
- Keely, R. B., 1969g, "Radiation Contamination Status Report, April 1969," memorandum to W. H. Lewis, Nuclear Fuel Services, West Valley, New York, May 5. [SRDB Ref ID: 24422, p. 149]
- Keely, R. B., 1969h, "Radiation Contamination Status Report, January 1969," memorandum to W. G. Urbon, Nuclear Fuel Services, West Valley, New York, February 3. [SRDB Ref ID: 24422, p. 158]
- Keely, R. B., 1970a, "Safety & Industrial Relations Monthly Report August 1970," memorandum to J. P. Duckworth, West Valley, New York, September 8. [SRDB Ref ID: 24422, p. 102]
- Keely, R. B., 1970b, "Safety and Industrial Relations Monthly Report March 1970," memorandum to J. P. Duckworth, West Valley, New York, April 6. [SRDB Ref ID: 24422, p. 121]

- Keely, R. B., 1970c, "Safety and Industrial Relations Monthly Report October 1970," memorandum to J. P. Duckworth, West Valley, New York, November 6. [SRDB Ref ID: 24422, p. 87]
- Keely, R. B., and T. K. Wenstrand, 1971, "Impact of Fuel Reprocessing on the Health Physics Profession," *Health Physics*, volume 20, pp. 143–151. [SRDB Ref ID: 30270]
- Kelleher, W. J., and E. J. Michael, 1973, Low Level Radioactive Waste Site Burial Inventory for the West Valley Site, Cattaraugus County, N.Y., New York State Department of Environmental Conservation, Bureau of Radiological Pollution Control, Albany, New York, June 20. [SRDB Ref ID: 26321, p. 80]
- Kester, R. T., 1971, "Yearly Report from Bioassay Technician," memorandum to D. P. Wilcox, West Valley, New York, February 22. [SRDB Ref ID: 24437, p. 1378]
- Kubiak, M. S., 1997, WVDP Internal Dosimetry Program Manual and Technical Basis Document, WVDP-070, West Valley Nuclear Services Company, West Valley Demonstration Project, West Valley, New York, July 28. [SRDB Ref ID: 24027]
- Kubiak, M. S., 1998, WVDP Internal Dosimetry Program Manual and Technical Basis Document, WVDP-070, West Valley Nuclear Services Company, West Valley Demonstration Project, West Valley, New York, September 14. [SRDB Ref ID: 24028]
- Laurer, G. R., 1968, untitled letter to R. Keely (Nuclear Fuel Services), New York University Medical Center Institute of Environmental Medicine, New York, New York, August 23.
- Lewis, W. H., 1966a, "Status Report of West Valley Plant for Week Ending December 9, 1966," memorandum to T. C. Runion, December 9. [SRDB Ref ID: 28765, p. 20]
- Lewis, W. H., 1966b, "West Valley Status Report for week ending December 16, 1966," memorandum to T. C. Runion, West Valley, New York, December 19.
- Lewis, W. H., 1967a, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), December 20.
- Lewis, W. H., 1967b, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), September 27. [SRDB Ref ID: 28343, p. 64]
- Lewis, W. H., 1968, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), January 31. [SRDB Ref ID: 28343, p. 376]
- Loud, G. C., 1965a, "Radiation-Contamination Status Report, October, 1965," memorandum to W. H. Lewis, West Valley, New York, November 9. [SRDB Ref ID: 24419, p. 225]
- Loud, G. C., 1965b, "Radiation-Contamination Status Report, September, 1965," memorandum to W. H. Lewis, West Valley, New York, October 4. [SRDB Ref ID: 24419, p. 228]
- Loud, G. C., 1965c, "Radiation-Contamination Status Report, November, 1965," memorandum to W. H. Lewis, West Valley, New York, December 10. [SRDB Ref ID: 24419, p. 223]
- Loud, G. C., 1966a, "Radiation-Contamination Status Report, December, 1965," memorandum to W. H. Lewis, West Valley, New York, January 6. [SRDB Ref ID: 24419, p. 219]

- Loud, G. C., 1966b, "Radiation Contamination Status Report, February, 1966," memorandum to W. H. Lewis, West Valley, New York, March 7. [SRDB Ref ID: 24419, p. 210]
- Loud, G. C., 1966c, "Radiation Contamination Status Report, March, 1966," memorandum to W. H. Lewis, West Valley, New York, April 5. [SRDB Ref ID: 24419, p. 204]
- Loud, G. C., 1966d, "Radiation-Contamination Status Report, May, 1966," memorandum to W. H. Lewis, West Valley, New York, June 13. [SRDB Ref ID: 24419, p. 194]
- Metzler, G. H., 1971, "Limiting Exposure on Benz Personnel," memorandum to Health & Safety Technicians, West Valley, New York, May 25. [SRDB Ref ID: 24437, p. 1289]
- Miller, R. N., 1972a, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, Rockville, Maryland, April 21. [SRDB Ref ID: 24455, p. 217]
- Miller, R. N., 1972b, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, Rockville, Maryland, April 7.
- Monroe, H. L., 1968, untitled letter to W. T. Doran (U.S. Atomic Energy Commission), March 19. [SRDB Ref ID: 24431, p. 193]
- Morgan, K. Z., 1961, "Dosimetry Requirements for Protection from Ionizing Radiations," in *Selected Topics in Radiation Dosimetry*, proceedings of the symposium on selected topics in radiation dosimetry, International Atomic Energy Agency, Vienna, Austria.
- Morrow, P. K., 1972a, "Health and Safety Monthly Report (September)," memorandum to J. P. Duckworth, West Valley, New York, October 5. [SRDB Ref ID: 24422, p. 36]
- Morrow, P. K., 1972c, "Health & Safety Monthly Report," memorandum to J. P. Duckworth, West Valley, New York, August 7. [SRDB Ref ID: 24422, p. 40]
- Morrow, P. K., 1972b, "Health and Safety Monthly Report (October)," memorandum to J. P. Duckworth, West Valley, New York, November 7. [SRDB Ref ID: 24422, p. 35]
- Morrow, P. K., 1972d, "Health and Safety Monthly Report November," memorandum to J. P. Duckworth, West Valley, New York, December 6. [SRDB Ref ID: 24422, p. 34]
- Morrow, P. K., 1972e, "Health & Safety Monthly Report," memorandum to J. P. Duckworth, West Valley, New York, September 12. [SRDB Ref ID: 24422, p. 38]
- Nelson, H. A., 1972, "Johnson & Higgins Survey, West Valley Facilities," letter to J. F. Miller, Rockville, Maryland, August 11. [SRDB Ref ID: 24404, p. 1306]
- Nelson, P. R., 1973a, untitled letter to R. N. Miller (Nuclear Fuel Services), Directorate of Regulatory Operations, Region 1, U.S. Atomic Energy Commission, Newark, New Jersey, February 5. [SRDB Ref ID: 24455, p. 316]
- Nelson, P. R., 1973b, untitled letter to R. N. Miller (Nuclear Fuel Services), Directorate of Regulatory Operations, King of Prussia, Pennsylvania, December 7. [SRDB Ref ID: 24455, p. 446]

- Nelson, P. R., 1976, untitled letter to R. W. Deuster (Nuclear Fuel Services) on Inspection No. 75-09, Docket No. 50-201, U.S. Nuclear Regulatory Commission, Region 1, King of Prussia, Pennsylvania, January 21. [SRDB Ref ID: 24456, p. 182]
- NFS (Nuclear Fuel Services), 1968, Report on the Failure of a Filter in the Main Ventilation System on September 4, 1968, West Valley, New York, September 27.
- NFS (Nuclear Fuel Services), 1969, Plutonium Shipping Record, West Valley, New York, June 3.
- NFS (Nuclear Fuel Services), 1972a, Head End Ventilation System Annual Performance Report, West Valley, New York. [SRDB Ref ID: 29127, p. 309]
- NFS (Nuclear Fuel Services), 1972b, "Finger Dosimeter Records," West Valley, New York. [SRDB Ref ID: 30262]
- NFS (Nuclear Fuel Services), 1973a, *Radiation Area Extended Work Procedure*, ANA-1, Rev. 1, West Valley, New York, January 1. [SRDB Ref ID: 28426, p. 10]
- NFS (Nuclear Fuel Services), 1973b, Environmental Report, NFS' Reprocessing Plant, West Valley, New York, Docket Number 50-201, Rockville, Maryland. [SRDB Ref ID: 29128]
- NFS (Nuclear Fuel Services), 1974a, *Environmental Report, NFS' UF₆ Plant, West Valley, New York,* Docket Number 70 - 071, Rockville, Maryland. [SRDB Ref ID: 28431, p. 2]
- NFS (Nuclear Fuel Services), 1974b, Nuclear Fuel Services Fuel Reprocessing Plant, West Valley, New York, Health and Safety Manual, Rev. 3, West Valley, New York, April 30. [SRDB Ref ID: 28398, p. 23]
- NFS (Nuclear Fuel Services), 1974c, Health and Safety Logbook beginning March 27, 1972, West Valley, New York. [SRDB Ref ID: pending]
- NFS (Nuclear Fuel Services), 1974d, *Monthly Report, Radioactive Waste Burial Study*, West Valley, New York, February 19. [SRDB Ref ID: 26314, p. 35]
- NFS (Nuclear Fuel Services), 1976, "Radiological Protection," Chapter 7, Safety Analysis Report, NFS' Reprocessing Plant, West Valley, New York, Revision 1, Nuclear Fuel Services, Rockville, Maryland, February. [SRDB Ref ID: 27086]
- North, E. D., and J. R. Clark, 1968, A Study of Particulate Release Rate During the Period March 8 10, 1968, Nuclear Fuel Services, West Valley, New York, March 24. [SRDB Ref ID: 30271]
- NYSERDA (New York State Energy Research and Development Authority), 2004, "The Western New York Nuclear Service Center (The West Valley Site)," <u>http://www.nyserda.org/programs/West_Valley/default.asp</u> [SRDB Ref ID: 30288]
- Oldham, W. A., 1977, untitled letter to M. W. Stradley, 1-77-029, Nuclear Fuel Services, West Valley, New York, May 18. [SRDB Ref ID: 24404, p. 1173]
- ORAUT (Oak Ridge Associated Universities Team), 2005a, *Dose Reconstruction from Occupationally Related Diagnostic X-ray Procedures*, ORAUT-OTIB-0006 Rev. 03 PC-1, Oak Ridge, Tennessee, December 21.

Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 95 of 152
------------------------------	-----------------	----------------------------	----------------

- ORAUT (Oak Ridge Associated Universities Team), 2005b, Internal Dose Overestimates for Facilities with Air Sampling Programs, ORAUT-OTIB-0018 Rev. 01, Oak Ridge, Tennessee, August 9.
- ORAUT (Oak Ridge Associated Universities Team), 2005c, Interpretation of Dosimetry Data for Assignment of Shallow Dose, ORAUT-OTIB-0017 Rev. 01, Oak Ridge, Tennessee, October 11.
- ORAUT (Oak Ridge Associated Universities Team), 2006a, *Technical Basis Document for the Oak Ridge National Laboratory – Occupational Medical Dose*, ORAUT-TKBS-0012-3 Rev. 01 PC-1, Oak Ridge, Tennessee, July 21.
- ORAUT (Oak Ridge Associated Universities Team), 2006b, *External Dose Reconstruction*, ORAUT-PROC-0006 Rev. 01, Oak Ridge, Tennessee, June 5.
- ORAUT (Oak Ridge Associated Universities Team), 2006c, *Technical Basis Document for the Hanford Site – Occupational External Dose*, ORAUT-TKBS-0006-6 Rev. 02, Oak Ridge, Tennessee, November 21.
- ORAUT (Oak Ridge Associated Universities Team), 2006d, A Standard Complex-Wide Methodology for Overestimating External Doses Measured with Film Badge Dosimeters, ORAUT-OTIB-0010 Rev. 01, Oak Ridge, Tennessee, June 5.
- ORAUT (Oak Ridge Associated Universities Team), 2007a, *Estimating Doses for Plutonium Strongly Retained in the Lung*, ORAUT-OTIB-0049 Rev. 00, Oak Ridge, Tennessee, February 6.
- ORAUT (Oak Ridge Associated Universities Team), 2007b, *Maximum Internal Dose Estimates for Certain DOE Complex Claims*, ORAUT-OTIB-0002 Rev. 02, Oak Ridge, Tennessee, February 7.
- O'Reilly, J. P., 1975, untitled letter to R. W. Deuster (Nuclear Fuel Services) on Inspection Nos. 50-201/74-10 and 70-959/74-02, U.S. Atomic Energy Commission, Directorate of Regulatory Operations, Region 1, King of Prussia, Pennsylvania, January 15. [SRDB Ref ID: 24456, p. 65]
- Petkus, L. L., Paul, J., Valenti, P. J., Houston, H., and May, J., 2003, "A Complete History of the High-Level Waste Plant at the West Valley Demonstration Project," submission to the Waste Management 2003 Symposium, Tucson, Arizona, February.
- Roberts, R. S., 1986, "Area Radiation Monitoring," memorandum to D. J. Harward, West Valley Demonstration Project, West Valley, New York, April 24.
- Runion, T. C., 1967a, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, Wheaton, Maryland, September 18. [SRDB Ref ID: 24455, p. 28]
- Runion, T. C., 1967b, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, Wheaton, Maryland, April 4. [SRDB Ref ID: 24455, p. 15]

- Runion, T. C., 1968, untitled letter to L. D. Low (U.S. Atomic Energy Commission, Division of Compliance), Nuclear Fuel Services, Wheaton, Maryland, January 13. [SRDB Ref ID: 24455, p. 38]
- Runion, T. C., 1970, "Statement before the Joint Committee on Atomic Energy, Part II, Hearings on the Environmental Effects of Producing Electric Power," Nuclear Fuel Services, Wheaton, Maryland, February 25. [SRDB Ref ID: 30228]
- Slawson, J. W., 1999, WVDP External Dosimetry Technical Basis Document, Program Manual, and Quality Assurance Plan, WVDP-071, Rev. 7, West Valley Nuclear Services Company, West Valley, New York, November 12. [SRDB Ref ID: 24213]
- TKW [author's initials], 1970, "Input for Dust Flush TOP," memorandum to J. Birchley, Nuclear Fuel Services, West Valley, New York, July 8. [SRDB Ref ID: 24437, p. 1042]
- Urbon, W. G., 1968a, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, West Valley, New York, September 9. [SRDB Ref ID: 28343, p. 272]
- Urbon, W. G., 1968b, untitled letter to L. D. Low (Director, Division of Compliance, U.S. Atomic Energy Commission), Nuclear Fuel Services, West Valley, New York, May 6. [SRDB Ref ID: 28343, p. 322]
- Vance, R. F., 1986, *Characterization of the Head End Cells at the West Valley Nuclear Fuel Reprocessing Plant*, DOE/NE/44139-31, West Valley Nuclear Services Company, West Valley, New York, November.
- Wenstrand, T. K., 1967a, "Radiation Contamination Status Report, November 1967," memorandum to R. B. Keely, Nuclear Fuel Services, West Valley, New York, December 15. [SRDB Ref ID: 24419, p. 24]
- Wenstrand, T. K., 1967b, "Yearly Whole Body Exposure for 1967," memorandum to R. B. Keely, Nuclear Fuel Services, December 7. [SRDB Ref ID: 28325, p. 23]
- Wenstrand, T., 1967c, Supplementary Analysis of Whole Body Counts. [SRDB Ref ID: 24404, p. 1797]
- Wenstrand, T. K., 1967d, "Radiation Contamination Status Report, October 1967," memorandum to R. B. Keely, Nuclear Fuel Services, West Valley, New York, November 16. [SRDB Ref ID: 24419, p. 53]
- Wenstrand, T. K., 1968a, "Radiation Contamination Status Report, December 1967," memorandum to R. B. Keely, Nuclear Fuel Services, West Valley, New York, January 8. [SRDB Ref ID: 24419, p. 2]
- Wenstrand, T. K., 1968b, "Radiation Contamination Status Report, March 1968," memorandum to R.
 B. Keely, Nuclear Fuel Services, West Valley, New York, April 1. [SRDB Ref ID: 24422, p. 183]
- Wenstrand, T. K., 1968c, untitled letter to J. J. Mueller (Eberline Instrument Company), February 29. [SRDB Ref ID: 24431, p. 209]

- Wenstrand, T. K., 1968d, untitled letter to Isotopes Inc., West Valley, New York, September 23. [SRDB Ref ID: 24431, p. 52]
- Wenstrand, T. K., 1968e, "Radiation Contamination Status Report, February 1968," memorandum to R. B. Keely, Nuclear Fuel Services, West Valley, New York, March 1. [SRDB Ref ID: 24422, p. 186]
- Wenstrand, T. K., 1968f, "Radiation Contamination Status Report, January 1968," memorandum to R. B. Keely, Nuclear Fuel Services, West Valley, New York, February 6. [SRDB Ref ID: 24422, p. 203]
- Wenstrand, T. K., 1969a, "Radiation Contamination Status Report, September 1969," memorandum to R. B. Keely, Nuclear Fuel Services, West Valley, New York, October 6. [SRDB Ref ID: 24422, p. 135]
- Wenstrand, T. K., 1969b, "Radiation Contamination Status Report, August 1969," memorandum to J. P. Duckworth, West Valley, New York, September 3. [SRDB Ref ID: 24422, p. 137]
- Wenstrand, T. K., 1969c, "Radiation-Contamination Status Report October 1969," memorandum to R. B. Keely, West Valley, New York, November 6. [SRDB Ref ID: 24422, p. 132]
- Wenstrand, T. K., 1970, "Radiation Work Restrictions," memorandum to distribution, West Valley, New York, April 10.
- Wenstrand, T. K., 1971a, "Health and Safety Monthly Report October 1971," memorandum to J. P. Duckworth, West Valley, New York, November 5. [SRDB Ref ID: 24422, p. 56]
- Wenstrand, T. K., 1971b, "Summary of 1970 Radiation Exposures," memorandum to J. P. Duckworth, West Valley, New York, March 9. [SRDB Ref ID: 29089, p. 134]
- Wenstrand, T. K., 1971c, "Health and Safety Monthly Report November 1971," memorandum to J. P. Duckworth, West Valley, New York, December 8. [SRDB Ref ID: 24422, p. 54]
- Wenstrand, T. K., 1971d, "Health and Safety Monthly Report May 1971," memorandum to J. P. Duckworth, West Valley, New York, June 7. [SRDB Ref ID: 24422, p. 64]
- Wenstrand, T. K., 1971e, "Reduction of Whole Body Exposures to 5 Rems/Year," memorandum to J. P. Duckworth, West Valley, New York, July 1.
- Wenstrand, T. K., 1971f, "Safety and Industrial Relations Monthly Report April 1971," memorandum to J. P. Duckworth, West Valley, New York, May 7. [SRDB Ref ID: 24422, p. 66]
- Wenstrand, T. K., 1971g, "Contamination Around HEV," memorandum to B. E. Knight, West Valley, New York, October 12. [SRDB Ref ID: 24437, p. 1148]
- Wenstrand, T. K., 1972a, Plant Radiation Status March 15, 1972, memorandum to J. P. Duckworth, West Valley, New York, March 17. [SRDB Ref ID: 28325, p. 12]
- Wenstrand, T. K., 1972b, "Health and Safety Monthly Report January 1972," memorandum to J. P. Duckworth, West Valley, New York, February 8. [SRDB Ref ID: 24422, p. 50]

- Wenstrand, T. K., 1972c, "Radiation Exposure for 1971," memorandum to J. P. Duckworth, June 1. [SRDB Ref ID: 29089, p. 118]
- Wenstrand, T. K., 1972d, "Status of Plant Decontamination," memorandum to J. P. Duckworth, West Valley, New York, July 27. [SRDB Ref ID: 28325, p. 2]
- Wenstrand, T. K., 1972e, *Plutonium Nitrate Contaminated Puncture Wound*, West Valley, New York.
- Wenstrand, T. K., 1972f, "Health and Safety Monthly Report February 1972," memorandum to J. P. Duckworth, West Valley, New York, March 8. [SRDB Ref ID: 24422, p. 48]
- Wenstrand, T. K., 1972g, "Health and Safety Monthly Report May, 1972," memorandum to J. P. Duckworth, West Valley, New York, June 7. [SRDB Ref ID: 24422, p. 42]
- Wenstrand, T. K., 1972h, "Health and Safety Monthly Report December 1971," memorandum to J. P. Duckworth, West Valley, New York, January 2. [SRDB Ref ID: 24422, p. 52]
- Wenstrand, T. K., 1972i, "Health & Safety Monthly Report June 1972," memorandum to J. P. Duckworth, West Valley, New York, July 10. [SRDB Ref ID: 24422, p. 41]
- Wenstrand, T. K., 1972j, "Health and Safety Monthly Report April 1972," memorandum to J. P. Duckworth, West Valley, New York, May 11. [SRDB Ref ID: 24422, p. 44]
- Wenstrand, T. K., 1972k, "Health and Safety Monthly Report March 1972," memorandum to J. P. Duckworth, West Valley, New York, April 13. [SRDB Ref ID: 24422, p. 46]
- Wenstrand, T. K., 1973, "Radiation Levels at WTF Shelter," memorandum to B. E. Knight, West Valley, New York, April 19. [SRDB Ref ID: 29089, p. 67]
- Wenstrand, T. K., 1974, "LWA and UWA Pump Changes," memorandum to J. R. Clark, West Valley, New York, December 5. [SRDB Ref ID: 28398, p. 10]
- WVDP (West Valley Demonstration Project), 2005, "Summary of Facility Radiological Status by Area," Appendix C, WVDP Decommissioning Plan, Rev. 0, Draft 2. [SRDB Ref ID: 30280]
- WVNSC (West Valley Nuclear Services Company), 1983, 1982 Environmental Monitoring Program Report For The West Valley Demonstration Project, West Valley, New York, May.
- WVNSC (West Valley Nuclear Services Company), 1986, 1985 Environmental Monitoring Program Report For The West Valley Demonstration Project, WVDP-040, West Valley, New York, March.
- WVNSC (West Valley Nuclear Services Company), 1988, Personnel <u>In Vivo</u> Counting, RC-DOS-6, Rev. 0, West Valley Demonstration Project, West Valley, New York, November 2. [SRDB Ref ID: 24207]
- WVNSC (West Valley Nuclear Services Company), 1990a, *In Vitro Monitoring*, RC-DOS-7, Rev. 1, West Valley Demonstration Project, West Valley, New York, July 31. [SRDB Ref ID: 24193]
- WVNSC (West Valley Nuclear Services Company), 1990b, <u>In Vitro</u> Monitoring, RC-DOS-7, Rev. 2, West Valley Demonstration Project, West Valley, New York, December 7. [SRDB Ref ID: 24194]

	Document No. ORAUT-TKBS-0057	Revision No. 00	Effective Date: 06/22/2007	Page 99 of 152
--	------------------------------	-----------------	----------------------------	----------------

- WVNSC (West Valley Nuclear Services Company), 1990c, Interpretation of <u>In Vitro</u> Bioassay Measurements, RC-DOS-30, Rev. 0, West Valley Demonstration Project, West Valley, New York, October 1. [SRDB Ref ID: 24207]
- WVNSC (West Valley Nuclear Services Company), 1993, Personnel <u>In Vivo</u> Counting, RC-DOS-6, Rev. 2, West Valley Demonstration Project, West Valley, New York, May 12. [SRDB Ref ID: 24186]
- WVNSC (West Valley Nuclear Services Company), 1994, Sealed Rooms Paper Characterization, WVDP-RFI-016, Rev. 0, West Valley, New York, May. [SRDB Ref ID: 30284]
- WVNSC (West Valley Nuclear Services Company), 1997, Interpretation of Bioassay Measurements, RC-DOS-30, Rev. 2, West Valley Demonstration Project, West Valley, New York, September 30. [SRDB Ref ID: 24209]
- WVNSC (West Valley Nuclear Services Company), 1999, *Area and Emergency Dosimetry Badges*, RC-DOS-34, Rev. 6, West Valley Demonstration Project, West Valley, New York, October 29.

Page 1 of 52

TABLE OF CONTENTS

<u>SECTI</u>	ON		TITLE	PAGE
A1.0	Acid R	ecovery (Cell	106
	A1.1		gical Conditions	
		A1.1.1	External Exposure Data	106
A2.0	Acid R	ecovery F	Pump Room	106
	A2.1	Radiolog	gical Conditions	107
		A2.1.1	External Exposure Data	
		A2.1.2	Removable Contamination Data	107
A3.0	Analyti		Laboratories, and North Operating Aisle	
	A3.1	Radiolog	gical Conditions	
		A3.1.1	External Exposure Data	
		A3.1.2	Removable Contamination Data	109
A4.0	Cell Ad	cess Ais	le	109
	A4.1	Radiolog	gical Conditions	109
		A4.1.1	Removable Contamination Data	109
		A4.1.2	Airborne Contamination Data	109
A5.0	Cell C		ms	109
	A5.1	Impact o	f the Thorex Campaign on Airborne Activity Levels in the Cell	
			ooms	
	A5.2		Purpose Cell Crane Room and Extension	
		A5.2.1	Radiological Conditions	
		A5.2.2	External Exposure Data	
		A5.2.3	Removable Contamination Data	
		A5.2.4	Airborne Contamination Data	
	A5.3		Mechanical Cell Crane Room	
		A5.3.1	External Exposure Data	
		A5.3.2	Removable Contamination Data	
		A5.3.3	Airborne Contamination Data	
	A5.4		al Process Cell Crane Room	
		A5.4.1	External Exposure Data	
			Removable Contamination Data	
		A5.4.3	Airborne Contamination Data	
A6.0			ating Aisle and Chemical Viewing Aisle	
	A6.1		gical Conditions	
			External Exposure Data	
		A6.1.2	Removable Contamination Data	113
A7.0	Chemi	cal Proce	ss Cell	113

Page 2 of 52

	A7.1	Radiological Conditions		13
A8.0	Contro	Room		13
	A8.1			
			sure Data1	
A9.0	Equipr	ant Decentemination B	nom and Equipment Decentamination Ream	
A9.0			oom and Equipment Decontamination Room	14
	A9.1			
			sure Data1	
		•	ntamination Data1	
			amination Data1	
	F 4	an and Draduat Durifian		
A10.0			ion Cells1	
	A10.1			
			sure Data1	
			ntamination Data1	
		A10.1.3 Airborne Conta	amination Data1	16
A11.0	Extrac	on Chemical Room	1 [.]	16
	A11.1	Radiological Conditions		16
			sure Data1	
			ntamination Data1	
A12.0	Extrac	on Sample Aisle and Pr	ocess Sample Cell 21	17
	, _	A12.1.1 Removable Co	ntamination Data1	17
			amination Data	
				47
A13.0	Fuel R			
			onditions1	
			ncentration Data1	
			sure Data12	
			ntamination Data12	
		A13.1.5 Airborne Conta	amination Data12	22
A14.0	Guard	House	1:	22
	A14.1	Radiological Conditions		22
A15.0	Gener	Operating Aisle	1:	23
	A15.1	Radiological Conditions		23
			Data1	
			amination Data	
	0			<u></u>
A16.0				
	A16.1	Radiological Conditions		23

Page 3 of 52

	A16.1.1 External Exposure Data	124
	A16.1.2 Removable Contamination Data	124
A17.0	Head End Ventilation Building and Crane Room	
	A17.1 Radiological Conditions.	124
	A17.1.1 External Exposure Data A17.1.2 Removable Contamination Data	
		124
A18.0	Hot Acid Cell	125
	A18.1 Radiological Conditions	
	A18.1.1 External Exposure Data	
	A18.1.2 Removable Survey Data	125
		405
A19.0	Hot Shop	
	A19.1 Radiological Conditions.	
	A19.1.1 External Exposure Data A19.1.2 Removable Contamination Data	
	A 19.1.2 Removable Contamination Data	125
A20.0	Instrument Shop/Old Instrument Shop	126
	A20.1 Radiological Conditions	
	A20.1.1 External Exposure Data	126
	A20.1.2 Removable Contamination Levels	
A21.0	Interceptor and New Interceptor	
	A21.1 Radiological Conditions.	
	A21.1.1 External Exposure Data	127
A22.0	Laundry	127
-	A22.1 Radiological Conditions	
	A22.1.1 External Exposure Data	
	A22.1.2 Removable Contamination Data	
	A22.1.3 Airborne Contamination Data	127
A23.0	Load-in Facility	128
A24.0	Low Level Waste Treatment Facility	128
	A24.1 Radiological Conditions	
	A24.1.1 External Exposure Data	128
A25 0	Low Level Wastewater Treatment Building	128
A20.0	A25.1 Radiological Conditions	
	A25.1.1 External Exposure Data	
	A25.1.2 Removable Contamination Data	
A26.0	Lower Extraction Aisle	
	A26.1 Radiological Conditions	129

Page 4 of 52

A27.0 Lower Warm Aisle 129 A27.1 Radiological Conditions 130 A27.1.1 External Exposure Data 130 A27.1.2 Removable Contamination Data 130 A27.1.3 Airborne Contamination Data 130 A28.0 Main Office Building 131 A28.1 Radiological Conditions 131 A28.1 External Exposure Data 131 A28.1 Radiological Conditions 131 A28.1.2 Removable Contamination Data 131 A28.0 Maintenance Shop and Warehouse 131 A29.0 Maintenance Shop and Warehouse 131 A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Aithorne Contamination Data 134 <tr< th=""><th></th><th>A26.1.1 External Exposure Data</th><th>129</th></tr<>		A26.1.1 External Exposure Data	129
A27.1 Radiological Conditions. 130 A27.1.1 External Exposure Data 130 A27.1.2 Removable Contamination Data. 130 A27.1.3 Airborne Contamination Data. 130 A28.0 Main Office Building. 131 A28.1 Radiological Conditions. 131 A28.1.1 External Exposure Data 131 A28.1.2 Removable Contamination Data. 131 A29.0 Maintenance Shop and Warehouse. 131 A29.1 Radiological Conditions. 132 A30.0 Manipulator Repair Room. 132 A30.1 Radiological Conditions. 132 A30.1.2 Removable Contamination Data. 132 A30.1.2 Removable Contamination Data. 132 A31.0 Rechanical Operating Aisle (North, East and West) 132 A31.1 Ratiological Conditions. 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data. 133 A31.1.3 Airborne Contamination Data. 134 A32.0 MSM Shop/Contact Size Reduction Facil	A27.0	Lower Warm Aisle	129
A27.1.1 External Exposure Data 130 A27.1.2 Removable Contamination Data. 130 A27.1.3 Airborne Contamination Data. 130 A28.0 Main Office Building. 131 A28.1 Radiological Conditions. 131 A28.1.1 External Exposure Data 131 A28.1.2 Removable Contamination Data. 131 A28.1.1 External Exposure Data 131 A28.0 Maintenance Shop and Warehouse. 131 A29.1 Radiological Conditions. 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions. 132 A30.1.1 External Exposure Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data. 133 A31.1.1 External Exposure Data 133 A31.1.1 External Exposure Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions. 13			
A27.1.2 Removable Contamination Data. 130 A27.1.3 Airborne Contamination Data. 131 A28.0 Main Office Building 131 A28.1 Radiological Conditions. 131 A28.1.1 External Exposure Data 131 A28.1.2 Removable Contamination Data. 131 A29.0 Maintenance Shop and Warehouse 131 A29.1 Radiological Conditions. 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions. 132 A30.1 External Exposure Data 132 A30.1 Radiological Conditions. 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Ratiological Conditions. 133 A31.1.1 External Exposure Data 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data. 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data. <td< td=""><td></td><td></td><td></td></td<>			
A27.1.3 Airborne Contamination Data 130 A28.0 Main Office Building 131 A28.1 Radiological Conditions 131 A28.1.2 Removable Contamination Data 131 A28.1.2 Removable Contamination Data 131 A28.1.2 Removable Contamination Data 131 A29.0 Maintenance Shop and Warehouse 131 A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 134 A33.1.2 Removable Contamination Data<			
A28.1 Radiological Conditions 131 A28.1.1 External Exposure Data 131 A28.1.2 Removable Contamination Data 131 A29.0 Maintenance Shop and Warehouse 131 A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A30.1.1 External Exposure Data 132 A31.1 External Exposure Data 133 A31.1 External Exposure Data 132 A31.1 Ratiological Conditions 133 A31.1 External Exposure Data 133 A31.1 Ratiological Conditions 133 A31.1.1 External Exposure Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134			
A28.1 Radiological Conditions 131 A28.1.1 External Exposure Data 131 A28.1.2 Removable Contamination Data 131 A29.0 Maintenance Shop and Warehouse 131 A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A30.1.1 External Exposure Data 132 A31.1 External Exposure Data 133 A31.1 External Exposure Data 132 A31.1 Ratiological Conditions 133 A31.1 External Exposure Data 133 A31.1 Ratiological Conditions 133 A31.1.1 External Exposure Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134	A28 0	Main Office Building	131
A28.1.1 External Exposure Data 131 A28.1.2 Removable Contamination Data 131 A29.0 Maintenance Shop and Warehouse 131 A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 External Exposure Data 133 A31.1.1 External Exposure Data 133 A31.1.1 External Exposure Data 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A32.1.2 Removable Contamination Data 134 A32.1.1 External Exposure Data 135 A33.1.3 Airborne Contamination Data <t< td=""><td>/ 2010</td><td></td><td></td></t<>	/ 2010		
A28.1.2 Removable Contamination Data 131 A29.0 Maintenance Shop and Warehouse. 131 A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1 External Exposure Data 134 A32.1 Radiological Conditions 134 A33.1.3 Airborne Contamination Data 134 A33.1 Radiological Conditions 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Con			
A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A32.1.3 Airborne Contamination Data 134 A32.1.4 Radiological Conditions 134 A32.1.1 External Exposure Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A34.1.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 136 A34.1 Radiological Conditions 136 A34.1.2 Removable Contamination Data 136			
A29.1 Radiological Conditions 132 A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A32.1.3 Airborne Contamination Data 134 A32.1.4 Radiological Conditions 134 A32.1.1 External Exposure Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A34.1.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 136 A34.1 Radiological Conditions 136 A34.1.2 Removable Contamination Data 136	A29 0	Maintenance Shop and Warehouse	131
A30.0 Manipulator Repair Room 132 A30.1 Radiological Conditions 132 A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1 Raternal Exposure Data 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.1 External Exposure Data 135 A34.1 Radiological Conditions	/ 120.0		
A30.1 Radiological Conditions			
A30.1.1 External Exposure Data 132 A30.1.2 Removable Contamination Data 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A32.1.1 External Exposure Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.3 Airborne Contamination Data 135 A33.1.1 External Exposure Data 135 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions<	A30.0		
A30.1.2 Removable Contamination Data. 132 A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions. 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data. 133 A31.1.3 Airborne Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions. 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1 Radiological Conditions 136 A34.1 Reternal Exposure Data 136 A34.1 Rediological Conditions 136 A34.1 Reternal Exposure Data 136 A3			
A31.0 Mechanical Operating Aisle (North, East and West) 132 A31.1 Radiological Conditions 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 133 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1.1 External Exposure Data 134 A32.1 Radiological Conditions 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.3 Airborne Contamination Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1.1 External Exposure Data <t< td=""><td></td><td></td><td></td></t<>			
A31.1 Radiological Conditions. 133 A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions. 134 A32.1 Rational Exposure Data 134 A32.1.2 Removable Contamination Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1 Radiological Conditions. 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.3 Airborne Contamination Data 135 A34.1.1 External Exposure Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1.1 External Exposure Data 136 A34.1.2 Removable Contamination Data 136 A35.0 Off Gas Cell 137		A30.1.2 Removable Contamination Data	132
A31.1.1 External Exposure Data 133 A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1 Ratiological Conditions 134 A32.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1 Radiological Conditions 135 A33.1.1 External Exposure Data 135 A33.1 Radiological Conditions 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1 External Exposure Data 136 A34.1.1 External Exposure Data 136 A34.1.2 Removable Contamination Data 136 A35.0 Off Gas Cell 137	A31.0	Mechanical Operating Aisle (North, East and West)	132
A31.1.2 Removable Contamination Data 133 A31.1.3 Airborne Contamination Data 134 A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1 Radiological Conditions 134 A32.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1 Radiological Conditions 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.2 Removable Contamination Data 135 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1 Radiological Conditions 136 A34.1.1 External Exposure Data 136 A34.1.1 External Exposure Data 136 A34.1.1 External Exposure Data 136 A34.1.2 Removable Contamination Data 136 A35.0 Off Gas Cell 137 <			
A31.1.3 Airborne Contamination Data134A32.0 MSM Shop/Contact Size Reduction Facility134A32.1 Radiological Conditions134A32.1.1 External Exposure Data134A32.1.2 Removable Contamination Data134A33.0 Off Gas Aisle and Process Sample Cell 3135A33.1 Radiological Conditions135A33.1 Radiological Conditions135A33.1.1 External Exposure Data135A33.1.2 Removable Contamination Data135A33.1.3 Airborne Contamination Data136A34.0 Off Gas Blower Room136A34.1 Radiological Conditions136A34.1.1 External Exposure Data136A34.1.2 Removable Contamination Data136A34.1.1 External Exposure Data136A34.1.2 Removable Contamination Data136A34.1.2 Removable Contamination Data137A35.0 Off Gas Cell137			
A32.0 MSM Shop/Contact Size Reduction Facility 134 A32.1 Radiological Conditions 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1 Radiological Conditions 135 A33.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.3 Airborne Contamination Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1 External Exposure Data 136 A34.1 Radiological Conditions 136 A34.1.1 External Exposure Data 136 A34.1.2 Removable Contamination Data 136 A34.1.2 Removable Contamination Data 137 A35.0 Off Gas Cell 137			
A32.1 Radiological Conditions. 134 A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data. 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1 Radiological Conditions. 135 A33.1 External Exposure Data 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.3 Airborne Contamination Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions. 136 A34.1 Radiological Conditions 136 A34.1 Radiological Conditions 136 A34.1.1 External Exposure Data 136 A34.1.2 Removable Contamination Data 137 A35.0 Off Gas Cell 137		A31.1.3 Airborne Contamination Data	134
A32.1.1 External Exposure Data 134 A32.1.2 Removable Contamination Data 134 A33.0 Off Gas Aisle and Process Sample Cell 3 135 A33.1 Radiological Conditions 135 A33.1.1 External Exposure Data 135 A33.1.2 Removable Contamination Data 135 A33.1.3 Airborne Contamination Data 136 A34.0 Off Gas Blower Room 136 A34.1 Radiological Conditions 136 A34.1 External Exposure Data 136 A34.1 Removable Contamination Data 136 A34.1 External Exposure Data 136 A34.1.2 Removable Contamination Data 137 A35.0 Off Gas Cell 137	A32.0		
A32.1.2 Removable Contamination Data		A32.1 Radiological Conditions	134
A33.0Off Gas Aisle and Process Sample Cell 3135A33.1Radiological Conditions135A33.1.1External Exposure Data135A33.1.2Removable Contamination Data135A33.1.3Airborne Contamination Data136A34.0Off Gas Blower Room136A34.1Radiological Conditions136A34.1.1External Exposure Data136A34.1.2Removable Contamination Data136A35.0Off Gas Cell137		A32.1.1 External Exposure Data	134
A33.1 Radiological Conditions.135A33.1.1 External Exposure Data135A33.1.2 Removable Contamination Data135A33.1.3 Airborne Contamination Data136A34.0 Off Gas Blower Room136A34.1 Radiological Conditions.136A34.1.1 External Exposure Data136A34.1.2 Removable Contamination Data137		A32.1.2 Removable Contamination Data	134
A33.1.1 External Exposure Data	A33.0	Off Gas Aisle and Process Sample Cell 3	135
A33.1.2 Removable Contamination Data		A33.1 Radiological Conditions	135
A33.1.3 Airborne Contamination Data			
A34.0 Off Gas Blower Room			
A34.1 Radiological Conditions		A33.1.3 Airborne Contamination Data	136
A34.1 Radiological Conditions	A34.0	Off Gas Blower Room	136
A34.1.1 External Exposure Data			
A34.1.2 Removable Contamination Data		A34.1.1 External Exposure Data	136
	A35.0	Off Gas Cell	137
A35.1 Radiological Conditions		A35.1 Radiological Conditions	
A35.1.1 External Exposure Data			

Page 5 of 52

A36.1.1 External Exposure Data 138 A37.0 Process Chemical Room 138 A37.1 Radiological Conditions 138 A37.1.1 External Exposure Data 138 A38.0 Process Mechanical Cell 139 A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium 139 A39.0 Product Cell, and Uranium Loadout Areas 140 A39.1 Radiological Conditions. 140 A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data. 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions. 141 A40.1 Atiobore Contamination Data 140 A40.1 Radiological Conditions. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area. 141 A43.1 Radiolo	A36.0	Permanent Ventilation System Building A36.1 Radiological Conditions	
A36.1.2 Removable Contamination Data. 138 A37.0 Process Chemical Room 138 A37.1 Radiological Conditions. 138 A37.1.1 External Exposure Data 138 A37.1.2 Removable Contamination Data. 138 A38.0 Process Mechanical Cell. 139 A38.1 Radiological Conditions. 139 A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium 139 A39.1 Radiological Conditions. 140 A39.1 External Exposure Data 140 A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data. 140 A39.1.3 Airborne Contamination Data. 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions. 141 A41.0 Remote Handled Waste Facility. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.			
 A37.0 Process Chemical Room A37.1 Radiological Conditions A37.1.1 External Exposure Data A37.1.2 Removable Contamination Data A38.0 Process Mechanical Cell A38.1 Radiological Conditions A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium Product Cell, and Uranium Loadout Areas A39.1 Radiological Conditions A39.1.1 External Exposure Data A39.1 Radiological Conditions A39.1.2 Removable Contamination Data A39.1.3 Airborne Contamination Data A40.0 Pulser Equipment Aisle A40.1 Radiological Conditions A40.1 Radiological Conditions A41.0 Remote Handled Waste Facility A43.1 Radiological Conditions A44.1 Radiological Conditions A45.1 Radiological Conditions A45.			
A37.1 Radiological Conditions			
A37.1 Radiological Conditions	A37.0	Process Chemical Room	138
A37.1.1 External Exposure Data 138 A37.1.2 Removable Contamination Data. 138 A38.0 Process Mechanical Cell. 139 A38.1 Radiological Conditions. 139 A38.0 Process Mechanical Cell. 139 A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium 139 A39.1 Radiological Conditions. 140 A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle. 140 A40.1 Aairborne Contamination Data 141 A41.0 Remote Handled Waste Facility. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.1 External Exposure Data 142 A43.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Aiborne Contamination Data 142 A43.1.4 External Exposure Data 142 A43.1		A37.1 Radiological Conditions	138
A38.0 Process Mechanical Cell			
A38.1 Radiological Conditions 139 A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium 139 Product Cell, and Uranium Loadout Areas 139 A39.1 Radiological Conditions 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions 141 A40.1 Airborne Contamination Data 140 A40.1 Radiological Conditions 141 A40.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 External Exposure Data 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A43.1.4 External Exposure Data 142 A44.1.2 Re		A37.1.2 Removable Contamination Data	138
A38.1 Radiological Conditions 139 A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium 139 Product Cell, and Uranium Loadout Areas 139 A39.1 Radiological Conditions 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions 141 A40.1 Airborne Contamination Data 140 A40.1 Radiological Conditions 141 A40.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 External Exposure Data 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A43.1.4 External Exposure Data 142 A44.1.2 Re	A38 0	Process Mechanical Cell	139
A39.0 Product Packaging and Shipping, Product Packaging and Handling, Uranium Product Cell, and Uranium Loadout Areas 139 A39.1 Radiological Conditions 140 A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions 141 A40.1.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A43.1.4 External Exposure Data 142 A43.1.3 Airborne Contamination Data 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Cont	/\00.0		
Product Cell, and Uranium Loadout Areas 139 A39.1 Radiological Conditions. 140 A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions. 141 A40.1 Radiological Conditions. 141 A40.1 Radiological Conditions. 141 A41.0 Remote Handled Waste Facility. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area. 141 A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.1 External Exposure Data 142 A44.1.1 External Exposure Data 142 A44.1 Radiological Conditions. 142 A44.1 Radiological Conditions. 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building. 143 <td></td> <td></td> <td> 100</td>			100
A39.1 Radiological Conditions. 140 A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions. 141 A40.1 Radiological Conditions. 141 A40.1 Radiological Conditions. 141 A40.1 Radiological Conditions. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A42.0 Scrap Removal Area. 141 A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.1 Radiological Conditions. 142 A44.1.1 External Exposure Data 142 A44.1 Radiological Conditions. 143 A45.0 Supernatant Treatment System Support Building. 143 <	A39.0		
A39.1.1 External Exposure Data 140 A39.1.2 Removable Contamination Data 140 A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions 141 A40.1 Radiological Conditions 141 A40.1 Remote Handled Waste Facility 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1 Radiological Conditions 142 A43.1.2 Removable Contamination Data 142 A43.1.2 Removable Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1 Radiological Conditions 143			
A39.1.2 Removable Contamination Data			
A39.1.3 Airborne Contamination Data 140 A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions 141 A40.1 Radiological Conditions 141 A40.1 Adv.1.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions 142 A44.1 Radiological Conditions 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1.1 External Exposure Data 143			
A40.0 Pulser Equipment Aisle 140 A40.1 Radiological Conditions 141 A40.1.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A42.0 Scrap Removal Area 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.1 Radiological Conditions 142 A44.1 Radiological Conditions 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1.1 External Exposure Data 143		A39.1.2 Removable Contamination Data	140
A40.1 Radiological Conditions. 141 A40.1.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data. 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions. 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 143 A45.1 Radiological Conditions. 143		A39.1.3 Airborne Contamination Data	140
A40.1 Radiological Conditions. 141 A40.1.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data. 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions. 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 143 A45.1 Radiological Conditions. 143	A 40 0	Pulsar Equipment Aisle	140
A40.1.1 Airborne Contamination Data 141 A41.0 Remote Handled Waste Facility 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions 142 A44.1 Radiological Conditions 142 A44.1 Radiological Conditions 142 A44.1 Radiological Conditions 143 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1 External Exposure Data 143 A45.1 Radiological Conditions 143 A45.1 External Exposure Data 143	A40.0		
A41.0 Remote Handled Waste Facility. 141 A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions 142 A44.1 External Exposure Data 142 A44.1 Radiological Conditions 142 A44.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1.1 External Exposure Data 143 A45.1.1 External Exposure Data 143			
A42.0 Sample Storage Cell, Analytical Hot Cells, and Analytical Decontamination 141 A43.0 Scrap Removal Area			
Aisle 141 A43.0 Scrap Removal Area 141 A43.1 Radiological Conditions 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions 142 A44.1 Exposure Data 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1 External Exposure Data 143 A45.1 Radiological Conditions 143	A41.0	Remote Handled Waste Facility	141
A43.0 Scrap Removal Area. 141 A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data. 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions. 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building. 143 A45.1 Radiological Conditions. 143 A45.1 External Exposure Data 143 A45.1 Radiological Conditions. 143 A45.1 Radiological Conditions. 143 A45.1 External Exposure Data 143	A42.0		
A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data. 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions. 142 A44.1 External Exposure Data 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data. 143 A45.0 Supernatant Treatment System Support Building. 143 A45.1 Radiological Conditions. 143 A45.1.1 External Exposure Data 143		Aisle	141
A43.1 Radiological Conditions. 142 A43.1.1 External Exposure Data 142 A43.1.2 Removable Contamination Data. 142 A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions. 142 A44.1 External Exposure Data 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data. 143 A45.0 Supernatant Treatment System Support Building. 143 A45.1 Radiological Conditions. 143 A45.1.1 External Exposure Data 143	A43.0	Scrap Removal Area	141
A43.1.1External Exposure Data142A43.1.2Removable Contamination Data142A43.1.3Airborne Contamination Data142A44.0Solvent Storage Terrace142A44.1Radiological Conditions142A44.1.1External Exposure Data142A44.1.2Removable Contamination Data143A45.0Supernatant Treatment System Support Building143A45.1Radiological Conditions143A45.1External Exposure Data143A45.1Radiological Conditions143A45.1Radiological Conditions143A45.1External Exposure Data143A45.1External Exposure Data143			
A43.1.2 Removable Contamination Data142A43.1.3 Airborne Contamination Data142A44.0 Solvent Storage Terrace142A44.1 Radiological Conditions142A44.1.1 External Exposure Data142A44.1.2 Removable Contamination Data143A45.0 Supernatant Treatment System Support Building143A45.1 Radiological Conditions143A45.1 External Exposure Data143A45.1 Radiological Conditions143A45.1 Radiological Conditions143A45.1.1 External Exposure Data143			
A43.1.3 Airborne Contamination Data 142 A44.0 Solvent Storage Terrace 142 A44.1 Radiological Conditions 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1 Radiological Conditions 143 A45.1.1 External Exposure Data 143			
A44.1 Radiological Conditions. 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building. 143 A45.1 Radiological Conditions. 143 A45.1 External Exposure Data 143 A45.1 Radiological Conditions. 143 A45.1.1 External Exposure Data 143			
A44.1 Radiological Conditions. 142 A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building. 143 A45.1 Radiological Conditions. 143 A45.1 External Exposure Data 143 A45.1 Radiological Conditions. 143 A45.1.1 External Exposure Data 143			
A44.1.1 External Exposure Data 142 A44.1.2 Removable Contamination Data 143 A45.0 Supernatant Treatment System Support Building 143 A45.1 Radiological Conditions 143 A45.1.1 External Exposure Data 143	A44.0	5	
A44.1.2 Removable Contamination Data			
A45.0 Supernatant Treatment System Support Building			
A45.1 Radiological Conditions		A44.1.2 Removable Contamination Data	143
A45.1 Radiological Conditions	A45.0	Supernatant Treatment System Support Building	
A45.1.1 External Exposure Data143			
		A45.1.1 External Exposure Data	

Page 6 of 52

A46.0	Upper Extraction Aisle A46.1 Radiological Conditions A46.1.1 External Exposure Data	143
	A46.1.2 Removable Contamination Data	
A47.0	Upper Warm Aisle and Process Sample Cell 1	144
	A47.1 Radiological Conditions	
	A47.1.1 External Exposure Data	
	A47.1.2 Removable Contamination Data	
	A47.1.3 Airborne Contamination Levels	146
A48.0	Utility Room and Stairwells	146
	A48.1 Radiological Conditions	
	A48.1.1 External Exposure Data	
	A48.1.2 Removable Contamination Data	
	A48.1.3 Airborne Concentration Data	
A49.0	Ventilation Exhaust Cell	148
	A49.1 Radiological Conditions	148
	A49.1.1 External Exposure Data	
A50.0	Ventilation Systems	
	A50.1 Main Ventilation System	
	A50.2 Head End Ventilation System	150
A51.0	Ventilation Wash Room	150
	A51.1 Radiological Conditions	150
	A51.1.1 External Exposure Data	
	A51.1.2 Airborne Contamination Data	
A52.0	Waste Tank Farm	151
	A52.1 Radiological Conditions	151
	A52.1.1 External Exposure Data	151

Page 7 of 52

This section describes specific facilities and areas where personnel exposures occurred, with an emphasis on radiological conditions and occurrences.

The ground level of the reprocessing plant was the 100-ft elevation. There was one level below the ground level and four levels above. Attachment B contains drawings of the reprocessing plant and the site.

A1.0 ACID RECOVERY CELL

The Acid Recovery Cell (ARC) was in the southwest corner of the plant on the 114.5-ft level. It housed the fractionator and other equipment used for recovery of process acid. The recovered acid would be mixed with chemicals in the XCR before reuse. Significant dose rates existed in the vicinity of acid recovery equipment from the buildup of ruthenium and carryover from the waste evaporators.

The ARC equipment was known to leak during operation. A spill in the ARC in 1967 required removal of nearly 24 in. of the affected floor. Six additional inches of concrete had to be poured over the original floor thickness to provide shielding. The spill also affected the cells on the ground level below, and reached the soil beneath the process building. It was determined to be the source of a groundwater plume that was discovered years later (WVNSC 1994 and WVDP 2005).

A1.1 RADIOLOGICAL CONDITIONS

A1.1.1 <u>External Exposure Data</u>

In November 1967 piping from the Acid Recovery Cell read 3.5 R/hr at 12 in.

On March 5, 1968, a tank in the Acid Recovery Cell read 30 R/hr on its sides and 100 R/hr at the bottom (Wenstrand 1968b).

In April 1968 chemical decontamination of the Acid Recovery Cell reduced exposure rates from a general level of 2 R/hr to 4 R/hr to 125 mR/hr. The maximum exposure rate was reduced from 50 R/hr to 3 R/hr. Shielding of localized activity reduced the general level further to 120 mR/hr (Keely 1968j).

Decontamination efforts in the Acid Recovery Cell in September 1969 reduced radiation levels by a factor of 20 (Wenstrand 1969a).

A2.0 ACID RECOVERY PUMP ROOM

The ARPR was located in the southwest corner of the plant on the ground level. It contained equipment that supported operation of the Acid Recovery System and a sampler that collected a 24-hour composite sample of the fractionator condensate. This condensate was discharged to the plant's liquid effluent interceptor system.

Decontamination work in the ARPR was performed between April 28, 1976, and May 6, 1976. On May 6, 1976, the door between the ARPR and the South Stairs was sealed using a plywood cover

Page 8 of 52

with its edges caulked over. A concrete sill had been installed at the door on May 1, 1976 (WVNSC 1994).

A2.1 RADIOLOGICAL CONDITIONS

The ARPR was affected by the high exposure rates associated with the acid recovery system throughout the plant and was chronically contaminated from maintenance operations. In addition, leaks from ARPR equipment resulted in erosion of the concrete walls and floor.

A2.1.1 External Exposure Data

In early February 1967 operators taking samples in the ARPR had only 15 minutes before they reached their allowable weekly exposure limit. By February 19, 1967, exposure rates had increased to the point where the operators had only 2 minutes before they reached their weekly limit (Keely 1967c).

"Easily" removable contamination continued to be a problem in the ARPR (and the OGBR) in April 1968, giving skin dose rates of 120 mrad/hr (Keely 1968j).

In February 1972 replacement of the 7G-5 jet in the ARPR required 40 rem of whole-body exposure. The initial working area exposure rate was 60 R/hr. Shielding was installed to reduce the exposure rate to where a reasonable working time could be established (Wenstrand 1972f).

An exposure rate of 30 R/hr was encountered in the ARPR in September 1972 (Morrow 1972a).

In October 1972 exposure rates of 20 R/hr were encountered during cleanup work in the ARPR. This is referred to as an area radiation dose rate. It was not a hot spot (Morrow 1972b).

A2.1.2 <u>Removable Contamination Data</u>

Smears from the ARPR in February 1968 showed typical levels of 1.8E+06 dpm/100 cm² beta (Wenstrand 1968e).

A3.0 ANALYTICAL AISLE, LABORATORIES, AND NORTH OPERATING AISLE

The analytical level of the plant (131-ft elevation) included six radiochemical labs:

- Hot Lab
- QC Lab
- Alpha Lab
- Product Lab (also sometimes referred to as the Uranium Lab)
- Mass Spectrometry Lab
- Emission Spectrometry Lab

Page 9 of 52

There was also a counting room north of the Mass Spectrometry Lab and a chemical storage room. Access to the laboratory areas was via the Analytical Aisle. The Analytical Aisle contained viewing windows and manipulators for operations within the analytical hot cells and Sample Cell 2C.

Under the WVDP the laboratories were modified somewhat to support HLW vitrification operations. Some of the laboratories were expanded and renamed. One was called the Radiochemistry Lab. Another was the Vitrification Lab.

The North Operating Aisle was on the north end of the analytical level east of the CPC Crane Room (CCR). On the east side of the North Operating Aisle was the access to the hoist mechanism for the shield door between the PMC and the Process Mechanical Cell Crane Room (PMCR). This area was known as the penthouse.

NFS decontaminated all of the operating era laboratories after shutdown.

A3.1 RADIOLOGICAL CONDITIONS

A3.1.1 <u>External Exposure Data</u>

A chronic source of exposure in the Analytical Aisle was activity buildup in the ventilation system air washer. Activity in the washer caused exposure rates up to 40 mR/hr in the Analytical Aisle, which was located directly above the washer cell. NFS (1976) states that this exposure rate could be kept at 20 mR/hr with repeated decontamination of the washer and the addition of lead shielding to the floor of the Analytical Aisle.

In addition to the air washer, the ventilation system ducting was another chronic source of external personnel exposure in the analytical laboratories. Buildup of activity in the duct would produce exposure rates in the analytical laboratories of 10 mR/hr to 20 mR/hr. Lead shielding was added to the floors of the labs to the extent allowed by floor loading constraints (NFS 1976).

Another source of exposure was buildup of contamination from maintenance activities in the penthouse area resulted in exposure rates of 5 mR/hr to 10 mR/hr in the adjacent analytical areas (Wenstrand 1972a).

Routine handling of samples was also an exposure mechanism. Samples having dose rates up to 500 mrem/hr were analyzed in the laboratories in hoods. Shadow shielding was apparently used (NFS 1973b, p. 6.1-6).

In early 1968 the Hot Lab contained a high radiation area caused by solution leaking from a faulty drain (Runion 1968, p. 21 of Action Plan - Part 2).

In October 1969 the exposure rate in the Analytical Aisle was 50 mR/hr.

In 1990 dose rates in the North Operating Aisle ranged up to 8 mrem/hr. In 2004 the general level was around 1.5 mrem/hr, and in 2005 it was typically less than 1 mrem/hr except for one area by the east doorway that ranged up to 2 mrem/hr (WVDP 2005).

Page 10 of 52

As of 2005 dose rates in the analytical area were low, coming primarily from fume hoods and the ventilation duct. Typical levels were said to be 0.1 mrem/hr to 2 mrem/hr, with a level of 2.9 mrem/hr being reported in the Analytical Aisle in May of 2005 (WVDP 2005).

A3.1.2 <u>Removable Contamination Data</u>

On November 29, 1966, particulate activity from the PMC leaked into the analytical chemistry laboratories resulting in "gross contamination of all laboratories." Cleanup took 4 days.

An inspection by the plant housekeeping committee on January 27, 1967, pointed out a Zone IV leak in the Analytical Aisle that was asserted to have been there for months.

In June 1969 a sample bottle exploded in the Alpha Lab causing removable contamination levels of up to 2E+07 dpm/100 cm² alpha. The report states, "No personnel internal exposure to contamination occurred" (Keely 1969d).

A4.0 CELL ACCESS AISLE

The Cell Access Aisle (CAA) was on the ground level north of Extraction Cells 2 and 3 and west of the UPC. It contained shield doors that provided access to Extraction Cells 2 and 3, the Liquid Waste Cell, and the UPC. The CAA served as an airlock when contact maintenance was being performed in these areas (WVDP 2005).

A4.1 RADIOLOGICAL CONDITIONS

A4.1.1 <u>Removable Contamination Data</u>

Smears from the CAA taken January 15, 1968, showed typical removable levels of 5,000 dpm/100 cm² alpha (Wenstrand 1968f).

In June 1968 the typical removable contamination in the CAA was said to remain at 800,000 dpm/100 cm² alpha (Keely 1968a). The same level is reported for July 1968 also (Keely 1968k).

In February 1969 smearable contamination in the CAA was reduced from 200,000 dpm/100 cm² "to a low Zone 3" (Keely 1969f).

A4.1.2 <u>Airborne Contamination Data</u>

The CAA became an airborne contamination area during January 1967 (Keely 1967d, p. 2).

A5.0 CELL CRANE ROOMS

The remotely operated cranes and power manipulators used in the PMC, CPC, and GPC required periodic maintenance. Access to this equipment was via crane rooms located at one end of each cell. A shield door separated the crane rooms from the adjoining process cells. The equipment was first remotely decontaminated using spray systems before contact maintenance was performed in the

Page 11 of 52

crane rooms. Rubber gloves and mats were sometimes used to reduce beta exposures in these areas (NFS 1976).

A5.1 IMPACT OF THE THOREX CAMPAIGN ON AIRBORNE ACTIVITY LEVELS IN THE CELL CRANE ROOMS

In November 1968 airborne activity in the cell crane rooms was noted to be increasing due to alphaemitting thorium daughters from processing of thorium-uranium fuel from Indian Point 1. NFS developed methods to correct count data to determine the concentration of the long-lived alpha emitters (Keely 1968f). By December 1968 airborne activity in the cell crane rooms was said to remain "at maximum levels" (1,000 MPC) during Con-Ed (Indian Point 1) Core A processing "because of short-lived Thoron decay product." Occasional water fogging was used to reduce airborne levels for entries (Keely 1969a). In February 1969 the airborne activity in the crane rooms "remains at maximum levels" (1,000 MPC) "as thorium contamination in cells still provides a source for short-lived alpha-emitting daughters." The maximum concentration during the month was 50,000 MPC in the CCR (Keely 1969f).

A5.2 GENERAL PURPOSE CELL CRANE ROOM AND EXTENSION

The GCR was directly west of the GPC on the same level (below grade). In 1971 the GCR was lengthened to accommodate storage of the crane and the power manipulator. This area is referred to as the GCR Extension.

The GCR was used for contact maintenance work on the GPC crane, the GPC power manipulator, and the mechanism for the door between the cell and the GCR. This equipment would typically be decontaminated before maintenance activities (WVNSC 1994). Water would reportedly infiltrate the area on occasion during heavy rains (WVDP 2005).

In 2001 the GCR was used by the WVDP to support clean-up activities in the GPC (WVDP 2005).

A5.2.1 <u>Radiological Conditions</u>

A5.2.2 External Exposure Data

During operations, the typical and maximum exposure rates observed in the GCR before decontamination were 8 R/hr and 25 R/hr, respectively (NFS 1976).

In 1999, the general area dose rate in the GCR was approximately 100 mrem/hr, except for the south side, which showed approximately 140 mrem/hr. The highest level measured was 2,200 mrem/hr on the floor near the sump (WVDP 2005).

In 2002 the general dose rate in the GCR extension was in the range of 15 mrem/hr to 30 mrem/hr (WVDP 2005).

Page 12 of 52

A5.2.3 <u>Removable Contamination Data</u>

A smear survey of the GCR airlock on February 24, 1968, showed removable beta levels ranging from 11,000 dpm/100 cm² to 200,000 dpm/100 cm² (Wenstrand 1968e, p. 3).

Removable contamination surveys in the GCR in 1999 and 2000 showed levels up to 28,000 dpm/100 cm^2 alpha and 1.25E+6 dpm/100 cm^2 beta (WVDP 2005).

A5.2.4 <u>Airborne Contamination Data</u>

In January 1968 airborne activity in the GCR exceeded 1000 MPC on 3 successive days (January 23 to 25). The maximum concentration during this time was 30,000 MPC, or 6E-08 μ Ci/cm³ alpha (Wenstrand 1968e, p. 2).

On February 6, 1968, airborne activity in the GCR was 9.4E-11 μ Ci/cm³ alpha and 1.2E-8 μ Ci/cm³ beta (Wenstrand 1968e, p. 3).

In June 1968 airborne activity in the GCR remained above 1000 MPC for 3 days, preventing entry (Keely 1968a). (1000 MPC was NFS' limit for supplied air respiratory protection.)

A5.3 PROCESS MECHANICAL CELL CRANE ROOM

Access to the PMCR, which was on the 114.5-ft elevation of the plant, was via a hatch in the ceiling of the MRR below.

A5.3.1 External Exposure Data

During operations, the typical and maximum exposure rates observed in the PMCR before decontamination were 7 R/hr and 20 R/hr, respectively (NFS 1976).

In 2003 the general area dose rate in the PMCR ranged from 45 mrem/hr to 100 mrem/hr 3 ft above the floor (WVDP 2005).

A5.3.2 <u>Removable Contamination Data</u>

On February 13, 1968, removable beta contamination in the PMCR airlock ranged from 16,000 dpm/100 cm² to 600,000 dpm/100 cm² (Wenstrand 1968e, p. 3).

In 2003 removable contamination on the PMCR door hoist mechanism was up to 14,000 dpm/100 cm² alpha and 263,000 dpm/100 cm² beta. No data were available for the Crane Room itself, but the levels were expected to be high (WVDP 2005).

A5.3.3 <u>Airborne Contamination Data</u>

In February 1968 "typical" airborne activity in the PMCR was 6.6E-7 μ Ci/cm³ beta and 8.2E-10 μ Ci/cm³ alpha (Wenstrand 1968e, p. 2).

Page 13 of 52

A5.4 CHEMICAL PROCESS CELL CRANE ROOM

The CCR was at the north end of the CPC oriented 90 degrees to its west wall. It was two levels above the ground level of the CPC on the 131-ft elevation.

A5.4.1 <u>External Exposure Data</u>

During operations, the typical and maximum exposure rates observed in the CCR before decontamination were 3 R/hr and 6 R/hr, respectively (NFS 1976).

A5.4.2 <u>Removable Contamination Data</u>

On February 13, 1968, typical removable beta contamination in the CCR airlock ranged from 120,000 dpm/100 cm² to 400,000 dpm/100 cm² (Wenstrand 1968e, p. 3).

A5.4.3 Airborne Contamination Data

On February 23, 1968, airborne activity in the CCR was $1.5E-10 \ \mu \text{Ci/cm}^3$ alpha and $7.2E-7 \ \mu \text{Ci/cm}^3$ beta (Wenstrand 1968e, p. 3).

During February 1969 the concentration of thoron decay progeny in the CCR reached a maximum of 50,000 MPC (Keely 1969f). This was despite processing of thorium fuel from Indian Point Unit 1 having been completed on January 20, 1969.

A6.0 CHEMICAL OPERATING AISLE AND CHEMICAL VIEWING AISLE

The COA was east of the CPC on the 114.5-ft elevation, between the CPC and the PMC. The Chemical Viewing Aisle (CVA) was west of the CPC, between it and the 2nd floor offices in the Office Building.

The COA contained Sampling Station 1-C, which was used to remotely sample the process vessels in the CPC.

A6.1 RADIOLOGICAL CONDITIONS

A6.1.1 <u>External Exposure Data</u>

The COA contained a high radiation area caused by backup of solution in a steam line (Runion 1968, p. 16 of Action Plan - Part 2).

A July 27, 1972, summary of plant decontamination activities said radiation levels in the COA had been reduced through various decontamination efforts, both in the COA and in the extraction cells. Remaining sources of radiation were contamination on the floor and residual activity in piping and instrument lines. A steam line was said still to require heavy shielding and should be replaced to reduce radiation levels further. The report also mentions exposure rates in the CVA originating from the Southwest Stairwell have not changed from a previous survey in March 1972 (Wenstrand 1972d, p. 2).

Page 14 of 52

A6.1.2 <u>Removable Contamination Data</u>

Contamination would be carried into Sampling Station 1-C from the manipulator used to perform the remote sampling. This contamination was said to be limited to the immediate vicinity of the sampling station (Runion 1968, p. 16 of Action Plan - Part 2).

A7.0 CHEMICAL PROCESS CELL

The CPC is where the leaching (dissolving) process was performed on small pieces of fuel following mechanical segmentation in the PMC. The CPC contained two 4,000-L dissolvers. The dissolved fuel was chemically adjusted as necessary in the CPC to create the feed solution for the solvent extraction process carried out in the extraction cells.

A7.1 RADIOLOGICAL CONDITIONS

The CPC was never a routinely occupied area.

In May 1968 a remote survey just inside the CPC showed 220 R/hr. (Keely 1968e). In 1981 the exposure rate in the CPC was said to range from 12 R/hr to 32 R/hr (Golden, Frank, and Prina 1982).

A8.0 CONTROL ROOM

The Control Room was located on the fourth floor of the processing plant on the 144-ft elevation. It was used for the monitoring and control of plant processes. Adjacent to the Control Room were the Control Room Office and an area containing water distillation equipment.

A8.1 RADIOLOGICAL CONDITIONS

There were two chronic sources of external personnel exposure in the Control Room:

- The plant's main ventilation duct
- The recovered acid storage tanks in the Hot Acid Cell

A8.1.1 <u>External Exposure Data</u>

In January 1967 exposure rates in the Control Room were 10 mR/hr to 15 mR/hr due to activity in the ventilation duct (between the air washer and the stack) (Keely 1967d, p. 3).

On February 26, 1968, the exposure rate in the Control Room ranged from 1 mR/hr to 5 mR/hr (Wenstrand 1968e, p. 2).

Exposure rates in the Control Room increased from 2 mR/hr to 10 mR/hr in June 1969 (Keely 1969d). The exposure rate dropped back to 2.5 mR/hr in July after flushing of the ventilation duct (Keely 1969e).

Page 15 of 52

The July 27, 1972, summary of plant decontamination activities says reduced activity in the ventilation duct (post shutdown) resulted in "some reduction" of radiation levels in the Control Room, however, a spill in the northwest corner was said to have increased levels in that area (Wenstrand 1972d, p. 3).

NFS (1976) says the exposure rate in the Control Room from radioactivity in the ventilation ducting was typically 5 mR/hr to 10 mR/hr.

In May of 2005 dose rates in the Control Room area were generally less than 1 mrem/hr with a high of 1.4 mrem/hr (WVDP 2005).

A9.0 EQUIPMENT DECONTAMINATION ROOM AND EQUIPMENT DECONTAMINATION ROOM VIEWING AISLE

The EDR was on the ground level in the northwest corner of the process building, adjacent to the CPC and the Scrap Removal (SR) area. It contained a decontamination pool known as the "soaking pit" and equipment for decontamination of large vessels and equipment.

A9.1 RADIOLOGICAL CONDITIONS

A9.1.1 External Exposure Data

The general area exposure rate in the EDR in the first quarter of 1968 was 30 mR/hr to 40 mR/hr. Extremity dose rates were estimated at 590 mrad/hr to 650 mrad/hr (Urbon 1968b).

A9.1.2 <u>Removable Contamination Data</u>

Removable beta contamination in the EDR ranged up to 2.1E+06 dpm/100 cm² during the week of February 12, 1968 (Wenstrand 1968e, p. 3).

In September 1968 the EDR was reduced to "Zone 3" levels for removable contamination during the month (meaning it was Zone IV previously) (Keely 1968c).

A9.1.3 <u>Airborne Contamination Data</u>

Airborne activity in the EDR exceeded 1,000 MPC on one sample during March 1968 (Wenstrand 1968b).

A10.0 EXTRACTION AND PRODUCT PURIFICATION CELLS

Solvent extraction was carried out in a series of four cells: Extraction Cells 1 to 3 (XC1 to XC3), and the Product Purification Cell (PPC). The four cells were approximately 60 ft high each, so they passed through every elevation of the process building from ground level up to the 160-ft elevation. The cells contained extraction columns and evaporators.

The first two partition cycles, separation of uranium and plutonium from fission products, followed by separation of the plutonium from the uranium, were carried out in XC1. The final partition cycle and first uranium and plutonium extraction cycles were conducted in XC2. The second (final) plutonium

Page 16 of 52

and uranium extraction cycles and cleanup were performed in XC3. Final purification of plutonium and uranium nitrate process streams was performed in the PPC. Uranium was processed on the north side of the PPC and plutonium on the south side.

Sometimes the plant records will contain references to the Plutonium Purification Cell or just the Plutonium Cell. These are references to the south (plutonium) side of the PPC.

A10.1 RADIOLOGICAL CONDITIONS

The extraction cells presented both internal and external radiation exposure hazards from high airborne contamination levels and high dose rates. The PPC was subject to "significant" spills of radioactive liquids including one that contaminated the south wall of the south (plutonium) side to a height of 35 ft (WVDP 2005). During the operations era, entries into the PPC would cause airflow reversal issues on other levels of the plant, resulting in area contamination.

A10.1.1 External Exposure Data

Surveys in XC3 on February 29, 1968, showed working exposure rates from 300 mR/hr to 500 mR/hr, with a localized reading of 5 R/hr at 12 in. from a particular component (Wenstrand 1968e, p. 2).

In October 1969 a survey at the entrance to XC2 showed a whole-body exposure rate of 5 R/hr.

A manned entry was made into XC1 on June 29, 1972, following water flush activities. A maximum exposure rate of 50 R/hr was indicated near tank 4D-1 (WVNSC 1994). Several more entries were made into XC1 in July 1972, identifying exposure rates up to 20 R/hr at Tank 4-D-1 (Morrow 1972c). A survey in XC1 on February 21, 1973, found exposure rates 30 R/hr to 50 R/hr at the second stair landing and 10 R/hr to 50 R/hr at the first landing (WVNSC 1994).

Decontamination efforts in XC2 in May 1972 reduced exposure rates from the floor from 100 R/hr to 3 R/hr (Wenstrand 1972g).

The contamination on the south wall of the south side of the PPC read up to 53 mrem/hr as of 2003. The dose rate on the north side ranges from 1 mrem/hr to 3 mrem/hr (WVDP 2005).

A10.1.2 <u>Removable Contamination Data</u>

On February 29, 1968, removable alpha contamination in XC3 ranged from 1.5E+06 dpm/100 cm² to 6.5E+06 dpm/100 cm². Removable beta ranged from 3.5E+06 dpm/100 cm² to 6.4E+06 dpm/100 cm² (Wenstrand 1968e, p. 3).

A survey in 1986 showed a maximum of 400,000 dpm/100 cm² removable alpha on the floor of the north side of the PPC before application of strippable coating. Levels on the walls of the north side showed a maximum of 6,700 dpm/100 cm² removable alpha. Removable levels in the PPC remained high as of 2003.

Page 17 of 52

A10.1.3 Airborne Contamination Data

Air samples from the PPC showed concentrations of 2.0E-9 μ Ci/cm³ alpha on February 23, 1968, and 6.7E-11 μ Ci/cm³ alpha on February 26, 1968 (Wenstrand 1968e, p. 2).

In April 1968 modification work in the PPC (plutonium side) had to be interrupted on several occasions due to excessive airborne activity levels (>1,000 MPC). Smearable contamination reached 5E+06 dpm/100 cm² alpha (Keely 1968j). On April 19, 1968, the concentration in the PPC reached 5000 MPC (Author unknown 1968).

Airborne activity in the PPC reached 30,000 MPC during an entry on October 30, 1968. Personnel had to be evacuated until remote decontamination reduced the level to 1000 MPC (Keely 1968d).

An entry was made into the PPC in May 1969 after an isotopic evaluation showed the plutonium fraction of the airborne contamination was 4% before cell entry, 30% after resin dump, and 7% at completion. Entry had been prevented at first when an assumption of 100% plutonium for the alpha in air meant the concentration exceeded limits for supplied air respiratory protection (Keely 1969c, p. 1).

A November 11, 1971, memorandum alludes to the problems of airborne plutonium levels in the PPC and that workers have to wait for it to settle before making entries. Surface contamination and resuspension are also issues (Heacker 1971).

A11.0 EXTRACTION CHEMICAL ROOM

The XCR was above the extraction cells on the 160-ft elevation of the plant. It is where chemical solutions for the solvent extraction process were prepared.

A11.1 RADIOLOGICAL CONDITIONS

Some steps of the extraction chemical makeup process made use of acid from the acid recovery system. High exposure rates were therefore an issue. In addition, the XCR was chronically contaminated from leaks, spills, and equipment maintenance or replacement activities.

A11.1.1 <u>External Exposure Data</u>

The typical exposure rate in the XCR during the month of February 1968 ranged from 2.5 mR/hr to 500 mR/hr (Wenstrand 1968e, p. 2).

Dose rates of 50 R/hr were measured in the vicinity of the XCR in December 1971. The source was recovered acid in a tank (Wenstrand 1972h).

The July 27, 1972, summary of plant decontamination activities says flushing of tanks and removal of contaminated concrete in the XCR had reduced radiation levels by a factor of 10 to 100. The principal remaining radiation source was a tank reading 20 mR/hr to 30 mR/hr at contact. This tank read 1 R/hr to 2 R/hr before decontamination (Wenstrand 1972d, p. 3).

Page 18 of 52

A11.1.2 <u>Removable Contamination Data</u>

Removable beta under the tanks in the XCR ranged from 21,000 dpm/100 cm² to 240,000 dpm/100 cm² on January 22, 1968 (Wenstrand 1968f, p. 3).

Smearable contamination in the XCR area was well into Zone 4 levels in December 1971 (Wenstrand 1972h).

A12.0 EXTRACTION SAMPLE AISLE AND PROCESS SAMPLE CELL 2

The XSA was located on the 131-ft elevation of the plant, which was known as the analytical level. The XSA was adjacent to the north walls of the four extraction cells, between the cells and the laboratories. It included PSC-2, which was equipped with gloveboxes and sampling stations for sampling the adjacent extraction cells. The gloveboxes were removed in 1986 (WVDP 2005).

A12.1 RADIOLOGICAL CONDITIONS

The XSA contained two sample stations that suffered from contamination problems purported to be from insufficient bagging and airflow reversals caused by entries into the PPC (Runion 1968, p. 14 of Action Plan - Part 2). The contamination problems from entries into the PPC were such a problem that, as of early 1968, NFS required the XSA to be cleared of personnel and the door locked before a PPC entry was made. Subsequently, the XSA had to be surveyed once work in the PPC was completed (Runion 1968, p. 15 of Action Plan - Part 2). At the time they were enacted (early 1968), these measures were intended to be temporary until the sampling stations and gloveboxes could be improved to mitigate the contamination problems.

A12.1.1 <u>Removable Contamination Data</u>

General removable alpha levels in the XSA ranged from 5,000 dpm/100 cm² to 10,000 dpm/100 cm² on November 20, 1967.

A12.1.2 Airborne Contamination Data

In October 1967 air samples "taken on each shift" from the XSA and PSC-1 showed long-lived airborne alpha concentrations of 2E-12 μ Ci/cm³ and 5.4E-11 μ Ci/cm³ (Wenstrand 1967d).

Airborne activity levels rose to MPC in the XSA during a shutdown of the ventilation system following the filter failure incident on September 4, 1968 (Keely 1968c).

A13.0 FUEL RECEIVING AND STORAGE

The FRS facility was used to handle and decontaminate shipping casks for nuclear fuel and to move fuel using service crane bridges. It consisted of the fuel SP, the cask receiving area, the cask decontamination area (pit), and the pool water treatment area. Fuel was transferred from the FRS to the PMC via a transfer tunnel in the southwest corner of the SP.

Page 19 of 52

Other facilities associated with the FRS were a radioactive waste processing building (known as the Hittman Building) and the resin pit.

The radioactive waste processing building was located in a yard area north of the FRS. It was used for dewatering and storage of filter media from FRS pool cleanup systems and ion exchange resins. Spent resin was dewatered and stored in High Integrity Containers located 50 ft north of the FRS Building (WVDP 2005).

The resin pit was an in-ground concrete vault located outside the southeast corner of the FRS Building. Spent filter media and ion exchange resin from the pool water treatment area were flushed to a drum in the pit. A drain line went from the pit to the Interceptor system.

Fuel was stored in the FRS pool until 2001. In 2002 and 2003 the pool was drained, empty canisters and storage racks were removed, and the SP and Cask Unloading Pool (CUP) were decontaminated and sealed (WVDP 2005).

A13.1.1 <u>Radiological Conditions</u>

Receipt and storage of ruptured fuel assemblies resulted in significant buildup of fission products in the SP. The radioactivity concentration in the pool eventually reached 0.1 μ Ci/cm³, prompting the installation of auxiliary cleanup systems to augment the primary system. However, even with the auxiliary system the contamination level of the pool water could only be reduced to 0.01 μ Ci/cm³. Hence, significant levels of contamination would be found "Whenever items were removed from the pool." Radiation levels would reach 20 mR/hr to 100 mR/hr during routine operations in some areas of the FRS (NFS 1976).

Personnel exposures in the FRS area would also result from preparation of casks for loading into the pool. Workers were exposed to the surface dose rates from the casks while they were prepared for immersion (NFS 1976). Incoming casks could have a contact dose rate up to 200 mR/hr (limit per shipping regulations). Personnel were routinely in close proximity to the casks while preparing them for immersion into the pool and unloading of the fuel (Runion 1968, p. 1 of Action Plan - Part 2). FRS workers removing and cleaning fuel shipping cask internals worked in exposure rates up to 300 mR/hr (Loud 1965b, p. 2). The average collective dose for FRS workers over 1970 and 1971 was 250 person-rem. A May 12, 1975, Nuclear Insurance Survey report by Johnson & Higgins states the highest level of personnel exposure at West Valley was around 400 mrem/quarter received by the fuel unloading operators (Johnson & Higgins 1975).

Liquids would be spilled into work areas in the FRS, resulting in airborne contamination and personnel intakes. There was also potential for exposure to fission gases released when cask lids were removed (in the pool) (Bailey 1990). Other routes of personnel exposure in the FRS were handling of contaminated tools, drumming of filter and demineralizer media from the pool water treatment system, and shipping cask decontamination operations. There were multiple instances of personnel exposures associated with flushing of shipping casks.

Underwater tools and the crane cables and blocks allowed highly contaminated pool water to drip onto the service bridges. Casks were contaminated to "several hundred thousand" dpm/100 cm² beta

Page 20 of 52

from the pool water upon being removed from the pool. Unloaded casks were moved from the SP to the decontamination pit, where they were cleaned using spray and scrub techniques to return them to acceptable contamination levels for shipping. The FRS service crane bridges were repeatedly contaminated from FRS operations. The bridges were isolated and controlled via rope and step-off pads (Runion 1968, p. 1 of Action Plan - Part 2).

A13.1.2 Pool Water Concentration Data

Table A-1 shows gross beta and gross alpha concentration data for the FRS CUP and SP for December 1965.

Table A-1. Gross beta and gross alpha concentration data for the CUP and SP, December 1965.

	Concentration (µCi/cm ³)		
Pool	Gross beta	Gross alpha	
CUP	3.1E-5	2.5E-9	
SP	2.8E-5	4.8E-9	

Table A-2 shows concentration data for the CUP and SP for January to June 1966. Data are given for soluble gross beta, gross alpha and tritium; and insoluble gross beta and gross alpha.

Table A-2. Ra	dioactivity concentratior	data for the CUP	and SP, Januar	y to June 1966.
---------------	---------------------------	------------------	----------------	-----------------

		Soluble (µCi/cm ³)		Insoluble	e (µCi/cm³)	
Date	Pool	Gross beta	Gross alpha	Tritium	Gross beta	Gross alpha
January 1966	CUP	8.0E-5	1.6E-7	6.5E-7	8.8E-7	1.0E-8
	SP	8.8E-5	3.0E-8	5.0E-6	2.0E-6	1.0E-8
February 1966	CUP	2.7E-5	< 1E-9	6.0E-6	1.9E-6	2.6E-9
	SP	2.8E-5	3.7E-9	9.5E-6	1.4E-6	9.4E-9
March 1966	CUP	5.9E-5	3.3E-7	3.9E-6	5.5E-6	< 1E-8
	SP	6.8E-5	< 1E-8	4.3E-6	2.0E-6	< 1E-8
April 1966	CUP	4E-5	1E-8	1E-5	3E-6	7E-10
-	SP	5E-5	< 1E-8	9E-6	3E-6	4E-9
May 1966	CUP	2E-4	6E-8	1E-4	6E-6	9E-9
	SP	2E-4	5E-8	1E-4	5E-6	1E-9
June 1966	CUP	1E-4	< 1E-8	4E-4	4E-5	9E-9
	SP	2E-4	< 1E-8	3E-3	1E-5	6E-10

For the February 1966 samples, "Gamma analysis showed that Co-60, Co-58, and Cs-137 are the principal contaminants" (Loud 1966b, p. 2).

Table A-3 shows gross beta concentration data for the CUP and SP over the period September 1965 to October 1969. Values reported for a month (rather than a specific date) are typical or representative values. Values are for the SP unless otherwise specified.

After reprocessing operations ceased in 1972, the FRS pool was drained and cleaned. After refilling, the contamination level of the pool water was reduced to 5E-3 µCi/cm³ (NFS 1976).

Page 21 of 52

Table A-3. Gross beta concentration data for the CUP and SP, September 1965 to October 1969.

	Gross beta	
	concentration	
Date	(µCi/cc)	Remarks
September 1965	1.1E-04	CUP
September 1965	7.8E-05	SP
September 16, 1965	1.6E-04	CUP concentration due to ruptured fuel assembly. Previously was 5.4E-6 µCi/cc.
October 1965	3.1E-04	CUP
October 1965	2.8E-04	SP
November 1965	1.4E-04	"No detectable alpha"
August 1966	2.0E-03	Small cracks noted in pool, causing contamination on nearby floor areas.
July 1, 1967	4.0E-03	Maximum. Low was 9E-5 µCi/cc
September 6, 1967	7.5E-03	
October 8, 1967	1.8E-02	
March 1969	1.0E-01	Waiting for removal of ruptured N Reactor fuel before attempting cleanup.
April 1969	1.0E-01	
May 1969	1.2E-01	
June 1969	1.2E-01	
July 1969	8.0E-02	
August 1969	1.7E-02	
September 1969	8.0E-03	
October 1969	4.0E-03	

On May 11, 1972, isotopic measurements were made on FRS pool water to examine the effectiveness of cleanup systems. Concentration data were given for ¹³⁴Cs, ¹³⁷Cs, ¹⁰⁶Ru/Rh, ¹⁴⁴Ce/Pr, and ¹²⁵Sb (Jaroszeski 1972).

A13.1.3 External Exposure Data

Table A-4 shows exposure rates over the top of the FRS pools for November 1965 to May 1969.

Table A-4. Exposure rates over the top of the FRS pools, November 1965 to May 1969.

, ,	Exposure rate	
Date	(mR/hr)	Remarks
November 1965	0.2	
January 1966	0.1 to 0.15	
February 1966	0.1 to 0.15	Seven fuel casks were received during the month.
March 1966	0.1 to 0.15	Ten fuel casks were received during the month.
April 1966	0.2	Fifteen fuel casks were received during the month.
May 1966	0.2	
June 1966	0.4	
May 1969	30 whole body	Average working level on bridges above pool.
	100 skin	

In December 1965 the FRS pool demineralizer was placed in service "for a few days" and showed an exposure rate "at the side" of 1.5 R/hr (Loud 1966a).

In September 1969 an expansion box on a fuel cask received read 5 R/hr on contact. Investigation found it contained high-activity primary coolant. Attempts to clean up the coolant using an ion

Page 22 of 52

exchange unit were hampered when the unit read 350 R/hr after 3 hours of operation (Wenstrand 1969a).

On December 5, 1969, a line venting the cask leaked coolant onto the concrete outside the CUP, which resulted in a high radiation area that persisted for days. The contaminated concrete had to be removed and lead fill added (Duckworth 1970).

In November 1971 shrouds were removed from the FRS pool resulting in exposure rates up to 40 R/hr. Shielding was provided for the FRS crane operator, reducing his work area exposure rate to 300 mR/hr (Wenstrand 1971c, p. 1).

In June 1972 decontamination efforts on the CUP reduced exposure rates to approximately 5 R/hr (Wenstrand 1972i).

During October 1972 exposure rates of 20 R/hr were encountered while handling spent resin in the FRS. This is referred to as an "area radiation dose rate"; that is, it was not a hot spot (Morrow 1972b).

During November 1972 exposure rates of 30 R/hr were encountered during removal of wastes from the FRS (Morrow 1972d).

Representative exposure rates for the FRS in 2002 and 2003 were (WVDP 2005).

- SP walls and floor = 6.7 mrem/hr to 8.5 mrem/hr.
- CUP walls and floor = 25.7 mrem/hr to 500 mrem/hr.
- Water treatment area = 5.4 mrem/hr on face of shield wall; 195 mrem/hr on middle of demineralizer column.
- Cask Decontamination Area = 0.17 mrem/hr in stall; 24 mrem/hr in pit sump.
- Hittman Building = 0.5 mrem/hr to 0.8 mrem/hr.
- Top of resin pit = 18 mrem/hr.
- Bottom of FRS pool transfer tunnel = 2,000 mrem/hr.

A13.1.4 <u>Removable Contamination Data</u>

Smears around the FRS Decontamination Pit showed removable levels from 3,000 dpm/100 cm² to 8E+06 dpm/100 cm² beta on 1/24/1968 (Wenstrand 1968f, p. 3).

Smearable contamination on an incoming cask was 1E+06 dpm/100 cm² beta in July 1968 (Keely 1968k).

Page 23 of 52

In September 1969 smearable contamination in excess of 50,000 dpm/100 cm² beta was found in the FRS rail track area (Wenstrand 1969a).

Smearable contamination on an incoming fuel cask showed a maximum of 7.5E+07 dpm/100 cm² April 1971. This is assumed to be removable beta contamination, though the reference does not explicitly say so (Wenstrand 1971f, p. 2).

NFS received fuel casks with removable contamination levels in excess of the 10 CFR Part 20 limit of 22,000 dpm/100 cm² five times between July 2 and November 7, 1974 (O'Reilly 1975, p. 1 of inspection report).

After the decontamination activities in 2002 to 2003, removable contamination levels in the FRS area were less than 2000 dpm/100 cm² alpha and 20,000 dpm/100 cm² beta (WVDP 2005).

A13.1.5 Airborne Contamination Data

There was high airborne beta activity in the FRS on December 20, 1966, attributed to removable activity in a drain (Keely 1967e).

April 1969: The "maximum weekly" long-lived air activity above the FRS pool for April 1969 was 4E-10 μ Ci/cm³ beta (Keely 1969g).

January 1972: airborne concentrations in the FRS have decreased by a factor of 10 due to the cleanup effort (Wenstrand 1972b).

A lid blew off a 55-gal drum during decanting of the FRS settling tank on May 15, 1974. Resulting airborne contamination levels were 1.56E-11 μ Ci/cm³ alpha and 2.66E-09 μ Ci/cm³ beta (G. 1974).

A14.0 GUARD HOUSE

The Guard House was the main point of entry to and exit from the plant, and where employee film badges were stored. It was also referred to as the Gate House.

A14.1 RADIOLOGICAL CONDITIONS

In August 1970 the AEC expressed concerned over exposure rates at the gatehouse. NFS said that while the exposure rates in that area were "higher than desired", they did not consider it to be an unrestricted area vis-à-vis 10 CFR Part 20. The only persons routinely in that area were the guards, whom were described as being "low in radiation exposure." NFS said radiation levels in that area would be "reduced to more desirable levels as soon as possible" (Duckworth 1970). The discussion pertains to the fact exposure rates at the Guard House exceeded 10 CFR Part 20 limits for an unrestricted area.

Page 24 of 52

A15.0 GENERAL OPERATING AISLE

The GOA was below grade on the north side of the GPC. It contains four shielded viewing windows that were used by workers operating manipulators and other equipment in the GPC.

A15.1 RADIOLOGICAL CONDITIONS

A15.1.1 Exposure Rate Data

A July 27, 1972, summary of plant decontamination activities says radiation levels in the GOA were reduced by a factor of two due to lower radiation levels in the HEV duct. It also says contamination around the west window was still causing a general area exposure rate of 20 mR/hr (Wenstrand 1972d).

The reported dose rate in the GOA as of 2005 was less than 1 mrem/hr (WVDP 2005).

A15.1.2 Airborne Contamination Data

The GOA was one of the areas that showed airborne contamination levels in excess of 40 MPC-hr during flushing of the plant ventilation system.

A16.0 GENERAL PURPOSE CELL

The GPC was 25 ft below the ground level of the plant, and ran perpendicular between the PMC and the CPC. The GPC served to transfer baskets containing 200 kg (design basis) of segmented fuel between the PMC and the CPC for dissolving. Afterward, they would be moved back into the GPC so the remaining cladding and fuel hardware could be packaged for transfer into the SR Area for disposal. The GPC would also be used for packaging of other process wastes and damaged equipment for transfer into the SR Area.

The GPC had three shielded viewing windows in its north wall, denoted east to west as GPC-A, -B, and -C (Vance 1986). The west window was a source of contamination into the GOA, which ran adjacent to the north wall of the GPC.

There was another cell on the other side of east wall of the GPC called the Miniature Cell. This cell was never used.

Vance (1986) says discussions with former employees indicated there had been a metal fire in the GPC during the operations era when a batch of leached cladding spontaneously ignited when it was dumped. It is not known specifically when this occurred. WVDP (2005) says three cladding fires occurred during operations.

A16.1 RADIOLOGICAL CONDITIONS

The GPC was never a routinely occupied area.

Page 25 of 52

A16.1.1 External Exposure Data

In 1986 dose rates 6 ft above the floor ranged from 40 rem/hr to 340 rem/hr. At 2 ft above the floor the dose rates ranged up to 650 rem/hr.

A characterization survey performed in November 2004 showed the following dose rates:

- 3 ft above the floor = 4 rem/hr to 200 rem/hr.
- 6 ft above the floor = 3 rem/hr to 45 rem/hr.
- 9 ft above the floor = 2 rem/hr to 32 rem/hr.

A16.1.2 <u>Removable Contamination Data</u>

Smear samples collected in 1986 showed removable ¹³⁷Cs up to 388 µCi/smear.

A17.0 HEAD END VENTILATION BUILDING AND CRANE ROOM

The HEV Building was located on the east side of the MSM Shop. It was built in 1970 to accommodate the HEV system. The HEV Building had two levels. The lower level housed filters, blowers, ductwork, and other equipment. The upper level contained a crane and filter change equipment. This area was often referred to as the HEV Crane Room. Like the main ventilation system, the HEV system could be operated on steam or electric power.

A17.1 RADIOLOGICAL CONDITIONS

A17.1.1 External Exposure Data

On October 12, 1971, extensive contamination was found in a surface water drainage ditch from the HEV area. Typical exposure rates ranged from 60 mR/hr to 100 mR/hr, and up to 150 mR/hr inside drains (Wenstrand 1971g).

In July 1972 decontamination of the floor and dock area of the HEV Crane Room reduced radiation levels in these areas by a factor of 10 to 12. Radiation fields from "shielding flaws at the sides of the HEV" still required shielding, though levels were lower due to less activity in the filters and decontamination of the filter chambers (Wenstrand 1972d, p. 2).

In 2002 dose rates from the HEV prefilters ranged up to 50 rem/hr. The roughing filters ranged up to 18 rem/hr and the first stage high-efficiency particulate air (HEPA) filter bank up to 2.3 rem/hr. Ductwork in the adjacent operating aisle ranged from 3 mrem/hr to 50 mrem/hr. Dose rates up to 61 mrem/hr were measured in the lower level of the HEV Building in May of 2005 (WVDP 2005).

A17.1.2 <u>Removable Contamination Data</u>

No specific information has been identified. The 2005 draft of the WVDP Decommissioning Plan says removable levels in the HEV Building "are expected to be significant" (WVDP 2005).

Page 26 of 52

A18.0 HOT ACID CELL

The Hot Acid Cell was located on top of the CPC at an elevation of 148 ft. It contained two storage tanks (7D-11 and 7D-12) for recovered acid. It also contained a pump in a niche.

A18.1 RADIOLOGICAL CONDITIONS

A18.1.1 External Exposure Data

On February 14, 1994, exposure rates of 5 mR/hr to 10 mR/hr were present near the floor and 10 mR/hr to 15 mR/hr at the base of the acid tanks (WVNSC 1994).

In 2001 dose rates inside the Hot Acid Cell ranged from 0.3 mrem/hr to 80 mrem/hr. Dose rates from piping, valves and the floor drain ranged from 5 mrem/hr to 60 mrem/hr (WVDP 2005).

A18.1.2 <u>Removable Survey Data</u>

A 1994 removable contamination survey showed levels up to 450 dpm/100 cm² alpha and 42,000 dpm/100 cm² beta (WVDP 2005).

A19.0 HOT SHOP

The Hot Shop was a portion of the "old maintenance shop adjacent to the new laundry" (Runion 1968, p. 7 of Action Plan - Part 2). The area was used for decontamination, repair, and maintenance of equipment such as MSMs and power manipulators. The Hot Shop was provided in 1967 to permit repair of contaminated equipment. A new Decontamination and MSM Repair Facility was under construction as of early 1968 with completion expected July 1 (Clark 1968b).

A19.1 RADIOLOGICAL CONDITIONS

Equipment was bagged before transfer to the Hot Shop, but maintenance activities there resulted in contamination of it and surrounding areas. Hot Shop personnel wore respiratory protection.

A19.1.1 External Exposure Data

On November 3, 1967, the Hot Shop showed a general background of 10 mR/hr to 20 mR/hr. Some manipulator parts read up to 21 rad/hr.

A19.1.2 <u>Removable Contamination Data</u>

Smears of the Hot Shop on January 22, 1968, showed removable beta levels of 240,000 dpm/100 cm^2 to 4E+06 dpm/100 cm^2 and alpha levels of 10,000 dpm/100 cm^2 to 12,000 dpm/100 cm^2 (Wenstrand 1968f, p. 3).

Typical removable beta contamination in the Hot Shop was 100,000 dpm/100 cm² on February 27, 1968 (Wenstrand 1968e, p. 3).

Page 27 of 52

Removable contamination increased above allowable limits in the Hot Shop on 3/3/1968 (Wenstrand 1968b, p. 2).

A20.0 INSTRUMENT SHOP/OLD INSTRUMENT SHOP

The Instrument Shop was located in the Ventilation Supply Room, which was east of the PMC on the 114.5-ft elevation. It was used for the repair of uncontaminated instruments until this function was relocated sometime in 1967. After this time the area was referred to as the Old Instrument Shop. The area itself was physically removed in 1985.

A20.1 RADIOLOGICAL CONDITIONS

A20.1.1 External Exposure Data

In January 1967 exposure rates in the Instrument Shop were 10 mR/hr to 40 mR/hr from activity in the ventilation duct (between the air washer and the stack) which passed adjacent to the area (Keely 1967d, p. 3).

A survey in the Old Instrument Shop on February 26, 1968, showed exposure rates from 250 mR/hr to 400 mR/hr (Wenstrand 1968e, p. 2).

As of 2005 dose rates adjacent to the ventilation duct in the Ventilation Supply Room ranged up to 7 mrem/hr (WVDP 2005).

A20.1.2 <u>Removable Contamination Levels</u>

Removable contamination in the Old Instrument Shop was reduced from "high Zone 4 levels to low Zone 3 levels" during the month of April 1969 (Keely 1969g). However, a leaking duct recontaminated the area back to Zone 4 levels the following month (Keely 1969c, p. 1).

A21.0 INTERCEPTOR AND NEW INTERCEPTOR

The original Interceptor was located within the plant security fence just east of the process building. Its purpose was to collect liquid wastes from floor drains, sink drains, blowdown from process water and steam, and cask wash water from the FRS. These liquids were collected in batches and analyzed before transfer to the lagoon system. Wastes were then stored in Lagoons 1 and 2 until they were processed in the Low-Level Waste Treatment (LLWT) Facility. Before May 1971, the wastewater went from Lagoon 2 to Lagoon 3 before being discharged to surface streams.

Potentially radioactive condensates in the processing plant were collected and sampled in batches before disposal. If the gross beta concentration exceeded 3E-07 μ Ci/cm³, the waste was transferred to the Interceptor system. Otherwise, it was discharged directly to surface streams. Secondary cooling water used in the High Level Waste Storage Facility and in the FRS cooler was also discharged directly to surface streams.

Page 28 of 52

A new Interceptor was installed by the WVDP in the late 1990s consisting of twin, open-top concrete storage tanks. The new Interceptor is located just east of the old one. The tanks are used to store radioactive liquids before treatment in the LLWT Facility (WVDP 2005).

In 2005 the old Interceptor was being used for storage of radioactive liquids that exceeded the effluent limit of 5E-03 μ Ci/cm³. Liquids can be transferred from the old Interceptor to the new Interceptor via steam jet (WVDP 2005).

A21.1 RADIOLOGICAL CONDITIONS

A21.1.1 <u>External Exposure Data</u>

Exposure rate surveys performed in August 2003 on the old Interceptor showed a range of 0.4 mR/hr at the top of the tank to 408 mR/hr near the bottom at a distance of 1 ft from the tank wall (WVDP 2005).

A valve in the new Interceptor valve pit showed 0.3 mR/hr in October 2003 (WVDP 2005).

A22.0 LAUNDRY

A new laundry facility went into operation in 1967 in an effort to lower workplace contamination experienced by laundry workers.

A22.1 RADIOLOGICAL CONDITIONS

A22.1.1 <u>External Exposure Data</u>

As of early 1968 clothing articles with dose rates up to 50 mR/hr could be sent to the plant laundry.

An AEC inspection report from 1972 summarizes external dose received by a laundry worker at West Valley between October 12, 1966, and January 19, 1972. His total whole-body dose over this period was 8.950 rem, and he had no quarterly dose in excess of 1.2 rem. The report states the worker's "extremity and skin exposure" over the 5.25 years was 11.7 rad. It is not known why the two were summed, if that was the case (Nelson 1973a, p. 14 of attachment). The whole-body dose averages to 426 mrem/quarter, or 1.7 rem/yr.

A22.1.2 <u>Removable Contamination Data</u>

Waste from the laundry facility backed up in June 1967, contaminating the First Aid Room to Zone IV levels (Keely 1967f).

A22.1.3 Airborne Contamination Data

On February 9, 1967, the airborne alpha activity in the laundry area increased "to levels requiring personnel to wear masks" (Keely 1967a, p. 1).

Page 29 of 52

As of early 1968 laundry personnel wore canister masks and worked under a hood flowing at "about 1,300 scfm" while sorting contaminated clothing before washing (Runion 1968, p. 6 of Action Plan - Part 2). The laundry room also contained a CAM (Clark 1968b).

A23.0 LOAD-IN FACILITY

The Load-in Facility (LIF) was built by the WVDP adjacent to the west wall of the EDR. It was built to make use of the EDR as the primary access for moving canisters and replacement equipment into the Vitrification Cell or the CPC (WVDP 2005).

The dose rate in the LIF is less than 0.1 mrem/hr (WVDP 2005).

A24.0 LOW LEVEL WASTE TREATMENT FACILITY

The LLWT facility began operating on May 24, 1971. It utilized ion exchange methods to remove cesium and strontium from liquid wastes collected by the Interceptor system. The effluent from the LLWT facility was stored in Lagoons 4 or 5. It would then be analyzed and transferred to Lagoon 3 for discharge to surface streams. If the analyses of wastes in Lagoons 4 or 5 exceeded concentration limits, the waste was recycled back to Lagoon 2. NFS (1976) says the LLWT facility removed "greater than 95% of the cesium and strontium" from liquid wastes.

A24.1 RADIOLOGICAL CONDITIONS

A24.1.1 <u>External Exposure Data</u>

The area around the LLWT facility's ion exchange beds read 30 mR/hr at contact and 5 mR/hr in the aisle shortly after it began operating in May 1971. Exposure rates from the first drums of sludge were 50 mR/hr contact 5 mR/hr at 3 ft (Wenstrand 1971d).

A25.0 LOW LEVEL WASTEWATER TREATMENT BUILDING

The Low Level Wastewater Treatment (LLW2) Building was built by the WVDP and put into service in 1998. Its purpose is to remove contaminants (⁹⁰Sr and ¹³⁷Cs primarily) from radioactive wastewater via ion exchange and filtration. It treats water from Lagoon 2 and groundwater from wells on the North Plateau (WVDP 2005).

Spent resin from the ion exchange modules is dewatered in a packaging area in the northeast end of the building. The liquid from the dewatering operation goes to a sump to be processed as wastewater. The spent resin is packaged and transferred out for storage and disposal (WVDP 2005).

Page 30 of 52

A25.1 RADIOLOGICAL CONDITIONS

A25.1.1 <u>External Exposure Data</u>

Survey data show contact readings on one of the ion exchange modules up to 11 mrem/hr. A 2003 survey of the sump exit piping showed 4 mrem/hr. General area dose rates were less than 1 mrem/hr in 2005 (WVDP 2005).

A25.1.2 Removable Contamination Data

Most removable contamination surveys do not show any detectable activity. A smear of the sump grating cover showed 1,815 dpm/100 cm² removable beta in 2003 (WVDP 2005).

A26.0 LOWER EXTRACTION AISLE

The LXA was immediately north of the extraction cells on the 114.5-ft elevation of the plant. It contained two PSCs with gloveboxes. The LXA was an operations and maintenance area that provided access to piping and instrumentation penetrations into the extraction cells and the UPC.

A26.1 RADIOLOGICAL CONDITIONS

As with numerous areas in the process building, the ventilation duct passing through the LXA was a chronic source of external personnel exposure.

A26.1.1 External Exposure Data

The July 27, 1972, summary of plant decontamination activities says the principal radiation sources in the LXA were the ventilation duct and ventilation washer (Wenstrand 1972d, p. 3).

In early 1968 the LXA had an area of elevated exposure rates (in excess of 100 mR/hr) due to backup in a steam supply line that supplied a jet in one of the process cells. Shielding was supposed to have been installed on the line by March 1, 1968 (Runion 1968, p. 11 of Action Plan - Part 2).

The exposure rate under the ventilation duct in the LXA was 200 mR/hr before it being flushed on October 3, 1969.

As of 2004 the general area dose rate in the LXA was typically 0.1 mrem/hr with higher levels present near ventilation ducts (WVDP 2005).

A27.0 LOWER WARM AISLE

The LWA was immediately adjacent to the extraction cells on the ground level. It contained shielded niches (concrete enclosures) for equipment such as air-operated pumps, valves, etc. that serviced the extraction cells. The LWA would become contaminated during replacement or repair of this equipment and from movement of contaminated filters from the OGBR through the LWA to the waste truck for disposal (Runion 1968, p. 9 of Action Plan - Part 2).

Page 31 of 52

General decontamination was performed on the LWA between 1972 and 1974. Additional cleanup and modifications (to support the WVDP) occurred in the early 1980s (WVDP 2005).

A27.1 RADIOLOGICAL CONDITIONS

A27.1.1 External Exposure Data

On November 7, 1967, a "leaking drain pipe" on the west wall of the LWA read 5 R/hr at 6 in. (Wenstrand 1967a).

DOG filters being stored in the LWA on March 29, 1968, were causing exposure rates from 1 R/hr to 50 R/hr in the aisle (Wenstrand 1968b).

In 1987 the dose rate in LWA Niche 1 ranged up to 2,700 mrem/hr. Rates for Niche 2 were up to 758 mrem/hr and up to 96 mrem/hr in Niche 3 (WVDP 2005).

Typical dose rates in the LWA (not in the niches) as of 2005 are 0.1 mrem/hr to 0.3 mrem/hr (WVDP 2005).

A27.1.2 Removable Contamination Data

Removable beta contamination in the LWA was 100,000 dpm/100 cm² to 600,000 dpm/100 cm² on November 9, 1967. Removable alpha was up to 18,000 dpm/100 cm².

On November 23, 1967, the LWA showed maximum levels of removable contamination on the floor of 750,000 dpm/100 cm² beta and 140,000 dpm/100 cm² alpha. Horizontal surfaces showed removable up to 1.8E+06 dpm/100 cm² beta and 4.5E+06 dpm/100 cm² alpha.

Removable contamination in the Product Packing and Shipping and LWA airlock ranged from 18,000 dpm/100 cm² to 6E+06 dpm/100 cm² beta on January 16, 1968. On January 20, 1968, the LWA showed removable levels in equipment niches of 500,000 dpm/100 cm² to 9E+06 dpm/100 cm² beta and 1E+06 dpm/100 cm² to 9E+06 dpm/100 cm² alpha (Wenstrand 1968f, p. 2).

In May 1968 "aggressive" decontamination efforts reduced removable beta contamination levels to Zone 3 limits in both the UWA and LWA. Removable alpha contamination in the LWA was still at Zone 4 levels (Keely 1968e).

A spill on June 30, 1969, resulted in removable contamination levels in the LWA of 1E+06 dpm/100 cm² (Keely 1969d).

A27.1.3 Airborne Contamination Data

In April 1968 the Plutonium Cell and the LWA had to be "fogged" with water to reduce airborne radioactivity levels to less than 1000 MPC so entry could be made using supplied air (Keely 1968j). The excessive airborne concentration in the LWA resulted from a filter change on April 4, 1968 (Author unknown 1968, p. 2).

Page 32 of 52

A28.0 MAIN OFFICE BUILDING

The main Office Building served as the main entrance to the processing plant. It had three floors and was located west of the CPC. Between the Office Building and the CPC was the Chemical Viewing Aisle.

The first floor of the Office Building included the Hot Lobby and locker room areas. The Hot Lobby was a dressout area where workers donned basic protective clothing. It served as a buffer area between the Office Building and the processing plant. The office building had another lobby area that was differentiated from the Hot Lobby, i.e., they were separate areas.

A28.1 RADIOLOGICAL CONDITIONS

The ventilation and acid recovery systems were chronic sources of external exposure in the office building. Contamination in the Southwest Stairwell was also a contributor.

A28.1.1 <u>External Exposure Data</u>

Radiation levels in the third floor offices increased to 5 mR/hr in September 1966. Personnel were moved to the Annex Building to decrease their exposure (Keely 1966).

"Background in the Control Room and Office areas sometimes rose to 10 mR/hr" from activity in the recovered acid storage tanks in the Hot Acid Cell (NFS 1976).

The July 27, 1972, summary of plant decontamination activities says radioactive piping was removed from the northwest corner of the OGA, resulting in "some reduction" in radiation levels in the 3rd floor office building. The report also says radiation levels in the Office Building originating from the Southwest Stairwell have not changed from a previous survey in March 1972 (Wenstrand 1972d, p. 2).

Most areas in the Office Building showed dose rates less than 32 µrem/hr in April and May of 2005. A maximum of 1.4 mrem/hr was measured on the first floor (WVDP 2005).

A28.1.2 <u>Removable Contamination Data</u>

The OGA and Southwest Stairwell were contaminated to Zone 4 levels by an acid leak in the OGA on October 23, 1969. Contamination was spread to the Office Building and Chemical Viewing Aisle (Wenstrand 1969b). The spill also contaminated an area beneath the floor of the men's shower room on the ground level (WVDP 2005).

A29.0 MAINTENANCE SHOP AND WAREHOUSE

These facilities were separate from the process building. Maintenance or repair operations on contaminated components were sometimes carried out in the Maintenance Shop. However, this was not routinely a radiological area. No indication of radioactive material being present in the warehouse has been found in references reviewed to date.

Page 33 of 52

A29.1 RADIOLOGICAL CONDITIONS

A temporary contamination zone was established in the Maintenance Shop in March 1968 for the repair of a PAR Manipulator (Wenstrand 1968b).

An AEC inspector looked at the "new" Maintenance Building and the Warehouse during an October 1973 inspection. No RAM was found in the warehouse. Two fuel canisters were found in the maintenance building, one of which appeared to have been modified by having a new section welded on. The contact exposure rate was 1 mR/hr (gross). Smear surveys and nasal swabs had been collected during the welding (Nelson 1973b, p. 2 of enclosure 2).

A30.0 MANIPULATOR REPAIR ROOM

The MRR was located north of the MOA and below the PMCR on the ground (100-ft) level of the plant. A ceiling hatch provided access to the PMCR for repair and adjustment of the power manipulator used in the PMC. The manipulator would be positioned in the Crane Room so its hand, wrist, and arm could be extended through the hatch into the MRR. This allowed it to be repaired without workers being directly exposed to the radiation in the Crane Room or from the manipulator's bridge.

A30.1 RADIOLOGICAL CONDITIONS

A30.1.1 External Exposure Data

Exposure rates in the MRR were significant during operations. The shielding of the MRR was found to be inadequate, causing exposure rates up to 50 mR/hr in adjacent areas.

In 2003 the dose rate in the MRR ranged from 10 mrem/hr to 12 mrem/hr (WVDP 2005).

A30.1.2 <u>Removable Contamination Data</u>

On February 13, 1968, the MRR airlock showed removable beta contamination ranging from 76,000 dpm/100 cm² to 900,000 dpm/100 cm² (Wenstrand 1968e, p. 2).

Removable contamination up to 4500 dpm/100 cm² alpha and 112,500 dpm/100 cm² beta were measured in the MRR in 2003 (WVDP 2005).

A31.0 MECHANICAL OPERATING AISLE (NORTH, EAST AND WEST)

Head-end mechanical operations were directed from operating aisles adjacent to the shielded viewing windows of the hot cells. The MOA surrounded three sides of the PMC on the ground (100 ft) level of the plant. The two sections of the MOA that ran adjacent to the east and west sides of the PMC were therefore often referred to independently as the East Mechanical Operating Aisle (EMOA) and the West Mechanical Operating Aisle (WMOA). Occasionally there will also be a reference to the north MOA, usually in relation to the MSM Repair Shop that was north of the PMC (i.e., on the other side of the MOA).

Page 34 of 52

A31.1 RADIOLOGICAL CONDITIONS

A31.1.1 External Exposure Data

An inspection by the plant housekeeping committee on January 27, 1967, found the plant to be in a "deplorable" condition. Radiological items noted in the inspection report include smoking in the WMOA, which apparently was not prohibited at the time, and an MSM in the aisle with fingers reading 5 R/hr contact and 10 mR/hr at 6 ft. The report says the MSM had been there for some time, and should either be decontaminated or moved to a less-traveled area. Shear filters in the EMOA were reading 10 mR/hr through the concrete wall at 10 in. This radiation area was not posted.

Air cylinders used in the PMC to operate various remote tools exhausted into a header that was located in the MOA approximately 10 ft above the floor. Activity accumulating in the header resulted in contact readings of 10 mR/hr to 300 mR/hr. General area exposure rates in the MOA were said to have been "less than 100 mR/hr" (Runion 1968, p. 3 of Action Plan - Part 2). In March 1968 filters were installed in pneumatic piping in the PMC, reducing exposure rates in the MOA to where only a "small area" was still designated a radiation area (Clark 1968d). A July 1968 report said the filters prevented all but a 3-ft section of the piping from being a radiation area. The 3-ft section was shielded so that the exposure rate at 18 in. was "typically 10 mR/hr" (Clark 1968a, p. 2). NFS (1976) states buildup of radioactivity in the plant air exhaust lines from cylinders in the PMC caused exposure rates up to 24 mR/hr next to the WMOA windows.

The MRR was not adequately shielded and exposure rates in the North Mechanical Operating Aisle "reached 50 mR/hr on occasions."

A July 27, 1972, summary of plant decontamination activities mentions removal of contaminated piping and other sources from the WMOA and cleanup of fixed contamination on floors and walls in the EMOA. The report says the filter units in operation on the west end of the FRS were causing "significant dose rates" in the EMOA. It also says decontamination efforts in the MRR had resulted in a significant reduction of dose rates in the EMOA (Wenstrand 1972d, p. 1). Another report says the decontamination efforts in the MRR reduced the exposure rate in the MOA by a factor of four (Wenstrand 1972j).

Typical dose rates in the MOA in 2005 range from 0.1 mrem/hr to 5.4 mrem/hr (WVDP 2005).

A31.1.2 <u>Removable Contamination Data</u>

On October 24, 1969, at 5:00 pm the EMOA and WMOA, along with numerous other areas of the plant, became contaminated to Zone III levels. The MOAs were contaminated to 2000 to 3000 dpm/100 cm² beta. Maintenance work was postulated as the cause of the widespread tracking of contamination, but no definite cause was established. The report mentions that high backgrounds make detection of "low" levels of contamination (800 to 1000 dpm beta) difficult. Overall, the cause was attributed to either failure of persons to self-monitor (using hand and foot monitors) or ineffectiveness of these monitors (Jaeger ca. 1969).

Page 35 of 52

A31.1.3 Airborne Contamination Data

In December 1966 airborne alpha activity in the MOA rose above NFS' concentration limit of 4E-11 μ Ci/cm³ for canister masks. The activity was attributed to contamination in the CAA that resulted from maintenance work in the Plutonium Cell (Keely 1967e).

A report dated July 8, 1970, states the east and west MOAs are some of the areas that show air concentrations greater than "40 MPC-hr" [sic] during duct flushing operations (TKW 1970).

A32.0 MSM SHOP/CONTACT SIZE REDUCTION FACILITY

Construction of a new MSM Repair and Decontamination shop (to replace the Hot Shop) was under way in May 1968 (Clark 1968d). It was completed within 1 year. The MSM Shop was used for the repair of MSMs from the mechanical and analytical cells. The MSMs were decontaminated remotely while still in place to reduce the exposure rate to about 1 R/hr. The MSMs were then packaged and transferred to the MSM Shop for further decontamination and repair.

The MSM Shop was decontaminated and renovated between July 1982 and June 1983. Contamination had penetrated the original floor to the extent that it had to be removed and repoured. As of 1994 the MSM Shop was used to repair and adjust 25 to 30 manipulators a year. The manipulators were first decontaminated in an area adjacent to the MSM Shop.

The MSM Repair Shop transitioned to the Contact Size Reduction Facility beginning in 1987.

A32.1 RADIOLOGICAL CONDITIONS

A32.1.1 External Exposure Data

Exposure rates up to 50 mR/hr were present in the MSM Shop from activity in the adjacent MRR.

A July 27, 1972, summary of plant decontamination activities said the "background" in the manipulator repair area of the MSM Shop originated from the HEV System filters, the demister and the duct located on the east wall. It stated the "small room in the southwest corner of the MSM Shop" contained several sources that "should be packaged and removed ... or buried", and that the drain line from the PMCR needed to be shielded. It said radiation levels in the MSM Shop originating from the MRR had been reduced, but other sources had been added, and that the north MSM Shop contained a "high radiation source" located by the double doors that needed to be packaged for storage or shielded (Wenstrand 1972d, p. 2).

A32.1.2 <u>Removable Contamination Data</u>

Removable contamination levels exceeded 50,000 dpm/100 cm² in the "new" MSM Repair Area in May 1969 (Keely 1969c, p. 1).

Page 36 of 52

A33.0 OFF GAS AISLE AND PROCESS SAMPLE CELL 3

The OGA was in the southwest area of the process building on the 131-ft elevation. It was also known as the Off Gas Operating Aisle or the Acid Recovery Aisle. The Acid Recovery Cell was in the southwest corner of the process building on the same level.

The OGA was used for monitoring and controlling operations in the OGC, the Acid Recovery Cell, and part of the CPC. It also provided access to PSC-3 and acted as a passageway between laboratories, the Office Building and the south and southwest stairs (WVDP 2005). PSC-3 contained three samplers for fission product solutions in XC1 (Runion 1968, p. 16 of Action Plan - Part 2).

A33.1 RADIOLOGICAL CONDITIONS

The OGA was impacted by the substantial spill of contaminated acid from the Acid Recovery Cell in 1967 (see Section A1.0).

A33.1.1 <u>External Exposure Data</u>

On November 12, 1967, the exposure rate in PSC-3 was 70 mR/hr to 150 mR/hr. The west side of the glove box read 11 rad/hr.

Radioactivity in the acid recovery system created significant exposure rates in the OGA (Runion 1968, p. 16 of Action Plan - Part 2; NFS 1976).

On June 26, 1972, cement blocks were removed from the OGA for burial. The blocks read 5 R/hr (general area) (Nelson 1973a, p. 14 of attachment). Dose rates as high as 20 rem/hr were recorded in the OGA in 1972. Concrete was removed from this area reducing the dose rate to a maximum of 400 mrem/hr (WVDP 2005).

The July 27, 1972, summary of plant decontamination activities says the radiation level on the OGA roof around the condenser had been reduced by a factor of 10 from decontamination efforts. The major source of activity then became the backup filters (Wenstrand 1972d, p. 3).

Work was performed in the OGA the week of February 20, 1974, to remove a contaminated stainless steel pipe embedded in the floor (O'Reilly 1975). The general area exposure rate at the start of the work was 15 mR/hr to 20 mR/hr. The exposure rate in contact with the pipe was 400 mR/hr.

As of 2005 dose rates in the OGA generally range from 0.1 mrem/hr to 0.7 mrem/hr (WVDP 2005).

A33.1.2 <u>Removable Contamination Data</u>

Smearable contamination reached Zone 4 levels due to the leak in the DOG vent pipe in January 1969 (Keely 1969h, p. 2).

PSC-3 became contaminated from leakage of recovered acid from a valve in a sampler. Contamination also resulted from penetrations in the floor and airflow into the area from the OGA.

Page 37 of 52

Staff stated the blocks removed from the OGA on June 26, 1972, were grossly contaminated, having been used to shield an acid recovery line. Analysis showed the contamination on the blocks included ¹⁰⁶Ru, ⁹⁰Sr, ²³⁹Pu, and ⁹⁵Zr/Nb (Nelson 1973a, p. 14 of attachment).

During decontamination work the week of February 20, 1974, removable levels were generally 4000 dpm/100 cm² to 5000 dpm/100 cm² with a maximum of 200,000 dpm/100 cm². Potential nuclides in the contamination included mixed fission products, uranium, and plutonium (O'Reilly 1975). The report does not say whether the stated removable levels were alpha or beta.

A33.1.3 Airborne Contamination Data

In January 1969 airborne activity in the OGA reached 20 MPC following failure of a temporary repair of the DOG vent pipe.

A34.0 OFF GAS BLOWER ROOM

The OGBR was in the southwest section of the plant on the ground level, directly north of the ARPR. It contained blowers, filters, and scrubber recirculation pumps for the process off gas system.

The OGBR was decontaminated between November 1975 and June 23, 1976. Equipment (blowers and filters) was removed and new concrete was poured to repair parts of the floor that had been eroded away by spills from the ARC above (WVNSC 1994).

The OGBR was entered several times in the 1980s to replace HEPA filters. As of 1994 the OGBR had not been entered since the fall of 1992 (WVNSC 1994).

A34.1 RADIOLOGICAL CONDITIONS

A34.1.1 <u>External Exposure Data</u>

A survey inside the 6 G-3 scrubber pump niche in the OGBR on January 4, 1968, showed a wholebody exposure rate of 4 R/hr at 18 in. The extremity dose rates ranged from 18 rad/hr to 20 rad/hr (Wenstrand 1968f, p. 2).

On January 15, 1968, the DOG filter in the OGBR read 600 R/hr on contact and 100 R/hr at 12 in. It read 1000 rad/hr at 10 in. (Wenstrand 1968f, p. 2). Changing of the DOG and VOG filters was a contact maintenance activity.

As of early 1968 an operator had to enter the OGBR once a day for operation of manual valves to change solutions in the off gas scrubbers. The exposure rate in this area was 300 mR/hr (Runion 1968, p. 18 of Action Plan - Part 2).

In April 1968 "easily" removable contamination continued to be a problem in the OGBR (as well as the ARPR), giving skin dose rates of 120 mrad/hr (Keely 1968j).

Page 38 of 52

In May 1968 a TLD disk was used to measure the dose rate from the floor of the OGBR, giving a result of 165 rad/hr (Keely 1968e).

In June 1968 the typical working area exposure rate in the OGBR was 1 to 2 R/hr (Keely 1968a).

Exposure rates of 15 R/hr were encountered during cleanup of the "niche" in the OGBR in November 1972 (Morrow 1972d).

HEPA filters removed for replacement in 2000 and 2001 read 55 mrem/hr (WVDP 2005).

In 2003 dose rates in the southwest part of the OGBR ranged from 70 mrem/hr to 700 mrem/hr (WVDP 2005).

As of 2005 the general area dose rate in the OGBR ranged from 10 mrem/hr to 80 mrem/hr (WVDP 2005).

A34.1.2 <u>Removable Contamination Data</u>

As of early 1968 the OGBR was chronically contaminated from replacement of the DOG and VOG filters (Runion 1968, p. 18 of Action Plan - Part 2).

In May 1968 cutie pie readings on smears from the OGBR indicated a maximum removable level of 4E+08 dpm/100 cm² (Keely 1968e).

A35.0 OFF GAS CELL

The OGC was in the southwest section of the plant on the ground level. It was directly north of the OGBR. The OGC contained equipment for the VOG and DOG systems.

A35.1 RADIOLOGICAL CONDITIONS

The OGC was another one of the areas affected by the 1967 acid spill from the Acid Recovery Cell above (see Section A1.0). This lead to high radiation levels in the northwest corner of the cell (WVDP 2005).

A35.1.1 External Exposure Data

In August 1972 an entry was made into the OGC for a radiation survey for the first time since fuel reprocessing began. The general area exposure rate was between 10 R/hr and 20 R/hr (Morrow 1972e). The radiation levels along the floor were 20 R/hr to 25 R/hr and as high as 50 R/hr in the northwest corner of the cell.

In 2002 dose rates in the area of the DOG scrubber ranged from 94 mrem/hr at 28 ft from the floor to 1,600 mrem/hr at floor level. Dose rates in the northwest corner of the cell ranged from 270 mrem/hr at 28 ft from the floor to 1,500 mrem/hr at the floor.

Page 39 of 52

A36.0 PERMANENT VENTILATION SYSTEM BUILDING

The PVS Building was constructed by the WVDP to provide ventilation to the STS Support Building, the STS Valve Aisle, and the STS Pipeway. The building contains equipment (filters primarily) to treat ventilation exhaust air before release to the atmosphere. The PVS Building has its own stack.

A36.1 RADIOLOGICAL CONDITIONS

A36.1.1 External Exposure Data

Exposure rates are reported to be 80 mrem/hr to 170 mrem/hr on contact with the filter housing (WVDP 2005).

A36.1.2 <u>Removable Contamination Data</u>

Routine surveys do not show detectable removable contamination. Removable beta of 2.5E+06 dpm/100 cm² has been measured in the inlet plenum (WVDP 2005).

A37.0 PROCESS CHEMICAL ROOM

The Process Chemical Room (PCR) was above the north end of the CPC on the 144-ft elevation of the plant. It was directly north of and adjacent to the Hot Acid Cell. It contained four chemical makeup tanks and associated pumps.

A37.1 RADIOLOGICAL CONDITIONS

A37.1.1 <u>External Exposure Data</u>

In June 1969 the general exposure rate in the PCR increased from 30 mR/hr to 200 mR/hr with localized spots around the sampler reading as high as 5 R/hr (Keely 1969d).

The July 27, 1972, summary of plant decontamination activities says radiation levels in the PCR were significantly reduced when the Hot Acid Cell was decontaminated.

As of 2005 the dose rate in the PCR was around 1 mrem/hr (WVDP 2005).

A37.1.2 <u>Removable Contamination Data</u>

The July 27, 1972, summary of plant decontamination activities says radiation levels in the PCR were significantly reduced when the Hot Acid Cell was decontaminated. The reduced levels allowed the detection of contamination in the PCR that had previously been "obscured" by the high background (Wenstrand 1972d, p. 3).

Page 40 of 52

A38.0 PROCESS MECHANICAL CELL

The PMC is where extraneous hardware was removed from fuel assemblies, which were then sheared into small pieces for dissolving. The sheared fuel dropped through a discharge chute into baskets in the GPC below.

The PMC included high-workload manipulators for handling fuel elements. Maintenance and repair of these manipulators (performed after they were removed from the cell) was a significant source of personnel exposures because of the substantial contamination from fuel particles. Exhaust from air cylinders used in the PMC to operate various remote tools was a source of contamination and elevated exposure rates in other areas of the plant, such as the MOA.

A general cleanup of the PMC was conducted between October 22, 1971, and September 15, 1972 (WVNSC 1994). The WVDP completed deactivation of the PMC in 2004 (WVDP 2005).

A38.1 RADIOLOGICAL CONDITIONS

The PMC was never a routinely occupied area.

A survey of the PMC in April 1972 showed exposure rates ranging from 1,500 R/hr to 4,500 R/hr (Wenstrand 1972j).

In 1986 gamma exposure rates in the PMC ranged from 0.8 R/hr to 40 R/hr at 6 ft from the floor. Beta-gamma levels ranged from 40 rem/hr to 240 rem/hr (WVDP 2005).

Surveys performed after the 2004 cleanup in grid locations 3 ft above the floor showed dose rates ranging from 1.5 rem/hr to 40 rem/hr (WVDP 2005).

A39.0 PRODUCT PACKAGING AND SHIPPING, PRODUCT PACKAGING AND HANDLING, URANIUM PRODUCT CELL, AND URANIUM LOADOUT AREAS

The aqueous plutonium and uranium nitrate products from fuel reprocessing were packaged in 10 L shipping containers in the PPH area. They were then shipped by truck from the PPS area above. The two were connected via an airlock (WVDP 2005). During operations the PPH contained glove boxes used for filling of product bottles. One was used for plutonium and the other for uranium.

The PPH became the Waste Reduction and Packaging Area under the West Valley Demonstration Project (WVNSC 1994). In 2005 it was being used for compressing LLW into metal storage containers using a 50-ton hydraulic compactor (WVDP 2005).

The UPC was on the ground level directly north of the PPC. It contained tanks for the collection and storage of uranyl nitrate before analysis and shipment. The function of these tanks was modified in 1988 to where they became hold tanks for the WVDP Low-level Waste Treatment System (WVDP 2005).

Page 41 of 52

The ULO, also on the ground level, was directly east of the UPC. The ULO contained a 4,000-gal weigh tank used to measure shipments of uranyl nitrate before transfer to tanker trucks or to the back of the cell for further processing (WVDP 2005).

A39.1 RADIOLOGICAL CONDITIONS

A39.1.1 External Exposure Data

May 1966: Several shipments of uranium product were made and two bottles of plutonium product were loaded out. The maximum radiation level on the Pu bottles was 130 mR/hr (Loud 1966d).

Exposure rates at 6 in. from the Product Packaging and Handling loading dock on January 20, 1968, were 2 R/hr whole body and 17 rad/hr extremity (Wenstrand 1968f, p. 2).

In 1996 dose rates in the UPC ranged from 10 mrem/hr to 450 mrem/hr. Surveys in 2003 showed dose rates of 120 mrem/hr on the underside of one of the waste tanks and 110 mrem/hr between the two tanks (WVDP 2005).

As of 2004 the dose rate in the PPH area was less than 1 mrem/hr (WVDP 2005).

As of 2005 the dose rate in the ULO area was typically less than 1 mrem/hr, with levels up to 29 mrem/hr in the pump room (WVDP 2005).

A39.1.2 <u>Removable Contamination Data</u>

Decontamination efforts in the UPC in April 1972 reduced the typical removable alpha contamination levels from 10^7 dpm/100 cm² to 10^5 dpm/100 cm² (Wenstrand 1972j).

In 1996 surveys showed removable levels up to 32,000 dpm/100 cm² alpha and 348 dpm/100 cm² beta in an area north of one of the tanks (WVDP 2005).

Low levels of removable contamination were present in the ULO area as of April 2005. Removable was not detected elsewhere in the area (WVDP 2005).

A39.1.3 Airborne Contamination Data

The airborne activity levels in the PPS area exceeded the MPC during the week of March 18, 1968 (Wenstrand 1968b).

In June 1969 long-lived alpha air activity in the PPH area exceeded the MPC for "a major portion of the month." The air activity was said to originate from contamination present on the north wall by the High Enriched Loadout Box (Keely 1969d).

A40.0 PULSER EQUIPMENT AISLE

The PEA was immediately south of the XCR on the 160-ft elevation of the process building. The PEA included air pulsers for the extraction columns in the extraction cells and other equipment. This

Page 42 of 52

equipment was removed in 1980 and the area was reconfigured to support operation of the LLW treatment system. The former PEA no longer exists (WVDP 2005).

A40.1 RADIOLOGICAL CONDITIONS

A40.1.1 Airborne Contamination Data

The airborne activity levels in the PEA exceeded the MPC during the week of March 18, 1968. The same document states this condition existed in both the PEA and the PPS area, suggesting the MPC of concern was that for alpha (²³⁹Pu) (Wenstrand 1968b, p. 1).

A41.0 REMOTE HANDLED WASTE FACILITY

The RHWF was built by the WVDP. It went into operation in June of 2004. It is used for size reduction and packaging of equipment containing large amounts of radioactive materials.

A42.0 SAMPLE STORAGE CELL, ANALYTICAL HOT CELLS, AND ANALYTICAL DECONTAMINATION AISLE

The Sample Storage Cell (SSC) was on the east side of the CPC at the 131-ft elevation (i.e., the analytical level of the plant). It contained a conveyor-elevator for transferring samples to the Analytical Hot Cells or laboratories. The SSC had three shielded viewing windows and three sets of manipulators in its north wall. As of 2005 the SSC remained highly contaminated and showed dose rates from 126 mrem/hr up to nearly 20 rem/hr (WVDP 2005, p. C-49).

Entries were sometimes made into the SSC for periodic maintenance of equipment in the Analytical Hot Cells that could not be removed. These entries were made via the Analytical Decontamination Aisle (ADA). The SSC would be remotely decontaminated before these entries, and internally contaminated items such as sample bottles would be removed via the conveyor system.

On the east side of the ADA were five Analytical Hot Cells and Sample Cell 2C. The ADA was sometimes referred to as the Analytical Cell Decontamination Area.

A43.0 SCRAP REMOVAL AREA

The SR area was on the ground (100 ft) level of the process building northeast of the CPC. This area is also sometimes referred to as the SR Cell or SR Room.

Leached hulls and process wastes (including failed equipment) were placed in 30-gal drums for burial. The drums were loaded inside the GPC, then passed through a hatch to the SR area. They were sprayed with water as they passed through the hatch and then transferred to a shielded cask inside the SR area. Excess water was allowed to drip off before the drums were placed in the transfer cask. The cask was placed on a trailer (which had been backed into the SR area) and both were decontaminated before being released to go to the HLW burial area.

Page 43 of 52

Decontamination of the SR area took place in 1972 and again in 1980. D&D of the SR Room took place between March and September 1986. The SR Room now contains Tank 7D-13, which formerly received liquids from the plant laundry and analytical laboratory drains. As of 1994 the tank received liquids from laboratory drains and from drum flushing operations at the Concrete Solidification System (WVNSC 1994).

A43.1 RADIOLOGICAL CONDITIONS

A43.1.1 External Exposure Data

A dissolver removed from the CPC in July 1969 read 30 R/hr at contact with its shield cask and 50 mR/hr at 50 ft (upon removal from the SR area) (Keely 1969e).

The 1986 D&D of the SR area reportedly reduced exposure rates in the SR Room to less than 1 mR/hr (WVNSC 1994). However, other references report levels from 1 mrem/hr to 40 mrem/hr at 1 ft from the floor in 2003, and up to 10 mrem/hr at 3 ft from the floor (WVDP 2005).

A43.1.2 <u>Removable Contamination Data</u>

The SR area was a chronic source of contamination because of the waste packing and removal operations. Typical contamination levels for the drums is said to have been in excess of 500,000 dpm/100 cm² as they came from the GPC to the SR area (Runion 1968, p. 4 of Action Plan - Part 2).

A43.1.3 Airborne Contamination Data

In January 1967 repair of the seal around the SR door resulted in differential pressure between the GPC and the SR Area, with the latter becoming an airborne activity area on several occasions thereafter (Keely 1967d, p. 2).

A44.0 SOLVENT STORAGE TERRACE

The Solvent Storage Terrace (SST) was located on the south side of the process building on the roof of the UWA at the 131-ft elevation. Storage tanks for recovered acid and solvent wastes were located on the SST. The Recovered Acid Storage Tank received acid from the bottom of the acid fractionator located in the Acid Recovery Cell. The solvent waste tanks received solvent from the extraction cells (WVNSC 1994).

A44.1 RADIOLOGICAL CONDITIONS

The SST became contaminated from spills and leaks from the tanks. Liquids from the SST drained to an unlined holding pond near Lagoon 1 known as the "solvent dike" (WVNSC 1994).

A44.1.1 <u>External Exposure Data</u>

On November 4, 1967, the solvent storage tank read 2.5 R/hr to 3 R/hr on contact.

Page 44 of 52

In June 1968 a survey of the SST showed hot spots on the floor reading up to 100 R/hr. The exposure rate at the bottom of the solvent storage tank was 300 R/hr (Keely 1968a).

As of 2005 dose rates on the SST were typically 0.1 mrem/hr or less (WVDP 2005).

A44.1.2 <u>Removable Contamination Data</u>

In July 1968 smears from the SST indicated removable beta contamination levels of 1E+08 dpm/100 cm² (Keely 1968k).

In March 1972 a leaking connection during solvent loadout caused removable beta contamination up to 10^7 dpm/100 cm² on the SST (Wenstrand 1972k).

A45.0 SUPERNATANT TREATMENT SYSTEM SUPPORT BUILDING

The STS Support Building was built by the WVDP to support STS operations. It is a two-story building located adjacent to and on top of the HLW storage tank 8D-1. The first level contains the valve aisle, operating aisle, and control room. The second story houses tanks and delivery systems. The STS Support Building supported STS operations from 1988 through 1995. Subsequently it was used to treat vitrification waste streams and for processing of sodium-bearing wastewater.

A45.1 RADIOLOGICAL CONDITIONS

A45.1.1 <u>External Exposure Data</u>

In May of 2002 dose rates in the valve aisle ranged from 0.9 rem/hr to 8.2 rem/hr 4 ft from the back wall. The dose rate ranged from 0.5 rem/hr to 3.3 rem/hr 12 in. from the viewing windows (WVDP 2005).

A45.1.2 <u>Removable Contamination Data</u>

Surveys on the first and second floors outside the valve aisle typically do not show detectable removable contamination. Removable contamination is said to be "very high" inside the valve aisle (WVDP 2005).

A46.0 UPPER EXTRACTION AISLE

The UXA was immediately north of the extraction cells on the 144-ft elevation of the process building. It served as an operations and maintenance area for extraction cell and other equipment. The area included valves, piping, instrumentation, ventilation ducts, and stack monitoring equipment.

A46.1 RADIOLOGICAL CONDITIONS

A46.1.1 <u>External Exposure Data</u>

As of early 1968 a high radiation area existed on the UWA in the area of a recovered acid line (Runion 1968, p. 11 of Action Plan - Part 2).

Page 45 of 52

Radiation levels around the 7C-1 jet in the UXA reached 10 R/hr at 18 in. twice during the month of May 1969 (Keely 1969c, p. 2).

The July 27, 1972, report on plant decontamination status said radiation from the west wall of the UXA appeared to be caused by "a shielding flaw between the aisle and the steam ventilation filter bank" (Wenstrand 1972d, p. 3).

In 2004 the general area dose rate in the UXA ranged from 0.1 mrem/hr to 6 mrem/hr. In 2005 the range was 0.1 mrem/hr to 4.0 mrem/hr (WVDP 2005).

A46.1.2 <u>Removable Contamination Data</u>

Horizontal surfaces in the UXA showed removable levels up to 280,000 dpm/100 cm² beta on January 1, 1968 (Wenstrand 1968f, p. 3).

A jet was mistakenly left open on May 25, 1972, allowing an estimated 1.5 to 2 gal of contaminated acid and water to leak onto the floor of the UXA. Surveys of the surrounding floor area showed 50,000 cpm alpha. The activity in the puddle was determined to be ²³⁹Pu.

A47.0 UPPER WARM AISLE AND PROCESS SAMPLE CELL 1

The UWA was immediately above the LWA, adjacent to the extraction cells on the 114.5-ft elevation. Like the LWA, it contained concrete niches that housed pumps, valves, and other equipment used in the solvent extraction process. There were six of these niches extending into the UWA. The equipment in the niches required routine maintenance or replacement, resulting in contamination of the area (Runion 1968, p. 10 of Action Plan - Part 2).

The UWA also contained PSC-1, which was on the northeast end of the aisle. PSC-1 was a shielded stainless-steel box that housed a glovebox and samplers for sampling purified plutonium and uranium solutions from the PPC.

NFS decontaminated the UWA, including the niches, in the 1972 to 1974 period. They also replaced several of the pumps. The aisle and niches were also decontaminated by the WVDP in 1985 (WVDP 2005). Equipment niches and associated equipment were removed from the UWA in 1986 (WVNSC 1994).

A47.1 RADIOLOGICAL CONDITIONS

A47.1.1 <u>External Exposure Data</u>

A September 18, 1967, letter from NFS to the AEC says the UWA area in general (i.e., outside the pump niches) only became a high radiation area when maintenance work was being performed (Runion 1967a, p. 2).

Page 46 of 52

On November 13, 1967, the exposure rate at the top of the 13G-2 pump niche in the UWA was 2.5 R/hr to 3.0 R/hr. The pump read 60 rad/hr and 12 R/hr at 2 in. The 13G-1 pump niche read 6 R/hr at the top and 20 R/hr to 30 R/hr at the bottom. The pump stand read 50 R/hr at contact.

Surveys in the UWA on January 20, 1968, showed exposure rates of 10 R/hr and dose rates up to 35 rad/hr (Wenstrand 1968f, p. 2).

Typical dose rates in the UWA as of 2005 ranged from 0.1 mrem/hr to 0.5 mrem/hr for the general area. There was a hot spot up to 35 mrem/hr on a drain line and up to 15 mrem/hr on the south wall. Surveys inside pump niches 1 through 5 in December 2003 to January 2004 showed the following maximum levels, each near the floor (WVDP 2005).

- UWA pump niche 1 = 40 mrem/hr
- UWA pump niche 2 = 1.8 mrem/hr
- UWA pump niche 3 = 45 mrem/hr
- UWA pump niche 4 = <1 mrem/hr
- UWA pump niche 5 = <1 mrem/hr

A47.1.2 <u>Removable Contamination Data</u>

On November 17, 1967, removable alpha in PSC-1 ranged from 150 dpm/100 cm² to 3700 dpm/100 cm² with hot spots on the floor as high as 320,000 dpm/100 cm².

Sample bottles in PSC-1 were bagged and transferred into a glovebox. The sampling station would periodically become contaminated from these operations, allegedly from inadequate bagging. Entries into the PPC also resulted in contamination of the sampling station from airflow reversals into the glovebox through its vent.

Removable beta contamination levels in the UWA ranged from 200,000 dpm/100 cm² to 1.5E+06 dpm/100 cm² on January 22, 1968 (Wenstrand 1968f, p. 3). In February 1968 smears of the UWA showed removable beta levels of 1.2E+06 dpm/100 cm² (Wenstrand 1968e, p. 2).

In May 1968 "aggressive" decontamination efforts reduced removable beta contamination levels to Zone 3 limits in both the UWA and LWA (Keely 1968e).

In August 1968 removable contamination in the UWA showed a maximum of 8E+06 dpm/100 cm² (Keely 1968b).

On October 29, 1968, smearable alpha contamination in PSC-1 reached 250,000 dpm/100 cm² during maintenance work (Keely 1968d).

Contamination in the UWA was reduced from Zone 4 to low Zone 3 during the month of February 1969 (Keely 1969f).

In August 1969 removable alpha contamination was 1E+06 dpm/100 cm² in PSC-1 following modifications to sample lines and installation of a glove box (Wenstrand 1969c).

Page 47 of 52

Removable contamination levels in the UWA before decontamination in 1985 ranged up to 2,070 dpm/100 cm² alpha and 19,800 dpm/100 cm² beta (WVDP 2005).

As of 2005 removable levels on the UWA were nondetectable, but levels up to 312,000 dpm/100 cm² beta-gamma had been measured in the niches (WVDP 2005).

A47.1.3 Airborne Contamination Levels

In October 1967 air samples "taken on each shift" from the XSA and PSC-1 showed long-lived airborne alpha concentrations of 2E-12 μ Ci/cm³ and 5.4E-11 μ Ci/cm³ (Wenstrand 1967d, p. 2).

A48.0 UTILITY ROOM AND STAIRWELLS

The Utility Room was a concrete block structure adjacent to the process building on its south side. It shared its north wall with the process building. This wall was reinforced concrete (WVDP 2005).

The process building contained four main reinforced concrete stairwells having landings on the various levels. These were the

- East Stairs: Near the PPC extending from the ground level to the 160-ft elevation
- North Stairs: Near the GOA extending from 76.5 ft (below ground level, i.e., the level of the GOA) up to the 131-ft (analytical) level
- South Stairs: North of the Utility Room extending from ground level up to the 160-ft elevation
- Southwest Stairs: South of the office area extending from ground level to an elevation of 152 ft

A48.1 RADIOLOGICAL CONDITIONS

The stairways (South and Southwest in particular), as well as the Utility Room, became contaminated from spills and frequent airflow reversals that would occur when doors were opened. These reversals resulted in flow of contamination from acid recovery and off gas areas into the stairwells and the Utility Room.

A48.1.1 <u>External Exposure Data</u>

In June 1969 exposure rates in the Southwest Stairwell increased from 20 mR/hr to 90 mR/hr during the "Yankee campaign"; that is, higher burnup fuel (Keely 1969d).

Exposure rates up to 6 R/hr were measured in the lower levels of the Southwest Stairs in the early 1970s (WVDP 2005).

Page 48 of 52

The July 27, 1972, summary of plant decontamination activities says the radiation levels in the shower and locker room areas originating from the Southwest Stairwell remained "essentially the same" as they did in March 1972 (Wenstrand 1972d, p. 2).

A typical dose rate of 30 mrem/hr with hot spots up to 125 mrem/hr are reported for the North Stairs on the east wall south of a viewing window into the PMCR, but no time frame is given for when or how long these exposure rates existed. Levels up to 20 mrem/hr gamma and 130 mrem/hr beta-gamma are reported for "different times in other areas" of the north stairwell (WVDP 2005).

In 1990 the dose rate in the south stairs at the Control Room landing (144-ft level) ranged up to 9 mrem/hr (WVDP 2005).

Typical dose rates for the stairwells in 2004 were (WVDP 2005):

- East stairs = 0.1 mrem/hr to 0.5 mrem/hr
- North stairs = 0.1 mrem/hr to 0.5 mrem/hr.
- South Stairs = 0.1 mrem/hr to 5.0 mrem/hr
- Southwest Stairs = 0.1 mrem/hr to 14 mrem/hr

Typical dose rates for the stairwells in 2005 were (WVDP 2005):

- East stairs = <0.04 mrem/hr to 1.1 mrem/hr
- North stairs = <0.04 mrem/hr to 0.6 mrem/hr
- South Stairs = 0.2 mrem/hr to 4.8 mrem/hr
- Southwest Stairs = 0.1 mrem/hr to 22 mrem/hr

The elevated dose rates for the Southwest Stairs were at the second landing.

A48.1.2 <u>Removable Contamination Data</u>

In January 1967 gamma analysis on sand from the Utility Room trench, which was reading 20 mR/hr to 50 mR/hr, showed "mostly Zr/Nb-95" (Keely 1967d, p. 3).

As of early 1968 the South Stairwell had become contaminated from an airflow reversal from the OGBR, which was located at the base of the stairway. These reversals occurred whenever the door at the base of the stairway was opened (Runion 1968, p. 19 of Action Plan - Part 2). Subsequently, the OGA and Southwest Stairway became contaminated since they received air from the South Stairs (Runion 1968, p. 20 of Action Plan - Part 2).

In October 1968 removable contamination on a wall in the Southwest Stairwell was 5E+06 dpm/100 cm² around a leak through the wall of the Acid Recovery Cell (Keely 1968d).

The Southwest Stairwell became contaminated to Zone 4 levels by an acid leak in the OGA on October 23, 1969 (Wenstrand 1969c).

Page 49 of 52

A48.1.3 Airborne Concentration Data

On July 8, 1970, the East and North stairs showed concentrations "close to" 40 MPC-hr [sic] during flushing of the ventilation ducts (TKW 1970).

An air sample collected from the Utility Room in January 1974 showed an alpha concentration of $5.8\text{E}-12 \ \mu\text{Ci/cm}^3$. Isotopic analysis of the alpha activity showed the following.

- Pu-238 = 7.6 wt%
- Pu-239 = 76.1 wt%
- Pu-240 = 11.2 wt%
- Pu-241 = 4.3 wt%
- Pu-242 = 0.8 wt%

A49.0 VENTILATION EXHAUST CELL

The VEC was located on the roof of the CPC at an elevation of 148 ft. It contained ductwork, filters, blowers, and controls for the main ventilation system. The VEC contained two parallel ventilation systems: electric powered for routine operations and steam powered as a backup. The two filter banks were therefore identified as "steam" or "electric."

A49.1 RADIOLOGICAL CONDITIONS

A49.1.1 External Exposure Data

During a filter changeout in 1994 the roughing filters read 1.8 rem/hr gamma at 2 in. The HEPA filters read 400 mrem/hr to 500 mrem/hr at 2 in. The floor of the filter housing ranged up to 1 rem/hr gamma (WVDP 2005).

As of 2005 general dose rates in the VEC ranged from 1 mrem/hr to 100 mrem/hr (WVDP 2005).

A50.0 VENTILATION SYSTEMS

Overall, the single largest source of personnel exposures at West Valley during its operations era was the plant ventilation system. The unanticipated magnitude of the problem of high specific activity fuel particles, coupled with plateout of these particles within the system and its failure to maintain necessary pressure differentials, was both a direct and indirect source of personnel exposure throughout the plant. The main ventilation system serviced the entire reprocessing plant from startup until October 25, 1970. On October 25, 1970, a new HEV system came on line that provided additional ventilation capacity for the head end process cells and operating aisles.

A50.1 MAIN VENTILATION SYSTEM

The main ventilation system consisted of an air washer followed by roughing and absolute filters along with associated blowers and ducting. After exiting the washer, the ventilation air was routed through a

Page 50 of 52

duct along the ceiling of the LXA, around the outside of the laboratories, over the top of the Control Room, and into the filter plenum in the VEC.

Particulate activity collecting on the interior of the ducting gave contact exposure rates from 100 mR/hr to 800 mR/hr. The system was modified in 1967 to allow periodic flushing of the ducts, which would offer temporary relief until the contamination built up again. These duct-flushing operations would also result in high airborne activity levels throughout the plant. In addition to the chronic local and area exposure rate problems associated with the ventilation system ducting, another significant source of personnel exposure was that associated with changing the filters (roughing and absolute) in the VEC.

After filtration, the process building ventilation system air was either exhausted through the stack or recycled. Recycled air was used in the LLWT Plant, the HLW Storage Facility, and the FRS. The recycle air passed through HEPA filters before reuse.

Other ventilation systems, which served to keep process vessels at negative pressure relative to the cells, which were at negative pressure relative to the aisles, included

- The DOG system
- The VOG system (for process vessels)
- The Waste Tank Farm ventilation system

The DOG system treated gases from the vacuum dissolvers in the CPC and purge gases from the fuel bundle shear in the PMC. The DOG system included scrubbers to reduce nitrogen oxides, which were also effective for removing particulates and iodines. North and Clark (1968) state silver nitrate reactors in the DOG system "have not been put into operation because the long-cooled fuel contains an insignificant amount of iodine-131." The DOG system effluents first passed through HEPA filters before discharge via the plant stack.

The VOG system ventilated gases from process vessels and tanks to the OGC, where it passed through scrubber and filters before discharge to the main ventilation system (WVNSC 1994).

The removal efficiency of the off gas scrubbers was lower than expected (NFS 1976). This resulted in higher than expected activity in the DOG and VOG absolute filters. Periodic changing of these filters, which was a contact maintenance activity, was a significant source of personnel exposures.

A document from ca. 1967 gives the criteria for replacement of the DOG filters, saying a filter shall be replaced whenever the exposure rate at 2 in. exceeds 500 R/hr. This measurement was to be taken whenever the exposure rate through the shield plug exceeded 6 R/hr, i.e., once it got to 6 R/hr the plug was to be removed and a measurement taken at 2 in. (Clark 1968e).

Following the modification of the plant to add the dedicated HEV system (see next section), the original building ventilation system serviced the nonprocessing areas of the plant, including the operating aisles, office areas, chemical makeup area, maintenance area, FRS pool area and the laboratories (NFS 1973b, p. 6.1-8).

Page 51 of 52

A50.2 HEAD END VENTILATION SYSTEM

Before 1970, the plant's main ventilation system served all of the plant, including the head end process cells and operating areas. In an effort to relieve the main ventilation system of the substantial airborne radioactivity generated in the head end processing, the HEV system was activated in 1970. The radioactivity removed by the HEV was greater than expected, resulting in dose rate problems in several areas adjacent to the HEV building. In addition, periodic replacement of the HEV filters was a source of significant personnel exposures.

The HEV system was added to the plant in response to the operational difficulties encountered from the high-activity particulate contamination associated with mechanical segmentation of fuel assemblies. The HEV system was expected to increase the differential pressure between occupied and contaminated areas, to increase the airflow through contaminated areas where contact maintenance was performed (the MSM shop in particular), and to divert the bulk of the particulate contamination to a dedicated filter system instead of the main ventilation system filters (Author unknown 1969). NFS felt their existing stack sampling and monitoring equipment could handle the increased flow.

The HEV system was licensed on October 20, 1970, and placed into operation October 25, 1970 (NFS 1971, p. 1). It serviced the cells and operating aisles involved in the mechanical processing of fuel. The air flowed into filter trains in the HEV Building and then out to the plant main stack (WVNSC 1994).

NFS states the HEV system reduced the exposure rates from the main ventilation system components, thus reducing personnel exposures associated with the main ventilation system ducting, air washer, etc. Exposure rates were reduced "significantly" in the Control Room, analytical aisles, and extraction aisle. Personnel exposures associated with changeout of main ventilation system filters were reduced, and the change frequency also decreased. The HEV system also reduced contamination levels in the airlocks and crane rooms, and reduced particulate emissions from the main stack. However, the location of the HEV exhaust duct near the fuel shearing operation resulted in higher than expected loading of the HEV filters and buildup of activity in the duct. The activity in the HEV duct and filters was responsible for 69 person-rem/yr of collective dose.

A51.0 VENTILATION WASH ROOM

The VWR was on the 114.5-ft elevation of the plant, directly south of the PMC. It contained the air washer for the main ventilation system. The purpose of the washer was to intercept particulate activity from the saw and shear in the PMC.

A51.1 RADIOLOGICAL CONDITIONS

Buildup of particulates in the ventilation air washer filters after several years of plant operation necessitated replacing the filters. Changeout of these filters and the air washer pump were a significant source of exposure for maintenance workers. Per NFS (1976), these two sources resulted in collective dose for maintenance workers of about 30 person-rem/yr from the VWR. However, this value likely reflects exposures after the HEV system came on line in October 1970. Personnel

Page 52 of 52

exposures before the HEV being in operation would have been higher. The air washer was decontaminated after the plant shut down in 1972.

In 2001 the dose rate on the ventilation duct in the VWR upstream of the inlet plenum was 1.5 rem/hr. The average for the entire length of the duct from the VWR to the VEC averaged 34 mrem/hr at 6 in. with a maximum of 130 mrem/hr (WVDP 2005).

A51.1.1 External Exposure Data

The working area exposure rate for a pump changeout in the VWR was in October 1969 was 10 R/hr to 15 R/hr.

1983 estimates of exposure rates in the VWR were general levels of 200 mR/hr to 1,000 mR/hr and in excess of 5 R/hr at the washer itself (WVNSC 1994, p. 85). In 2001 the dose rate on the floor ranged from 10 mrem/hr to 1,200 mrem/hr gamma. The highest dose rate was in an area around the floor drain that read 2,500 mrem/hr beta-gamma (WVDP 2005).

A51.1.2 <u>Airborne Contamination Data</u>

An air sample taken in the VWR on October 23, 1967, showed 4E-10 μ Ci/cm³ of "long-lived alpha" and 3E-10 μ Ci/cm³ of "long-lived beta" (Wenstrand 1967d, p. 1).

A52.0 WASTE TANK FARM

The Waste Tank Farm (WTF) area included the underground tanks used to contain high-level liquid wastes from fuel reprocessing. There were separate tanks for PUREX waste (neutralized) and THOREX wastes (not neutralized). The PUREX tank was 750,000 gal. The THOREX tank was 15,000 gal. Separation and solidification of these high-level liquid wastes were a major focus of the WVDP.

A52.1 RADIOLOGICAL CONDITIONS

A52.1.1 External Exposure Data

An April 19, 1973, memorandum (Wenstrand 1973, p. 2) describes "major problems" associated with radiation levels at the WTF shelter. It says the exposure rates make the area a high radiation area, so it must be locked. The sources of the exposure rates were vent lines, piping, and resin units.

ATTACHMENT B LANDAUER EXPOSURE REPORT CODES Page 1 of 1

EXPLANATION FAND REMARKS CONFAMINES INC. REPORT.

.

1. GUALITATIVE RANGE COVERED Exclosures reported in millirems from gamma and x-ray: 30 KEV to 20 MEV, beta: over 1.5 MEV, neutrons: 1 MEV to 10 MEV. Dosage beyond these limits is recorded but not necessarily in millirems miless arrangements were made for calibration at other energy ranges.

2. MINIMUM DOSAGES REPORTED

Exposures below minimum quantity measurable are recorded "M" ("M" in current period columns equals less than 10 millinems x or gamma, 40 milli-rens hard beta, 20 millinems fast neutron, or 10 millinems thermal neutron. "M" in cumulative total columns means all previous current exposures have been minimal, unless adjustments to these totals have been made at customer's request).

3. DETERMINATION OF CUMULATIVE DATA .

Cumulative totals equal sum of non-minimal readings for badges returned for processing and reported to date. Below minimal exposures are caded as zero. If other than weekly reporting periods are used the 13 week summary will be the nearest interval of greater duration. Calendar quarters are selected to most nearly conform to AEC and state recording requirements considering starting date and length of monitoring periods chasen.

4. SKIN DOSE TOTALS

Total and cumulative skin dose values given are the sum of both the law penetrating radiation and the high penetrating radiation. (Thus they will be the sum of all previous skin dose plus totol body exposures.Ested)

5. ADJUSTMENTS TO CUMULATIVE DATA

To aid in proper presentation of information for records required by the AEC and other regulatory badies, comendments to the cumulative totals icolumns 13, 14 and 15) may have been mode increasing or decreasing the totals from those ariginally reported. Such amendments are made anginety reported, such a minimum and more and the request of an authorized representative of the cleant and are only to reflect supplementary does demonstrating that the film badge exposure originally occurred in such a manater as to either overstate or understate the true dosage to the badge assignee. (Refer to adjustment column). Addition of previous exposure prior to commencement of use of the particular film badge assignment reported may also be reflected in the cumulative

6. USE OF CONTROL FILM

Reporting is ordinarily in net exposure and the control film reacing is deducted from the personnel film reading. But if the control appears to have been exposed differently from the personnel packets the densities on the personnel film are normalized to our centrols only and a non-minimal control reading reported. A control packet reading is given in arbitrary units, not necessarily millirems.

- 7. REPORTING OF BETA AND 'OR SOFT X-RAY Minimal beta or soft x-ray skin dase readings are unreported until after a positive skin dase exposure is recorded.
- 8. RING BADGE READINGS
- Ring badges are collibrated for high energy gamma and high energy beta only, unless special arrangements have been made. If ring badges are exposed to other radiation the value may not be dosage in millimens and may require further interpretation. (COLUMN 4) NOTES.

A- Not Returned.

- B-1 This film appears to have been domaged by light. The accuracy of any reading given would be affected thereby.
- 8-2 This film oppeor to have been damaged by moisture. The accuracy of any reading given would be offected thereby.
- 8-3 This film appears to have been damaged by chemical fogging. The accuracy of any reading given would be affected thereby.
- 5-4 This film appears to have been manufactured faultily. The accuracy of any reading given would be affected thereby.
- 5-5 This film appears to have been damaged by heat or pressure. The accuracy of any reading given would be affected thereby.
- 5-6 This film appears to have been damaged by age fog. The accuracy of any reading given would be affected thereby.
- E-7 This film appears to have been damaged by an oily substance. The accuracy of any reading given would be affected thereby.
- Evidence of contamination. .C
- This film packet appears to have been exposed out of the badge, therefore, the value given is based on a high energy gamma calibration and DA is valid only if the exposure were due to high energy gamma if it were due to beta particles, the doage may be from 1.5 to 20.0 times the reported value. If it were due to lower energy x or gamma rays, the value reported may be from 1.1 to 20.0 times the actual doluge.
- DB Although this im packet was slightly lightstruck, the reading appears to be minimal
- DC This film packet is partially lightstruck. There is apparently a dose recorded, however, no exact guantitative determination can be made.
- DD This film badge appears to have been shielded during exposure. The dose reported is not an exact quantitative determination, but only an indication that the badge was exposed.

- DE This film bacige oppears to have been shielded during exposure. There is a dose recorded, however, no exact quantitative determination can be made.
- DF This film packet appears to have been misplaced in the badge. The dase reported is not an exact quantitative determination, but is only an indication that the badge was exposed.
- DG Although this film packet was slightly lightstruck, there seems to be no apporent effect on the reading. 1.20
- DH The bet-gamma background on this film badge was too nigh to give a valid fast neutron reading.
- This reading is based on 50-150KV-x-ray. This-film DI badge appears to be defactive, please return badge for replacement.
- DJ This film packet is too old to process.
- DL This control packet appears to have been placed in a film badge indicating possible misuse. May we remind you, that the value of the control films is last if used for personnal monitaring or other radiation measurement ourposes.
- DM This reading is based on a high energy calibration and is volid only if the exposure were due to high energy gamma. This film bodge appears to be defective, please return badge for replacement.
- DN This reading appears to have been caused by chemical fogging rather than by ionizing radiation.
- DO This film appears to have been exposed in a badge other than ours. Therefore, no valid reading can be civen.
- DR This film appears to have been exposed from the rear of the badge.
- DS Amounts shown in columns 7 to 10 have been permanently subtracted from cumulative totals at customer's request.
- Amounts shown in columns 7 to 10 have been permanently added to cumulative totals at cus-DT tomer's request. .
- DU Amounts shown in columns 7 to 10 have beenapplied by customer for period prior to inception of Landover service and have been permanently added to cumulative totals. Amounts shown Columns 7 to 10 are previous
- DV lifetime exposures supplied by customer and have been permanently added to cumulative totals. DZ Other Comment - see attached note.
- Irregular exposure.
- E-1 Due to the irregular exposure the effective energy cannot be properly determined and the dosage is estimated arbitrarily based on 50 to 150 PKV x-rays as probable source of exposure. If different
- energy the value reported will not be the actual dosoce. .E-2 Due to the irregular exposure the effective energy
- control to the property determined and the dosage is estimated arbitrarily based on gamma or x-ray over 400 KEV as probable source of exposure. If different energy, the volue reported will not be the actual dosage.

.

.

G Received early. -H Unused.

 Finger beta-gamma film badge
 Wrist beta-gamma film badge Fast neutron-only body film bodge Beta gamma thermal neutron body film badge Dual beta-gamma body film bodge - Beta-generathermal seatron-fast neutron body badge Gamma wrist-TLD Gamma-body-TLD - Gamma finger-TLD - Gamma forehead-TLD A1000 beta-gomma body film badge Special TLD badge - A1000 beta-gamma, fast neutron body film badge Z -Other film badge (COLUMN 12) ENERGY RANGE For some badges, the range column on this may contain either L, M, or H. These entries are madel for exposures in excess of 50 mr and in- Z dicate! the approximate effective energy range of the x or gamma expasure. L indicates below approximately 100 KEV (effective); M indicates and approximately 100 KEV (effective); M indicates and approximately 250 KEV (effective); and H indicate: az in excess of approximately 250 KEV (effective), 03 (Very low energy x or gamma rays which would a result in exposure, predominately to the skin only, are separately itemized as type 2 radiation.) a vo (COLUMN 16) ADJUSTMENTS Adjustments made to cumulative totals with Big this or previous report at customer request. 50 Additions A - Additions **B** - Subtractions Additions & Subtractions D - Dosage data supplied by customer for ported E . Dosage data supplied by customer for part prior to inception of Landauer service, additional -changes have also been made. chonges have also been made. Previous lifetime exposure supplied by customer: Previous lifetime exposure supplied by customer, additional changes have also been made. (COLUMNS 17-18) PERMISSIBLE ACCUMULATED DOSE Unless birth date and lifetime exposure records

(COLUMN 5) DOSIMETER TYPE USED 892603

- Regular beta-gamma body film bodge

Beta-gamma fast neutron bady film badge

G - Gardray B

0

0

G

Document

<u>Z</u>0.

ORAUT-TKBS

-005

~

Revisi

ğ

S

8

Щ

ffe

ective

σ

ate:

<u>6</u>

22

/2007

σ

age

5

Ň

ç

-52

Unless birth date and litetime exposure records are supplied by the customer, no values are re-supplied this date, column 17 is determined by multiplying 5000 times the difference between age in years and 18 (f age is greater than 18). This blue is computed on a monthly basis. Column 18 is determined by subtracting column 15 from column 17. A letter "6" following date (in column 21) indicates substitution of birth date. A letter "C" following. date: (in column 21) indicates substitution of customer inception date. Permissible values are based on January 8, 1957 recommendations of the National Committee on Radiation Protection and Measurements. These values are given for total body exposures only.

ε.